





report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI
Colour	White
Year of manufacture	2013
Top speed	113 mph
Gearbox	6 speed automatic

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	26.9 mpg
Consumption extra urban	42.2 mpg
Consumption combined	35.3 mpg
CO2 emission	211 g/km
CO2 label	K



CarCheck.co.uk page 1/12



report date: 2024-03-29

# Internet history


## Entry 1

Date 2021-07-23

Pictures 23

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-03-29
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	19
Total items failed	6

MOT #11		2023-03-24 13:31
MOT test	number	456365644911
Result		✓ Passed
Next exp	ry date	2024-03-29
Advice	Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Vehicles internal headlight adjuster altered to recheck lights headlights were low		
Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))		

MOT #10	2022-03-18 10:54
MOT test number	715544324524
Result	<b>✓</b> Passed
Advice Oil leak, but not excessive (8.4.1 (a) (i))	

MOT #9	2021-03-30 12:06
MOT test number	950289022269
Result	✓ Passed

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

246093545338

Result

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #7

MOT test number

642441417423

Result

✓ Passed

MOT test number

Result

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))


Advice Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #5** 2019-01-03 09:49 **MOT** test number 420679007942 Result × Failed **Advice** Nearside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Offside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Advice Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) **Pass with rectification** Nearside Stop lamp(s) all not working (4.3.1 (a) (iii)) Pass with rectification Nearside Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a))

CarCheck.co.uk page 4/12



report date: 2024-03-29



MOT #3	2017-07-17 07:43
MOT test number	241699133493
Result	<b>★</b> Failed
Advice Oil leak	
Advice Front wipers beginning to sn	near
Pass with rectification Offside From	nt position lamp(s) not working 501 (1.1.A.3b)
Advice Emission light illuminated	
Advice Coolant level low	

MOT #2	2016-07-25 08:30
MOT test number	526584047142
Result	<b>✓</b> Passed
Advice Coolant level low	

MOT #1	2016-07-20 09:02
MOT test number	446556518808
Result	<b>X</b> Failed
Fail Offside Front Tyre has ply or cords exposed devoid of tread inner edge (4.1.D.1b)	

CarCheck.co.uk page 5/12



### Tax & MOT check



X MOT

Tax expired: 14 July 2023

Expired: 29 March 2024

Tax status	Expired at 14 July 2023
Days left	290 days too late
MOT expiry date	29 March 2024
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.


#### Damage 1

Date	
Category	
Туре	

#### Damage 2

Damage 2	
Date	
Category	





#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

More info >

## Owner history

Owner history	
For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downloner.	
*********	
*********	
***************************************	
	More info >
Plate changes	
See in this check if this VAUXHALL had different number plates.	
Number of plates	,
Current registration	NIE NIE
Plate since	
Current registration	NK SIN
Flate since	

CarCheck.co.uk page 9/12



report date: 2024-03-29

### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-07-24
Last registration	2023-03-24
Complete history	See info



Registration #1	2013-07-24	16 mi
Registration #2	2016-07-20	28.697 mi
Registration #3	2016-07-25	28.870 mi
Registration #4	2017-07-17	42.290 mi
Registration #5	2017-07-17	42.290 mi
Registration #6	2019-01-03	69.691 mi
Registration #7	2019-01-03	69.691 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		D.777 es

More info >

CarCheck.co.uk page 11/12



## Safety ratings

NCAP rating	****
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	see crash video



# Dimensions & weight

Width	2085 mm
Height	1761 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1936 kg
Max. allowed weight	2505 kg

## Additional information

Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 286966K LNQ

CarCheck.co.uk page 12/12