





report date: 2024-03-28

## General information

Make	FIAT
Model	DUCATO 35 MAXI C/C MULTIJET POWER
Colour	White
Year of manufacture	2013
Top speed	96 mph
Gearbox	6 speed Manual

# Engine & fuel consumption

Power	176 BHP
Max. torque 400 Nm at 1.400 rpm	
Engine capacity	2.999 сс
Cylinders	4
Fuel type	Diesel
CO2 emission	210 g/km
CO2 label	K



CarCheck.co.uk page 1/12



## Internet history

## Entry 1

Date 2021-09-17

Pictures 22

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2025-03-06
MOT pass rate	88 %
MOT passed	7
Failed MOT tests	1
Total advice items	19
Total items failed	6

MOT #8		2024-03-07 15:58
MOT test	number	198768056413
Result		✓ Passed
Next exp	iry date	2025-03-06
Minor (b) (i))	Nearside Registration plate lamp inoperative in the case of multiple lamps or light	sources (4.7.1
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))		novement (5.3.4
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive mo	vement (5.3.4 (a)

MOT #7	2023-02-28 16	:21
MOT test nu	umber 2582165272	80
Result	✓ Pass	sed
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4	
Advice	Offside Front Tyre worn close to legal limit/worn on edge worn on the edge 215/75R16 (5.2.3 (e))	)
Minor W	Vindscreen damaged but not adversely affecting driver's view (3.2 (a) (i))	
Advice (i))	Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a	a)
Minor N (b) (i))	learside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1	

CarCheck.co.uk page 3/12



**GK63LUT** 

report date: 2024-03-28

MOT #6 2022-03-02 17:20 MOT test number 433518733991

Result \( \sqrt{Passed} \)

Advice Offside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Minor Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #5 2021-03-01 15:30

**MOT test number** 998546921733

**Result** 
✓ Passed

**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #4** 2019-07-11 14:25

**MOT test number** 576883528228

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #3 2017-11-23 10:14

**MOT test number** 183759102107

Advice Rear Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/12



**GK63LUT** 

report date: 2024-03-28

MOT #2	2	2017-11-17 15:47
MOT tes	st number	492848760538
Result		<b>×</b> Failed
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)	
Fail	Nearside Front Suspension arm rubber bush deteriorated resulting in excessive m	ovement (2.4.G.2)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Fail	Offside Headlamp not working on dipped beam (1.7.5a)	
Fail	Registration plate lamp not working (1.1.C.1d)	
Fail	Offside Front Suspension arm rubber bush deteriorated resulting in excessive mov	vement (2.4.G.2)
Fail	Exhaust has a major leak of exhaust gases flexible joint (7.1.2)	

MOT #1	2016-11-02 10:14
MOT test number	205331906265
Result	<b>√</b> Passed

CarCheck.co.uk page 5/12



#### Tax & MOT check



Tax status	Valid until 1 December
Days left	217
MOT expiry date	6 March 2025
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 6/12



**GK63LUT** 

report date: 2024-03-28

#### Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

e when mistery	
For how long did the current and previous owner(s) have this FIAT? How many owners di Check it in the premium report and see all owner registrations. Download the full report	
STATE OF THE PARTY	
***************************************	
*********	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	
***************************************	
	More info >
Plate changes	
See in this check if this FIAT had different number plates.	
Number of plates	,
Current registration	OK SIN
Plate since	
Current registration	OK SIN
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FIAT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2013-11-22
Last registration	2024-03-07
Complete history	See info



Registration #1	2013-11-22	18 mi
Registration #2	2016-11-02	59.772 mi
Registration #3	2017-11-17	75.595 mi
Registration #4	2017-11-23	75.595 mi
Registration #5	2019-07-11	90.237 mi
Registration #6		71.777 es
Registration #6 Registration #7		11.777 ea
-		1.77 m
Registration #7		11.777 es 11.777 es 11.777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	2050 mm
Height	2254 mm
Length	6308 mm
Wheel base	3450 mm
Kerb weight	1735 kg
Max. allowed weight	3500 kg

## Additional information

Fuel delivery	Direct Injection	
Number of seats	3	
Number of axles	2	
Engine number Carcheck.co.uk	1905645	page 12/12