





report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER VX TD
Colour	Black
Year of manufacture	2002
Top speed	105 mph
0 - 60 mph	13.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	430 Nm at 1.400 rpm
Engine capacity	4.164 cc
Cylinders	6
Fuel type	Diesel
Consumption city	17.9 mpg
Consumption extra urban	26.2 mpg
Consumption combined	22.4 mpg
CO2 emission	340 g/km
CO2 label	М



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date 2022-04-04

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2025-03-10
MOT pass rate	95 %
MOT passed	19
Failed MOT tests	1
Total advice items	37
Total items failed	0

MOT #20	2024 02 10 16 21
MOT #20	2024-02-19 16:21
MOT test number	954605500820
Result	✓ Passed
Next expiry date	2025-03-10
Advice Slight corrosion underside	

MOT #19	2023-03-08 12:2	3
MOT test	number 74775892315	3
Result	✓ Passe	b
Advice (a) (i))	Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4	
Advice	Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))	

MOT #18		2022-03-11 16:50
MOT test	number	336073272124
Result		✓ Passed
Advice	Both rear shocks damp	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)))
Advice	Power steering noisy	
Advice	Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i))

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #17 2022-02-26 10:04

MOT test number 479831842590

Result × Failed **MAJOR** Bonnet cannot be secured in the closed position (3.1 (b) (i)) **MAJOR** Offside Rear Anti-roll bar pin or bush excessively worn outer (5.3.4 (a) (i)) **MAJOR** Offside Rear Brake lever has restricted free movement handbrake linkage siezed (1.1.15 (e)) **MAJOR** Offside Front Lower Suspension component ball joint excessively worn (5.3.4 (a) (i)) Advice Power steering noisy **MAJOR** Rear Registration plate inscription illegible (0.1 (b)) **MAJOR** Nearside Rear Anti-roll bar pin or bush excessively worn outer (5.3.4 (a) (i)) **MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii)) Advice Nearside Front Lower Suspension component ball joint has slight play (5.3.4 (a) (i)) Advice Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c)) **Advice** Both rear shocks damp

MOT #16 2021-02-17 10:36

MOT test number 511340721219

Advice Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement nearside and offside (5.3.4 (a) (i))

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

Advice Offside Rear Shock absorbers has slight external damage to the casing (5.3.2 (b))

Minor Offside Inner Prop shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #15 2020-02-18 11:34

MOT test number 745996162582

Minor Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

Advice Offside Rear Shock absorbers has slight external damage to the casing *corroded* (5.3.2 (b))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Rear & offside rear inner sills slightly corroded.

Advice Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

MOT #14 2019-02-19 10:53

MOT test number 747482514600

Result
✓ Passed

Advice Front Brake pad(s) wearing thin Nearside thinner. (1.1.13 (a) (ii))

MOT #13 2018-02-14 11:42

MOT test number 177437154041

Result
✓ Passed

MOT #12 2017-02-14 10:41

MOT test number 841371939638

Result
✓ Passed

Advice Anti-roll bar linkage has slight play in a pin/bush NSF + OSF (2.4.G.2)

MOT #11 2016-02-16 10:40

MOT test number 311086259007

Result ✓ Passed

CarCheck.co.uk page 5/14



(2.5.C.1a)

GX02PKT

report date: 2024-03-29

MOT #10 2015-02-17 10:36

MOT test number 807918945065

Result ✓ Passed

MOT #9 2014-02-18 10:39

MOT test number 698859144039

Result ✓ Passed

MOT #8 2013-02-14 12:04

MOT test number 996595043082

Result
✓ Passed

Advice Parking brake lever has little reserve travel (3.1.6b)

Advice Offside Inner Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt

Advice Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #7 2012-02-14 10:32

MOT test number 346705242098

Result

Passed

Advice Anti-roll bar rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice NSF tyre wearing low on edge

MOT #6 2011-02-14 10:29

MOT test number 449345841035

Result \(\sqrt{Passed} \)

Advice Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

MOT #5 2010-02-17 10:38

MOT test number 382078740023

Result
✓ Passed

CarCheck.co.uk page 6/14



MOT #4	2009-02-19 11:55
MOT test number	220300659007
Result	✓ Passed
MOT #3	2008-01-22 11:41
MOT test number	494092128041
Result	✓ Passed
MOT #2	2007-02-20 15:03
MOT test number	232431057047
Result	✓ Passed
MOT #1	2006-02-21 10:55
MOT test number	870072356073
Result	✓ Passed

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r	
manage of the same	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	NK SIE
Plate since	
Current registration	AK AK
Plate since	
	More info >

CarCheck.co.uk page 11/14



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-03-04
Last registration	2024-02-19
Complete history	See info



Registration #1	2002-03-04	10 mi
Registration #2	2006-02-21	87.211 mi
Registration #3	2007-02-20	105.664 mi
Registration #4	2008-01-22	118.585 mi
Registration #5	2009-02-19	129.633 mi
Registration #6	2010-02-17	140.683 mi
Registration #7	2011-02-14	151.771 mi
Registration #8	2012-02-14	162.219 mi
Registration #9	2013-02-14	171.475 mi
Registration #10	2014-02-18	177.465 mi
Registration #11	2015-02-17	187.413 mi
Registration #12		77,777 44
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.377 es
Registration #19		11.777 es
Registration #20		
Registration #20		0.777-00
Registration #21		11.77 m

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	1940 mm
Height	1890 mm
Length	4890 mm
Wheel base	2850 mm

Additional information

Fuel tank capacity	96 I
Fuel delivery	Direct Injection
Number of doors	5
Number of axles	2
Engine number	1HD0226721

CarCheck.co.uk page 14/14