



LC6IZBE

report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	POLO SE TDI
Colour	Grey
Year of manufacture	2011
Top speed	106 mph
0 - 60 mph	13.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 BHP
Max. torque	195 Nm at 1.500 rpm
Engine capacity	1.199 cc
Cylinders	4
Fuel type	Diesel
Consumption city	55.4 mpg
Consumption extra urban	78.5 mpg
Consumption combined	67.3 mpg
CO2 emission	102 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-02-06
Pictures	6
Listing price	View report



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

MOT expiry date	2024-11-22
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	11
Total items failed	4

MOT #12	2023-11-23 13:37
MOT test number	843981830202
Result	✓ Passed
Next expiry date	2024-11-22

MOT #11	2023-02-03 17:03
MOT test number	569207725609
Result	✓ Passed
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))
Advice	Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))

MOT #10	2023-02-02 09:54
MOT test number	554772294940
Result	✗ Failed
Advice	Nearside Front Steering rack has slight free play detected at steering wheel (2.3 (a) (i))
Minor	Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Fail	Nearside Front Inner Tyre has ply or cords exposed 185/60/15 (5.2.3 (d) (ii))
Fail	Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Nearside Front Road wheel fixing missing (5.2.1 (a) (i))
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #9** 2022-01-11 12:40**MOT test number** 654445041252**Result** ✓ Passed**Advice** Rear exhaust box outer skin badly corroded**Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing inner edge (5.2.3 (e))**MOT #8** 2020-09-28 14:04**MOT test number** 427597692681**Result** ✓ Passed**Advice** Nearside rear tyre starting to wear down**MOT #7** 2019-10-01 07:22**MOT test number** 818081582311**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Tyre has slight uneven wear to inner edge. (5.2.3 (e))**MOT #6** 2018-11-05 14:33**MOT test number** 646336909345**Result** ✓ Passed**MOT #5** 2018-11-05 10:48**MOT test number** 974439262772**Result** ✗ Failed**Advice** Nearside Rear Nail in tyre**Fail** Front Tyre has ply or cords exposed BOTH 185/60/15 (5.2.3 (d) (ii))



MOT #4	2017-11-03 09:56
MOT test number	503746244232
Result	✓ Passed
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt

MOT #3	2016-11-16 09:36
MOT test number	608984340134
Result	✓ Passed

MOT #2	2015-12-08 10:49
MOT test number	148701413209
Result	✓ Passed

MOT #1	2014-12-08 09:43
MOT test number	588482744336
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
22 November 2024

Tax status	Valid until 1 January
Days left	248
MOT expiry date	22 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 LC61ZBE
Plate since	2019-06-29
Current registration	 LC61ZBE
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-12-23
Last registration	2023-11-23
Complete history	See info



Registration #1	2011-12-23	23 mi
Registration #2	2014-12-08	27.376 mi
Registration #3	2015-12-08	31.311 mi
Registration #4	2016-11-16	37.218 mi
Registration #5	2017-11-03	41.676 mi
Registration #6	2018-11-05	46.437 mi
Registration #7	2018-11-05	46.437 mi
Registration #8	2019-11-05	51.277 mi
Registration #9	2019-11-05	51.277 mi
Registration #10	2019-11-05	51.277 mi
Registration #11	2019-11-05	51.277 mi
Registration #12	2019-11-05	51.277 mi
Registration #13	2019-11-05	51.277 mi
Registration #14	2019-11-05	51.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	86%
Pedestrian	41%
Safety systems	71%
Overall rating	78%
Video	see crash video



Dimensions & weight

Width	1682 mm
Height	1485 mm
Length	3970 mm
Wheel base	2470 mm
Kerb weight	1157 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles

2

Engine number

CFW 104375