



Mercedes-Benz

RJ08AVW


report date: 2024-03-28

General information

Make	MERCEDES
Model	VITO 111 CDI LONG TRAVELINER
Colour	Silver
Year of manufacture	2008
Gearbox	5 speed automatic

Engine & fuel consumption

Power	109 BHP
Max. torque	270 Nm at 1.600 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
CO2 emission	229 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-21
Pictures	25
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-07-20
MOT pass rate	64 %
MOT passed	16
Failed MOT tests	9
Total advice items	39
Total items failed	28

MOT #25	2022-07-21 07:26
MOT test number	602769490902
Result	✓ Passed
Next expiry date	2023-07-20
Minor	Front Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Minor	Front Windscreen wiper blade defective BOTH (3.4 (b) (i))
Advice	Front Oil leak, but not excessive (8.4.1 (a) (i))

MOT #24	2021-06-23 15:27
MOT test number	286879596219
Result	✓ Passed
Advice	Play in nearside and offside steering rack
Advice	Nearside Rear Nail in tyre

**MOT #23**

2021-06-22 10:03

**MOT test number**

798037430959

**Result****✗ Failed**

- Advice** Play in nearside and offside steering rack
- Advice** Nearside Rear Nail in tyre
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Fail** Offside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Fail** Nearside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))
- Minor** Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))
- Fail** Nearside Rear Brake pipe excessively corroded front to rear (1.1.11 (c))

**MOT #22**

2021-02-20 13:24

**MOT test number**

220469392795

**Result****✓ Passed**

- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #21**

2021-02-20 10:34

**MOT test number**

903687470646

**Result****✗ Failed****Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Headlamp not working on dipped beam (4.1.1 (a) (ii))**MOT #20**

2020-10-29 11:50

**MOT test number**

716659762340

**Result****✓ Passed****Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #19**

2020-10-27 13:55

**MOT test number**

767499402280

**Result****✗ Failed****Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #18** 2020-02-19 14:06**MOT test number** 662954809689**Result** ✓ Passed**MOT #17** 2020-02-19 14:06**MOT test number** 800495537917**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Pass with rectification** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**MOT #16** 2019-10-30 14:41**MOT test number** 323766286399**Result** ✓ Passed**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**MOT #15** 2019-10-26 13:42**MOT test number** 302311978211**Result** ✗ Failed**Fail** Exhaust emissions test not completed because smoke levels are significantly in excess of the specified limit values (8.2.2.2 (f))**Advice** Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))**Advice** Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i))**Fail** Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))



MOT #14	2018-11-10 10:47
MOT test number	405500542674
Result	✓ Passed
Advice	Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Service brake binding but not excessively (1.2.1 (f))
Advice	Offside front tyre worn on shoulder

MOT #13	2017-11-17 10:54
MOT test number	289669767842
Result	✓ Passed
Advice	Front brake discs worn
Advice	Spare wheel missing
Advice	Front tyres worn on shoulders

**MOT #12**

2017-11-15 12:56

**MOT test number**

689248222869

**Result**

✗ Failed

**Advice** Front tyres worn on shoulders**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively deteriorated so that it no longer prevents the ingress of dirt (2.4.G.2)**Fail** Nearside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Offside Rear Tyre has a lump, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Front brake discs worn**Fail** Nearside Rear Tyre(s) incorrect because different size tyres are fitted on the same axle. (4.1.A.1a)**Advice** Spare wheel missing**Fail** Offside Front Tyre has ply or cords exposed inner shoulder (4.1.D.1b)**Fail** Offside Front Brake pipe excessively corroded (3.6.B.2c)**Fail** Nearside Rear coil spring broken (2.4.C.1a)**MOT #11**

2017-02-27 19:44

**MOT test number**

311262714850

**Result**

✓ Passed

**MOT #10**

2017-02-27 18:51

**MOT test number**

449049028846

**Result**

✗ Failed

**Fail** Horn not working (1.6.2a)**MOT #9**

2016-02-02 15:04

**MOT test number**

634485076744

**Result**

✓ Passed

**Advice** Parking brake just met minimal pass efficiency adjustment and check advised



**MOT #8** 2015-02-03 10:59**MOT test number** 866544835072**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2015-02-03 10:59**MOT test number** 717874635006**Result** ✗ Failed**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear coil spring broken (2.4.C.1a)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2014-01-24 15:43**MOT test number** 275654524051**Result** ✓ Passed**MOT #5** 2014-01-24 15:43**MOT test number** 296444024027**Result** ✗ Failed**Pass with rectification** Offside Front position lamp(s) not working (1.1.A.3b)**MOT #4** 2013-01-09 10:29**MOT test number** 247099803008**Result** ✓ Passed



MOT #3	2012-01-16 14:46
MOT test number	128556412042
Result	✓ Passed
MOT #2	2011-01-11 09:37
MOT test number	309651311087
Result	✓ Passed
MOT #1	2010-02-03 10:34
MOT test number	963544630035
Result	✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:  
1 April 2023

X

MOT

Expired:  
20 July 2023

Tax status	Expired at 1 April 2023
Days left	394 days too late
MOT expiry date	20 July 2023
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2019-06-29
Current registration	 *****
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2008-04-17
Last registration	2022-07-21
Complete history	<a href="#">See info</a>



Registration #1	2008-04-17	22 mi
Registration #2	2010-02-03	14.273 mi
Registration #3	2011-01-11	50.304 mi
Registration #4	2012-01-16	83.958 mi
Registration #5	2013-01-09	106.515 mi
Registration #6	2014-01-24	126.520 mi
Registration #7	2015-02-03	143.719 mi
Registration #8	2016-02-02	157.351 mi
Registration #9	2017-02-27	162.840 mi
Registration #10	2017-02-27	162.840 mi
Registration #11	2017-11-15	172.970 mi
Registration #12	2017-11-17	172.970 mi
Registration #13	2018-11-10	222.065 mi
Registration #14	2019-05-20	25.377 mi
Registration #15	2019-05-20	25.377 mi
Registration #16	2019-05-20	25.377 mi
Registration #17	2019-05-20	25.377 mi
Registration #18	2019-05-20	25.377 mi
Registration #19	2019-05-20	25.377 mi
Registration #20	2019-05-20	25.377 mi
Registration #21	2019-05-20	25.377 mi
Registration #22	2019-05-20	25.377 mi
Registration #23	2019-05-20	25.377 mi
Registration #24	2019-05-20	25.377 mi
Registration #25	2019-05-20	25.377 mi





Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Additional information

Fuel tank capacity	75 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	9
Engine number	64698051672064