





report date: 2024-03-28

General information

Make	MINI
Model	COOPER S
Colour	Grey
Year of manufacture	2018
Top speed	146 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	189 BHP
Max. torque	280 Nm at 4.600 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	42.2 mpg
Consumption extra urban	55.4 mpg
Consumption combined	42.2 mpg
CO2 emission	129 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 2

Date	2021-12-16	
Pictures	0	
Listing price	<u>View report</u>	

source: heycar.co.uk

Entry 1

y -		
Date	2021-09-30	
Pictures	20	
Listing price	View report	









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-05-09
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	5
Total items failed	4

MOT #5	2023-05-03 08:50
MOT test number	472907834855
Result	✓ Passed
Next expiry date	2024-05-09

MOT #4		2023-04-29 09:55
MOT test number		348914392102
Result		X Failed
Fail Nearside Front Seat	belt not functioning as intended Seat belt twisted (7.1.2 (c))	
Pass with rectification	Offside Front Headlamp aim too low (4.1.2 (a))	
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))	
Advice Nearside Front S	Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	

MOT #3	2022-05-10 10:19
MOT test number	583977272994
Result	✓ Passed

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #2 2021-09-09 10:59

MOT test number 471673209537

Result ✓ Passed

Advice

Rear Tyre worn close to legal limit/worn on edge both rear tyres slightly worn on inner edge.

(5.2.3 (e))

Advice

Nearside Front Road wheel slightly distorted slight damage to nearside front inner rim (5.2.2 (c)

MOT #1 2021-09-09 10:59

MOT test number 537000917859

Result X Failed

Advice Nearside Front Road wheel slightly distorted slight damage to nearside front inner rim (5.2.2 (c) (i))

Pass with rectification Front Windscreen washer provides insufficient washer liquid (3.5 (a))

Advice Rear Tyre worn close to legal limit/worn on edge both rear tyres slightly worn on inner edge. (5.2.3 (e))

CarCheck.co.uk page 4/11



BK68EDF report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	9 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

More info >

Owner history	
For how long did the current and previous owner(s) have this MINI? How many owners di Check it in the premium report and see all owner registrations. Download the full report I	

	More info >
See in this check if this MINI had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NA
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0111.5	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-09-30
Last registration	2023-05-03
Complete history	See info



Registration #1	2018-09-30	20 mi
Registration #2	2021-09-09	26.747 mi
Registration #3	2021-09-09	26.747 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		71.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	79%
Children	73%
Pedestrian	66%
Safety systems	56%
Overall rating	71%
Video	see crash video



Dimensions & weight

Width	1727 mm
Height	1425 mm
Length	4005 mm
Wheel base	2567 mm
Kerb weight	1270 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	44
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11,

Number of axles 2

Engine number F959H875