





report date: 2024-01-16

General information

Make	VOLKSWAGEN
Model	TRANSPORTER T28 TDI P/V STARTLINE BMT
Colour	White
Year of manufacture	2016
Top speed	91 mph
0 - 100 km/h	15.4 seconds
0 - 60 mph	19.7 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	75 kW / 102 HP / 83 BHP
Max. torque	250 Nm at 1.500 rpm
Engine capacity	1.968 сс
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	48.7 mpg
Consumption combined	42.2 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/11



report date: 2024-01-16

Internet history

entry 1	E	n	tr	ъ	1
---------	---	---	----	---	---

Life y 1	
Date	2022-01-25
Pictures	0
Listing price	View report

source: cargurus.co.uk

CarCheck.co.uk page 2/11



GM16LZF report date: 2024-01-16

MOT history

MOT expiry date	2024-03-23
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	10
Total items failed	3

MOT #6	2023-03-24 11:08
MOT test number	875633283865
Result	✓ Passed
Next expiry date	2024-03-23

MOT #5	2023-03-22 08:04
MOT test number	930888754947
Result	X Failed
Fail Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))	
Advice Nearside Rear Nail in tyre and inner sidewall cracking	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning	ng (4.2.1 (a) (i))
Advice Offside Front Tyre slightly damaged/cracking or perishing Inner sidewall cracking	ing (5.2.3 (d) (ii))
Fail Nearside Reversing lamp inoperative (4.6.1 (a))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords and sidewall (5.2.3 (d) (i))	damage to outer
Minor Nearside Stop lamp(s) light intensity obviously reduced (4.3.3 (a) (i))	
Advice Nearside Front Tyre slightly damaged/cracking or perishing Inner sidewall cracking in the perish of the	cking (5.2.3 (d) (ii))

CarCheck.co.uk page 3/11



GM16LZF report date: 2024-01-16

MOT #4		2022-10-05 15:10
MOT test	number	772599331901
Result		✓ Passed
Advice	Offside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

Nearside Front Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))		
MOT #3		2021-06-21 08:19
MOT test	number	208145109420
Result		✓ Passed
MOT #2		2020-06-22 07:34
MOT test	number	808762329061
Result		✓ Passed
MOT #1		2019-06-19 07:48
MOT test	number	539938380756
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 4/11



GM16LZF
report date: 2024-01-16

Tax & MOT check



Tax status	Valid until 1 April
Days left	23
MOT expiry date	23 March 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	39
Standard rate (12 months)	£ 275,00,-
Standard rate (6 months)	£ 151,25,-

CarCheck.co.uk page 5/11



report date: 2024-01-16

Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	

Category

Type



Extra VOLKSWAGEN salvage check



CarCheck.co.uk

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

page 6/11



GM16LZF report date: 2024-01-16

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-01-16

More info >

Owner history

e mier metery	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

Plate changes	More info >
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NK SIK
Plate since	
Current registration	OK SING
Plate since	

CarCheck.co.uk page 8/11



report date: 2024-01-16

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 9/11



report date: 2024-01-16

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2016-06-16
Last registration	2023-03-24
Complete history	See info



Registration #1	2016-06-16	13 mi
Registration #2	2019-06-19	41.896 mi
Registration #3	2020-06-22	47.039 mi
Registration #4	2021-06-21	53.813 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es
Registration #8		N.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-01-16

Car features

50225	Air conditionir
50295	
50482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	****
Adult	79%
Children	74%
Pedestrian	32%
Safety systems	57%
Overall rating	66%
Video	see crash video



Dimensions & weight

Width	2283 mm
Height	1990 mm
Length	4892 mm
Wheel base	3400 mm
Kerb weight	1855 kg
Max. allowed weight	2800 kg

Additional information

Fuel tank capacity	80 I
Fuel delivery	Direct Injection
Number of doors	5
CarChack co.uk	nago 11/1

CarCheck.co.uk page 11/11

Number of seats	3
Number of axles	2
Engine number	CAAA938089