



TOYOTA



report date: 2024-03-28

General information

Make	TOYOTA
Model	URBAN CRUISER VVT-I
Colour	Blue
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	132 Nm at 3.800 rpm
Engine capacity	1.329 cc
Cylinders	4
Fuel type	Petrol
Consumption city	42.8 mpg
Consumption extra urban	57.7 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D





Internet history

Entry 1

Date	2021-07-24
Pictures	8
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	67 %
MOT passed	10
Failed MOT tests	5
Total advice items	49
Total items failed	3

MOT #15 2023-10-05 10:11

MOT test number 823192211430

Result ✓ Passed

Next expiry date 2024-10-20

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Minor Nearside Front Headlamp lens slightly defective and offside front (4.1.1 (b) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing and offside rear (5.2.3 (d) (ii))

MOT #14 2022-10-21 13:28

MOT test number 473639606525

Result ✓ Passed

Advice Exhaust corroded

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13**

2022-10-21 08:29

MOT test number

183083072419

Result**✗ Failed**

- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- MAJOR** Rear Brakes imbalanced across an axle (1.2.1 (b) (i))
- Advice** Exhaust corroded
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- MAJOR** Front Windscreen washer not working (3.5 (a))

MOT #12

2021-10-07 13:45

MOT test number

791940503428

Result**✓ Passed**

- Advice** Rear exhaust hangers corroded
- Advice** Headlamps cloudy given dim beam patterns
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement o\s and n\s (5.3.4 (a) (i))

**MOT #11**

2021-10-07 13:45

MOT test number

632857668485

Result**✗ Failed**

Advice Front Inner Suspension arm pin or bush worn but not resulting in excessive movement o\s and n\s (5.3.4 (a) (i))

Advice Headlamps cloudy given dim beam patterns

Pass with rectification Front Headlamp aim too low both (4.1.2 (a))

Advice Rear exhaust hangers corroded

MOT #10

2020-09-11 10:12

MOT test number

719691391431

Result**✓ Passed**

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement o\s and n\s (5.3.4 (a) (i))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MOT #9

2020-09-10 15:20

MOT test number

819258487053

Result**✗ Failed**

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Suspension arm pin or bush worn but not resulting in excessive movement o\s and n\s (5.3.4 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge on limit (5.2.3 (e))

MAJOR Windscreen washer not working (3.5 (a))

**MOT #8**

2019-09-13 13:44

MOT test number

189259564779

Result

✓ Passed

- Advice** O/s rear tyre perished
- Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Inner Suspension arm pin or bush worn but not resulting in excessive movement o/s and n/s (5.3.4 (a) (i))
- Advice** Exhaust hangers corroded

MOT #7

2018-09-12 08:40

MOT test number

654454730770

Result

✓ Passed

- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))

MOT #6

2018-09-11 11:55

MOT test number

797340432494

Result

✗ Failed

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))
- MAJOR** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Vehicles internal headlight adjuster altered to recheck lights
- Advice** Front Brake disc worn, but not excessively both sides lipped/worn (1.1.14 (a) (i))
- Advice** Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement back bush (5.3.4 (a) (i))

**MOT #5** 2017-08-30 14:27**MOT test number** 411318964760**Result** ✓ Passed**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2016-05-06 15:38**MOT test number** 716468693943**Result** ✓ Passed**Advice** Engine covers and under trays fitted**MOT #3** 2016-05-06 15:37**MOT test number** 304556264182**Result** ✗ Failed**Advice** Engine covers and under trays fitted**Pass with rectification** Nearside Front Headlamp aim too high (1.8)**Pass with rectification** Offside Front Headlamp aim too high (1.8)**MOT #2** 2015-02-21 14:46**MOT test number** 475022155067**Result** ✓ Passed**MOT #1** 2014-04-07 10:27**MOT test number** 785287394018**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
20 October 2024

Tax status	Valid until 1 March
Days left	307
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-



Damage history


Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-03-31
Last registration	2023-10-05
Complete history	See info



Registration #1	2011-03-31	23 mi
Registration #2	2014-04-07	20.395 mi
Registration #3	2015-02-21	24.201 mi
Registration #4	2016-05-06	36.187 mi
Registration #5	2016-05-06	36.187 mi
Registration #6	2017-08-30	47.412 mi
Registration #7	2018-09-11	56.855 mi
Registration #8	2018-09-12	56.855 mi
Registration #9	2019-09-13	66.569 mi
Registration #10	2019-09-13	66.569 mi
Registration #11	2019-09-13	66.569 mi
Registration #12	2019-09-13	66.569 mi
Registration #13	2019-09-13	66.569 mi
Registration #14	2019-09-13	66.569 mi
Registration #15	2019-09-13	66.569 mi
Registration #16	2019-09-13	66.569 mi
Registration #17	2019-09-13	66.569 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	58%
Children	71%
Pedestrian	53%
Safety systems	86%
Overall rating	62%
Video	see crash video



Dimensions & weight

Width	1725 mm
Height	1525 mm
Length	3930 mm
Wheel base	2460 mm
Kerb weight	1150 kg
Max. allowed weight	1590 kg

Additional information

Fuel tank capacity	42 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	1NR0254738