



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	TOURAN MATCH TDI
Colour	Silver
Year of manufacture	2009
Top speed	111 mph
0 - 60 mph	13.2 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	47.1 mpg
CO2 emission	155 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-10-08
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2025-02-02
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	32
Total items failed	11

MOT #19	2024-01-27 10:00
MOT test number	793690335625
Result	✓ Passed
Next expiry date	2025-02-02

MOT #18	2023-02-03 06:47
MOT test number	143698610545
Result	✓ Passed
Advice	Passenger seat(s) missing at time of test All rear seats
Minor	Nearside Front Upper Anti-roll bar linkage ball joint dust cover severely deteriorated **borderline** (5.3.4 (b) (i))
Minor	Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i))

MOT #17	2022-02-02 05:31
MOT test number	854784065025
Result	✓ Passed
Advice	Rear Brake disc worn, pitted or scored, but not seriously weakened Both sides (1.1.14 (a) (ii))

**MOT #16**

2021-01-22 08:49

MOT test number

780336418073

Result

✓ Passed

- Advice** Front and rear brake discs corroded
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

MOT #15

2021-01-22 08:49

MOT test number

504654867636

Result

✗ Failed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))
- Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front and rear brake discs corroded
- Pass with rectification** Offside Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Service brake fluctuating, but not excessively (1.2.1 (e))

**MOT #14** 2020-01-10 17:05**MOT test number** 629094749468**Result** ✓ Passed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #13** 2020-01-10 11:30**MOT test number** 244800456753**Result** ✗ Failed**Fail** Nearside Rear Hydraulic brake calliper leaking (1.1.16 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Front Service brake fluctuating, but not excessively (1.2.1 (e))**MOT #12** 2019-01-24 14:45**MOT test number** 155698347244**Result** ✓ Passed**Advice** Nearside Front Nail in tyre marked yellow**Advice** Play in steering rack inner joint(s)**Advice** Shock absorbers light misting of oil or has limited damping effect both OSF NSF (5.3.2 (b))**Advice** Inner Tyre worn close to legal limit/worn on edge both OSF NSF tread depth 2mm (5.2.3 (e))

**MOT #11**

2019-01-24 10:09

MOT test number

163847058136

Result**✗ Failed**

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords marked yellow (5.2.3 (d) (i))

Advice Offside Rear Valve stem slightly damaged (5.2.3 (j))

Pass with rectification Nearside Front Position lamp not working (4.2.1 (a))

Advice Play in steering rack inner joint(s)

Fail Nearside Front Lower Suspension arm ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))

Advice Inner Tyre worn close to legal limit/worn on edge both OSF NSF tread depth 2mm (5.2.3 (e))

Advice Nearside Front Nail in tyre marked yellow

Advice Shock absorbers light misting of oil or has limited damping effect both OSF NSF (5.3.2 (b))

MOT #10

2018-01-05 09:53

MOT test number

118157776175

Result**✓ Passed****MOT #9**

2018-01-05 09:53

MOT test number

158986424649

Result**✗ Failed**

Pass with rectification Offside Registration plate lamp not working (1.1.C.1d)

MOT #8

2017-01-27 11:57

MOT test number

312510349673

Result**✓ Passed**

Advice Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #7** 2016-01-26 14:13**MOT test number** 632357077228**Result** ✓ Passed**MOT #6** 2016-01-26 11:43**MOT test number** 620621257609**Result** ✗ Failed**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #5** 2015-01-28 08:57**MOT test number** 766818425096**Result** ✓ Passed**Notice** N/s/r tyre worn on inner edge**Notice** Nail in nearside rear tyre**MOT #4** 2014-01-13 11:15**MOT test number** 969403514087**Result** ✓ Passed**MOT #3** 2013-01-21 09:37**MOT test number** 845011523043**Result** ✓ Passed**MOT #2** 2012-11-02 11:20**MOT test number** 646097302340**Result** ✓ Passed



MOT #1	2012-11-02 10:06
MOT test number	137917702379
Result	✗ Failed
Fail	Offside Headlamp aim too high (1.8)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Offside Front Tyre has ply or cords exposed (4.1.D.1b)



Tax & MOT check

✓
Taxed
Tax due:
1 June 2024

✓
MOT
Expires:
2 February 2025

Tax status	Valid until 1 June
Days left	33
MOT expiry date	2 February 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 BK59ZKR
Plate since	2019-09-29
Current registration	 BK59ZKR
Plate since	2019-09-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2009-12-11
Last registration	2024-01-27
Complete history	See info



Registration #1	2009-12-11	14 mi
Registration #2	2012-11-02	43.245 mi
Registration #3	2012-11-02	43.245 mi
Registration #4	2013-01-21	45.153 mi
Registration #5	2014-01-13	56.298 mi
Registration #6	2015-01-28	67.676 mi
Registration #7	2016-01-26	77.524 mi
Registration #8	2016-01-26	77.524 mi
Registration #9	2017-01-27	90.550 mi
Registration #10	2018-01-05	104.972 mi
Registration #11	2018-01-05	104.972 mi
Registration #12	2019-01-27	121.277 mi
Registration #13	2019-01-27	121.277 mi
Registration #14	2019-01-27	121.277 mi
Registration #15	2019-01-27	121.277 mi
Registration #16	2019-01-27	121.277 mi
Registration #17	2019-01-27	121.277 mi
Registration #18	2019-01-27	121.277 mi
Registration #19	2019-01-27	121.277 mi
Registration #20	2019-01-27	121.277 mi
Registration #21	2019-01-27	121.277 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1794 mm
Height	1635 mm
Length	4391 mm
Wheel base	2678 mm
Kerb weight	2210 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	5

Number of seats	7
Number of axles	2
Engine number	BXE C57284