



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 T SE S60
Colour	Grey
Year of manufacture	-
Top speed	134 mph
0 - 60 mph	9.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	180 BHP
Max. torque	240 Nm at 1.850 rpm
Cylinders	5
Fuel type	Petrol
Consumption city	20.6 mpg
Consumption extra urban	39.8 mpg
Consumption combined	29.7 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-25
Pictures	12
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT #25	2022-10-13 13:58
MOT test number	655490223392
Result	✓ Passed
Next expiry date	2023-10-12

MOT #24	2022-10-13 11:35
MOT test number	689164722610
Result	✗ Failed
Fail Nearside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))	
Fail Offside Front Tyre tread pattern not visible over the whole tread area when minimum depth required is 1.0mm (5.2.3 (e))	

MOT #23	2021-10-07 11:30
MOT test number	288500024513
Result	✓ Passed

MOT #22	2020-09-23 09:19
MOT test number	384819095126
Result	✓ Passed

MOT #21	2020-09-23 09:19
MOT test number	701254922587
Result	✗ Failed
Pass with rectification Nearside Front Position lamp not working (4.2.1 (a) (ii))	
Pass with rectification Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))	

MOT #20	2019-09-11 12:43
MOT test number	687178451078
Result	✓ Passed

**MOT #19** 2019-09-11 09:56**MOT test number** 837469187821**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**Fail** Nearside Front Anti-roll bar linkage likely to fail (5.3.3 (b) (ii))**MOT #18** 2018-09-20 10:27**MOT test number** 705266338855**Result** ✓ Passed**Advice** Nearside Front Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #17** 2018-09-20 10:27**MOT test number** 537796422304**Result** ✗ Failed**Pass with rectification** Nearside Stop lamp(s) missing (4.3.1 (a) (ii))**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (3.5 (a))**Advice** Nearside Front Suspension rod pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #16** 2017-09-21 09:48**MOT test number** 669798275858**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #15** 2016-09-29 10:29**MOT test number** 486161785695**Result** ✓ Passed**Advice** Suspension arm synthetic bush deteriorated but not resulting in excessive movement front and rear (2.4.G.2)

**MOT #14** 2016-09-29 10:29**MOT test number** 832756061657**Result** ✗ Failed

Advice Suspension arm synthetic bush deteriorated but not resulting in excessive movement front and rear (2.4.G.2)

Pass with rectification Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #13 2015-09-23 12:02**MOT test number** 403578616301**Result** ✓ Passed

Advice Suspension arm synthetic bush deteriorated but not resulting in excessive movement front and rear (2.4.G.2)

Advice Brake pipe slightly corroded front and rear (3.6.B.2c)

MOT #12 2014-09-15 16:53**MOT test number** 696338554201**Result** ✓ Passed**MOT #11** 2013-09-02 09:19**MOT test number** 189655843236**Result** ✓ Passed**MOT #10** 2012-09-19 10:15**MOT test number** 438783862285**Result** ✓ Passed

**MOT #9** 2011-09-19 16:54**MOT test number** 768882861264**Result** ✓ Passed**Advice** Offside Front Direction indicators slightly discoloured (1.4.A.2f)**Notice** Headlamp main beam warning lamp not working**Advice** Nearside Front Direction indicators slightly discoloured (1.4.A.2f)**MOT #8** 2010-09-21 09:28**MOT test number** 392704760479**Result** ✓ Passed**MOT #7** 2009-09-21 16:44**MOT test number** 370254169216**Result** ✓ Passed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**MOT #6** 2009-09-21 16:44**MOT test number** 822484869252**Result** ✗ Failed**Advice** Offside Front Direction indicator slightly discoloured (1.4.A.2f)**Pass with rectification** Offside Registration plate lamp not illuminating the registration plate (1.1.C.1e)

**MOT #5** 2008-09-26 10:13**MOT test number** 744750678220**Result** ✓ Passed

- Advice** Front brake disc slightly pitted (3.5.1h)
- Notice** Nail in nearside rear tyre
- Notice** Fuel cap seal slight cracking, limit pass
- Advice** Offside Front Direction indicators slightly discoloured (1.4.A.2f)
- Notice** Steering rack has slight play
- Notice** O/s/r/tyre wearing low on tread also has slight cracking on tread

MOT #4 2007-10-12 12:23**MOT test number** 894115687225**Result** ✓ Passed**MOT #3** 2007-10-04 16:55**MOT test number** 984497277283**Result** ✗ Failed

- Notice** Wear to front brake discs
- Fail** Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
- Notice** Non obligatory mirror damaged
- Fail** Offside Rear Registration plate lamp not working (1.1.5c)
- Fail** Nearside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)



MOT #2	2007-08-03 10:00
MOT test number	414635317222
Result	✗ Failed
Fail	Offside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Nearside Front Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)
Fail	Offside Rear Registration plate lamp not working (1.1.5c)
Notice	Non obligatory mirror damaged
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2006-10-04 09:19
MOT test number	652797876241
Result	✓ Passed




Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	*****
Plate since	2023-03-29
Current registration	*****
Plate since	2023-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2003-09-26
Last registration	2022-10-13
Complete history	See info



Registration #1	2003-09-26	10 mi
Registration #2	2006-10-04	39.841 mi
Registration #3	2007-08-03	56.830 mi
Registration #4	2007-10-04	57.077 mi
Registration #5	2007-10-12	57.079 mi
Registration #6	2008-09-26	62.227 mi
Registration #7	2009-09-21	69.843 mi
Registration #8	2010-09-21	76.174 mi
Registration #9	2011-09-19	80.901 mi
Registration #10	2012-09-19	85.768 mi
Registration #11	2013-09-02	91.424 mi
Registration #12	2014-09-15	96.717 mi
Registration #13	2015-09-23	101.966 mi
Registration #14	2016-09-23	107.215 mi
Registration #15	2017-09-23	112.464 mi
Registration #16	2018-09-23	117.713 mi
Registration #17	2019-09-23	122.962 mi
Registration #18	2020-09-23	128.211 mi
Registration #19	2021-09-23	133.460 mi
Registration #20	2022-09-23	138.709 mi
Registration #21	2023-09-23	143.958 mi
Registration #22	2024-09-23	149.207 mi
Registration #23	2025-09-23	154.456 mi
Registration #24	2026-09-23	159.705 mi
Registration #25	2027-09-23	164.954 mi
Registration #26	2028-09-23	170.203 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	1813 mm
Height	1428 mm
Length	4603 mm
Wheel base	2715 mm
Kerb weight	1492 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Engine number	2874390