



UK

PN58TGJ


report date: 2024-03-29

General information

Make	VOLVO
Model	V50
Colour	Red
Year of manufacture	2008
Gearbox	-

Engine & fuel consumption

Engine capacity	1.798 cc
Fuel type	Petrol
CO2 emission	174 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-08-07
Pictures	14
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-08-13
MOT pass rate	62 %
MOT passed	13
Failed MOT tests	8
Total advice items	15
Total items failed	12

MOT #21	2023-07-20 08:50
MOT test number	894148771520
Result	✓ Passed
Next expiry date	2024-08-13
Advice	Hand brake has little reserve travel

MOT #20	2023-07-20 08:50
MOT test number	828054533327
Result	✗ Failed
Advice	Hand brake has little reserve travel
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))

MOT #19	2022-08-12 15:16
MOT test number	801335214502
Result	✓ Passed
Advice	Hand brake has little reserve travel

**MOT #18** 2022-08-12 08:41**MOT test number** 188683392390**Result** ✗ Failed**Advice** Hand brake has little reserve travel**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Fail** Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #17** 2021-08-14 18:41**MOT test number** 185379487288**Result** ✓ Passed**MOT #16** 2021-08-13 11:31**MOT test number** 997802987498**Result** ✗ Failed**Fail** Windscreen washer not working (3.5 (a))**MOT #15** 2020-10-29 09:39**MOT test number** 538973027035**Result** ✓ Passed**MOT #14** 2019-04-25 16:20**MOT test number** 252952048416**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #13**

2019-04-25 16:19

MOT test number

762580661977

Result**✗ Failed****Advice**

Offside Rear Outer Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice

Nearside Rear Nail in tyre

Pass with rectification

Nearside Front Position lamp not working (4.2.1 (a))

MOT #12

2018-04-10 11:59

MOT test number

190986026045

Result**✓ Passed****Advice**

Battery not secure in its tray bracket bolt missing

MOT #11

2018-04-10 09:14

MOT test number

277421519613

Result**✗ Failed****Advice**

Offside Rear Tyre low on pressure ,no nails in tread

Fail

Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice

Battery not secure in its tray bracket bolt missing

Advice

Parking brake lever has little reserve travel (3.1.6b)

MOT #10

2017-04-26 08:33

MOT test number

243459817108

Result**✓ Passed**

**MOT #9** 2017-04-25 12:12**MOT test number** 292781342145**Result** ✗ Failed

Fail Nearside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Front Suspension arm rubber mounting deteriorated resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #8 2016-04-12 15:38**MOT test number** 311469780117**Result** ✓ Passed**MOT #7** 2016-04-12 13:40**MOT test number** 966344717971**Result** ✗ Failed

Fail Parking brake lever has no reserve travel (3.1.6b)

Fail Parking brake: efficiency below requirements (3.7.B.7)

MOT #6 2015-01-26 12:32**MOT test number** 516596025045**Result** ✓ Passed**MOT #5** 2013-11-06 16:33**MOT test number** 695850513394**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #4	2013-08-27 09:32
MOT test number	429319933221
Result	✓ Passed
MOT #3	2012-09-07 15:35
MOT test number	377341152272
Result	✓ Passed
MOT #2	2011-08-17 15:18
MOT test number	756219221272
Result	✓ Passed
MOT #1	2011-08-17 15:18
MOT test number	205559921260
Result	✗ Failed
<div>Pass with rectification</div> Nearside Registration plate lamp not working (1.1.C.1d)	



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
13 August 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	13 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history


Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.


Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-09-26
Last registration	2023-07-20
Complete history	See info



Registration #1	2008-09-26	24 mi
Registration #2	2011-08-17	28.720 mi
Registration #3	2012-09-07	37.713 mi
Registration #4	2013-08-27	45.255 mi
Registration #5	2013-11-06	46.247 mi
Registration #6	2015-01-26	53.473 mi
Registration #7	2016-04-12	60.649 mi
Registration #8	2016-04-12	60.649 mi
Registration #9	2017-04-25	67.224 mi
Registration #10	2017-04-26	67.225 mi
Registration #11	2018-04-10	70.087 mi
Registration #12	2019-04-10	70.087 mi
Registration #13	2019-04-10	70.087 mi
Registration #14	2019-04-10	70.087 mi
Registration #15	2019-04-10	70.087 mi
Registration #16	2019-04-10	70.087 mi
Registration #17	2019-04-10	70.087 mi
Registration #18	2019-04-10	70.087 mi
Registration #19	2019-04-10	70.087 mi
Registration #20	2019-04-10	70.087 mi
Registration #21	2019-04-10	70.087 mi
Registration #22	2019-04-10	70.087 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Additional information

Number of seats 4

Engine number 143891