





report date: 2024-03-29

General information

Make	HONDA
Model	ACCORD VTEC EX
Colour	Silver
Year of manufacture	2007
Top speed	135 mph
0 - 60 mph	9.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	153 BHP
Max. torque	155 Nm at 6.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	25.9 mpg
Consumption extra urban	44.8 mpg
Consumption combined	35.3 mpg
CO2 emission	189 g/km
CO2 label	J



CarCheck.co.uk page 1/14



report date: 2024-03-29

Internet history


Entry 1

Date 2021-12-05

Pictures 9

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

	_				
11/1/	TC	n		$\overline{}$	r\/
IVIL	, ,		51	LU.	ıv
					. ,

MOT expiry date	2024-11-17
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	19
Total items failed	6

MOT #19	2023-11-14 14:39
MOT test number	482040372350
Result	✓ Passed
Next expiry date	2024-11-17

MOT #18		2022-11-14 10:42
MOT test	number	443332146253
Result		✓ Passed
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Advice	Nearside Rear Anti-roll bar pin or bush worn but not resulting in excessive move	ment (5.3.4 (a) (i))

MOT #17		2021-11-18 11:47
MOT test	number	592841540415
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive mo	vement (5.3.4 (a) (i))
Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		d (1.1.14 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #16 2021-11-18 11:47 **MOT** test number 757279493586 Result × Failed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) Advice Pass with rectification Nearside Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #15 2020-10-28 13:00 858864875621 **MOT test number** Result Passed **Advice** Nearside Rear Upper Vehicle structure is corroded but structural rigidity is not significantly reduced (6.1.1 (c) (i)) **Advice** Nearside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement d bush (5.3.4 (a) (i)) Offside Rear Upper Vehicle structure is corroded but structural rigidity is not significantly reduced Advice (6.1.1 (c) (i)) Offside Rear Anti-roll bar linkage pin or bush worn but not resulting in excessive movement d bush Advice (5.3.4 (a) (i))

MOT #14

MOT test number

Fesult

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT test number

Fail Offside Front Suspension rod ball joint likely to become detached drop link (5.3.4 (a) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2018-03-21 14:23 338353714256 **MOT** test number Result ✓ Passed 2018-03-13 15:11 **MOT #11 MOT** test number 705724547616 Result × Failed Fail Offside Front Headlamp not working on dipped beam (1.7.5a) Fail Offside Front Seat belt stitching badly frayed (5.2.2b)

MOT #10	2017-04-03 09:51
MOT test number	140653932463
Result	✓ Passed

MOT #9		2017-04-03 09:50
MOT test number		582540196992
Result		× Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)	

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #8		2016-03-24 08:55
MOT test number		976983039235
Result		✓ Passed
MOT #7		2015-04-08 08:45
MOT test number		679098995073
Result		✓ Passed
MOT #6		2015-04-08 08:45
MOT test number		509278995057
Result		× Failed
Pass with rectification	Offside Headlamp not working on dipped beam (1.7.5a)	
MOT #5		2014-04-01 09:24
MOT test number		595091294055
Result		✓ Passed
MOT #4		2013-04-03 09:37

2014 04 01 05.24
595091294055
✓ Passed
2013-04-03 09:37
729413493035
✓ Passed
2012-04-10 11:22
299531402432
✓ Passed
2011-04-13 09:18
749043801183
✓ Passed

CarCheck.co.uk page 6/14



report date: 2024-03-29

 MOT #1
 2010-04-13 16:19

 MOT test number
 142693300172

Result ✓ Passed

CarCheck.co.uk page 7/14



A20TSF report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 June
Days left	32
MOT expiry date	17 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this HONDA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	OK SIN
Plate since	
	More info

CarCheck.co.uk page 11/14



A20TSF report date: 2024-03-29

Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



A20TSF report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-04-13
Last registration	2023-11-14
Complete history	See info



Registration #1	2007-04-13	26 mi
Registration #2	2010-04-13	24.698 mi
Registration #3	2011-04-13	31.413 mi
Registration #4	2012-04-10	38.306 mi
Registration #5	2013-04-03	44.463 mi
Registration #6	2014-04-01	52.562 mi
Registration #7	2015-04-08	58.656 mi
Registration #8	2016-03-24	67.764 mi
Registration #9	2017-04-03	73.656 mi
Registration #10	2017-04-03	73.656 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 mg

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1445 mm
Length	4665 mm
Wheel base	2670 mm
Kerb weight	1365 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Engine number	K20Z21114647

CarCheck.co.uk page 14/14