





report date: 2024-03-28

General information

Make	PEUGEOT
Model	207 SPORT
Colour	Grey
Year of manufacture	2010
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	136 Nm at 4.000 rpm
Engine capacity	1.397 сс
Cylinders	4
Fuel type	Petrol
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg
CO2 emission	137 g/km
CO2 label	E



CarCheck.co.uk page 1/14



Internet history

Entry 1

Date	2021-05-26	
Pictures	1	
Listing price	<u>View report</u>	



source: autoonline.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT expiry date	2024-08-27
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	43
Total items failed	4

MOT #16		2023-08-25 13:42
MOT test	number	508769794003
Result		✓ Passed
Next exp	iry date	2024-08-27
Advice	Oil leak, but not excessive (8.4.1 (a) (i))	
Advice	Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))	
Minor	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.	.7 (g) (i))

MOT #15		2022-08-10 16:45
MOT test	number	269207228949
Result		✓ Passed
Advice	Front Headlamp has a product on the lens but not seriously reducing light	output (4.1.4 (b))
Advice	Slight wear offside front bottom ball joint	
Advice	Front discs worn	
Advice	Offside Front Outer cv boot weak	

MOT #14	2021-08-28 10:22
MOT test number	790367103666
Result	✓ Passed

CarCheck.co.uk page 3/14



Result

KM10VVP

report date: 2024-03-28

✓ Passed

MOT #13 2020-08-27 17:22

MOT test number 511069852715

Result ✓ Passed

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #12 2019-08-20 11:16

MOT test number 340336303722

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust mounting defective (6.1.2 (a))

MOT #11 2019-08-14 09:41

MOT test number 842613360946

Result X Failed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Exhaust mounting defective (6.1.2 (a))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

MAJOR Nearside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))

MAJOR Nearside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MAJOR Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

CarCheck.co.uk page 4/14



✓ Passed

MOT #10 2018-08-15 09:40

MOT test number 683442721302

Result ✓ Passed

Advice Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))

Advice Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear tyre tread cracking badly

Advice Offside Front Outer Tyre worn close to legal limit/worn on edge shoulder scrubbing (5.2.3 (e))

Advice Nearside Rear tyre cracking

Advice Nearside Front Outer Tyre worn close to legal limit/worn on edge shoulder bald (5.2.3 (e))

MOT #9 2017-08-16 12:58

MOT test number 814792552227

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Nail in tyre

Result

MOT #8 2017-08-16 10:13

MOT test number 154590097831

Result X Failed

Advice Offside Rear Nail in tyre

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Fail Offside Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #7 2016-08-16 08:58

MOT test number 272116415896

Result

Passed

CarCheck.co.uk page 5/14



KM10VVP

report date: 2024-03-28

MOT #6 2016-08-09 08:11

MOT test number 809327991457

Result X Failed

Fail Exhaust system not adequately supported (7.1.1)

Fail Nearside Outer Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT #5 2015-08-11 12:59

MOT test number 184621077129

Result

Passed

Advice Re-tested from No. 468522215290

MOT #4 2015-07-31 10:31

MOT test number 468522215290

Result × Failed

Notice Engine covers fitted obscuring some components in the engine bay

Notice Nail in nearside rear tyre

Fail Exhaust system not adequately supported (7.1.1)

Notice Child seat fitted not allowing full inspection of adult belt

Notice Play in N/S front door hinges

Notice N/S Rear tyre under inflated

Advice Exhaust has a minor leak of exhaust gases (7.1.2)

MOT #3 2014-07-23 13:13

MOT test number 496614604213

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/14



KM10VVP

report date: 2024-03-28

MOT #2 2013-08-07 07:56

MOT test number 955629413224

Result ✓ Passed

MOT #1 2013-05-21 10:08

MOT test number 299581043199

Advice Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

Advice Trailer electrical socket damaged, but the lead can still be securely connected (1.9.3b)

CarCheck.co.uk page 7/14



Tax & MOT check



Tax status	Valid until 1 February
Days left	278
MOT expiry date	27 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Е
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



KM10VVP

report date: 2024-03-28

More info >

Owner history For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>. More info > Plate changes See in this check if this PEUGEOT had different number plates. ober of plates faste since

CarCheck.co.uk page 11/14



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >


CarCheck.co.uk page 12/14



Mileage check

Registration #18

Odometer	In miles
Mileage registrations	18
First mileage registration	2010-06-08
Last registration	2023-08-25
Complete history	See info



Registration #1	2010-06-08	28 mi
Registration #2	2013-05-21	45.308 mi
Registration #3	2013-08-07	48.747 mi
Registration #4	2014-07-23	52.618 mi
Registration #5	2015-07-31	57.937 mi
Registration #6	2015-08-11	58.128 mi
Registration #7	2016-08-09	62.686 mi
Registration #8	2016-08-16	62.771 mi
Registration #9	2017-08-16	66.866 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		0.00 44
Registration #15		11.777 mi
Registration #16		0.00 44
Registration #17		0.074

7075.75.75

More info >

77.777 86

CarCheck.co.uk page 13/14



Car features

50225	Air conditionin
50295	
50482	
50501	
50566	
60567	
50569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1920 mm
Height	1502 mm
Length	4030 mm
Wheel base	2540 mm
Kerb weight	1234 kg
Max. allowed weight	1643 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 14/14

Number of axles 2

Engine number FGAR0818447