



ML6IEZM

report date: 2024-03-29

General information

| | |
|---------------------|--------------------------|
| Make | MINI |
| Model | MINI (R60) COOPER D ALL4 |
| Colour | Blue |
| Year of manufacture | 2011 |
| Top speed | 112 mph |
| 0 - 60 mph | 10.9 seconds |
| Gearbox | 6 speed Manual |

Engine & fuel consumption

| | |
|----------------------|---------------------|
| Power | 112 BHP |
| Max. torque | 270 Nm at 1.750 rpm |
| Engine capacity | 1.600 cc |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption combined | 64.2 mpg |
| CO2 emission | 129 g/km |
| CO2 label | D |





Internet history

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-02-02 |
| Pictures | 10 |
| Listing price | View report |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-11-24 |
| MOT pass rate | 79 % |
| MOT passed | 11 |
| Failed MOT tests | 3 |
| Total advice items | 11 |
| Total items failed | 3 |

| | |
|------------------|---|
| MOT #14 | 2023-11-22 12:16 |
| MOT test number | 364104387958 |
| Result | ✓ Passed |
| Next expiry date | 2024-11-24 |
| Advice | Nearside Front Tyre slightly damaged (5.2.3 (d) (ii)) |

| | |
|-----------------|------------------|
| MOT #13 | 2022-11-14 10:50 |
| MOT test number | 411306713930 |
| Result | ✓ Passed |

| | |
|-----------------|--|
| MOT #12 | 2021-11-25 09:29 |
| MOT test number | 382092452160 |
| Result | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |

**MOT #11** 2021-11-24 13:03**MOT test number** 551354290323**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2020-11-23 16:56**MOT test number** 775024127708**Result** ✓ Passed**MOT #9** 2020-11-14 15:03**MOT test number** 779430091778**Result** ✗ Failed**Advice** Coolant level low**Fail** Offside Rear Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt split (6.1.7 (g) (ii))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Rear exhaust heat shield insecure**MOT #8** 2020-05-23 10:27**MOT test number** 680146314223**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #7** 2019-04-24 13:32**MOT test number** 381172191034**Result** ✓ Passed

**MOT #6** 2019-04-24 13:32**MOT test number** 718924780288**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**MOT #5** 2018-04-27 09:08**MOT test number** 202681077128**Result** ✓ Passed**MOT #4** 2017-04-13 08:22**MOT test number** 882365065692**Result** ✓ Passed**MOT #3** 2016-04-29 08:32**MOT test number** 182330708813**Result** ✓ Passed**MOT #2** 2015-06-23 11:45**MOT test number** 785974575175**Result** ✓ Passed**Notice** Nail in offside rear tyre**MOT #1** 2014-07-04 15:43**MOT test number** 189355484191**Result** ✓ Passed



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this MINI had different number plates.

| | |
|----------------------|------------|
| Number of plates | 1 |
| Current registration | |
| Plate since | 2024-03-29 |
| Current registration | |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 16 |
| First mileage registration | 2011-09-30 |
| Last registration | 2023-11-22 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2011-09-30 | 19 mi |
| Registration #2 | 2014-07-04 | 26.489 mi |
| Registration #3 | 2015-06-23 | 28.845 mi |
| Registration #4 | 2016-04-29 | 31.145 mi |
| Registration #5 | 2017-04-13 | 39.341 mi |
| Registration #6 | 2018-04-27 | 50.510 mi |
| Registration #7 | 2019-04-24 | 60.914 mi |
| Registration #8 | 2019-04-24 | 60.914 mi |
| Registration #9 | 2019-04-24 | 60.914 mi |
| Registration #10 | 2019-04-24 | 60.914 mi |
| Registration #11 | 2019-04-24 | 60.914 mi |
| Registration #12 | 2019-04-24 | 60.914 mi |
| Registration #13 | 2019-04-24 | 60.914 mi |
| Registration #14 | 2019-04-24 | 60.914 mi |
| Registration #15 | 2019-04-24 | 60.914 mi |
| Registration #16 | 2019-04-24 | 60.914 mi |

More info >



Car features

The MINI factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

| | |
|----------------|---------------------------------|
| NCAP rating | ★★★★★ |
| Adult | 84% |
| Children | 83% |
| Pedestrian | 63% |
| Safety systems | 71% |
| Overall rating | 78% |
| Video | see crash video |



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1789 mm |
| Height | 1577 mm |
| Length | 4097 mm |
| Kerb weight | 1380 kg |
| Max. allowed weight | 1850 kg |

Additional information

| | |
|-----------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 5 |
| Number of seats | 5 |
| Engine number | 71247709 |