



report date: 2024-03-28

General information

Make	JAGUAR
Model	S-TYPE V6 SE
Colour	Black
Year of manufacture	2006
Top speed	145 mph
0 - 60 mph	7.5 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	240 BHP
Max. torque	299 Nm at 4.100 rpm
Engine capacity	2.967 cc
Cylinders	6
Fuel type	Petrol
Consumption city	18.5 mpg
Consumption extra urban	35.3 mpg
Consumption combined	26.4 mpg
CO2 emission	259 g/km
CO2 label	M





Internet history

Entry 1

Date	2021-12-30
Pictures	15
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



## MOT history

MOT expiry date	2024-08-25
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	50
Total items failed	11

MOT #22 2023-08-24 14:45

MOT test number 471183201304

Result ✓ Passed

Next expiry date 2024-08-25

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Outer Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Minor** Offside Rear Outer Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

MOT #21 2022-08-26 09:05

MOT test number 381677240080

Result ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #20**

2022-08-26 09:05

**MOT test number**

978683488937

**Result****✗ Failed****Minor**

Nearside Rear Suspension rod ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**Advice**

Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Pass with rectification**

Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

**Advice**

Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #19**

2021-10-27 14:34

**MOT test number**

229858036227

**Result****✓ Passed****MOT #18**

2020-09-21 13:08

**MOT test number**

703334786177

**Result****✓ Passed****Advice**

Unable to see/inspect rear inner and outer brake pads

**Advice**

Rear coil springs corroded

**Advice**

Offside Front Coil spring corroded lower part (5.3.1 (b) (i))

**Advice**

Front brake pads wearing low

**Advice**

Rear tyres getting low on tread

**Advice**

Offside Front Wheel bearing slightly noisy and slightly rough (5.1.3 (b) (i))

**MOT #17**

2020-09-21 13:08

**MOT test number**

967424032535

**Result****✗ Failed**

- Advice** Unable to see/inspect rear inner and outer brake pads
- Advice** Rear coil springs corroded
- Advice** Offside Front Coil spring corroded lower part (5.3.1 (b) (i))
- Advice** Front brake pads wearing low
- Advice** Rear tyres getting low on tread
- Pass with rectification** Offside Front Position lamp not working side light (4.2.1 (a) (ii))
- Advice** Offside Front Wheel bearing slightly noisy and slightly rough (5.1.3 (b) (i))

**MOT #16**

2019-04-02 09:17

**MOT test number**

401873517723

**Result****✓ Passed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Front brake pads wearing low

**MOT #15**

2019-03-29 12:27

**MOT test number**

383874781175

**Result****✗ Failed**

- Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt
- Advice** Offside Front tyre worn heavily on inner edge
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt
- DANGEROUS** Nearside Front Tyre has ply or cords exposed tyre inner edge due to cuts in more than 1 place (5.2.3 (d) (ii))
- Advice** Front brake pads wearing low

**MOT #14** 2018-03-22 10:00**MOT test number** 679203025156**Result** ✓ Passed

- Advice** Offside Front wheel bearing slightly rough when rotated
- Advice** Unable to inspect front inner brake pads
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #13** 2017-03-25 12:46**MOT test number** 983336514280**Result** ✓ Passed

- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #12** 2017-03-24 11:25**MOT test number** 680235698445**Result** ✗ Failed

- Advice** Nearside Front fog light broken glass sharp edges
- Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
- Fail** Nearside Stop lamp not working bulb in wrong (1.2.1b)
- Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Rear Child Seat fitted not allowing full inspection of adult belt

**MOT #11** 2016-03-18 12:07**MOT test number** 210420976018**Result** ✓ Passed**MOT #10** 2015-03-20 11:26**MOT test number** 429639675069**Result** ✓ Passed

**MOT #9** 2014-03-13 10:56**MOT test number** 178672774047**Result** ✓ Passed**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #8** 2014-03-13 10:21**MOT test number** 139042274024**Result** ✗ Failed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #7** 2013-03-08 14:47**MOT test number** 239047263006**Result** ✓ Passed**MOT #6** 2012-03-22 13:18**MOT test number** 905082282059**Result** ✓ Passed**Notice** Centre rear and near side rear seat belt buckles not tested due to child seat fitted in nsr seat**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2012-03-21 16:08**MOT test number** 138621282469**Result** ✗ Failed**Notice** Centre rear and near side rear seat belt buckles not tested due to child seat fitted in nsr seat**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Notice** Child seat fitted not allowing full inspection of adult belt**Fail** Offside Rear Stop lamp adversely affected by the operation of another lamp (1.2.1f)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2011-03-14 12:13**MOT test number** 276863371069**Result** ✓ Passed**Notice** Wiper blades splitting at ends.**MOT #3** 2010-03-15 13:05**MOT test number** 143814670024**Result** ✓ Passed**MOT #2** 2009-03-16 17:03**MOT test number** 343645379035**Result** ✓ Passed**MOT #1** 2009-03-16 11:32**MOT test number** 413445979028**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
25 August 2024

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	185
<b>MOT expiry date</b>	25 August 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	K
<b>Single payment (12 months)</b>	£ 395,00,-
<b>Single six month payment</b>	£ 217,25,-
<b>Total payable by 12 monthly instalments</b>	£ 414,75,-



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2006-03-23
Last registration	2023-08-24
Complete history	<a href="#">See info</a>



Registration #1	2006-03-23	6 mi
Registration #2	2009-03-16	20.808 mi
Registration #3	2009-03-16	20.808 mi
Registration #4	2010-03-15	26.496 mi
Registration #5	2011-03-14	31.290 mi
Registration #6	2012-03-21	37.498 mi
Registration #7	2012-03-22	37.498 mi
Registration #8	2013-03-08	43.211 mi
Registration #9	2014-03-13	49.874 mi
Registration #10	2014-03-13	49.874 mi
Registration #11	2015-03-20	59.402 mi
Registration #12	2016-03-18	68.767 mi
Registration #13	2016-03-18	68.767 mi
Registration #14	2016-03-18	68.767 mi
Registration #15	2016-03-18	68.767 mi
Registration #16	2016-03-18	68.767 mi
Registration #17	2016-03-18	68.767 mi
Registration #18	2016-03-18	68.767 mi
Registration #19	2016-03-18	68.767 mi
Registration #20	2016-03-18	68.767 mi
Registration #21	2016-03-18	68.767 mi
Registration #22	2016-03-18	68.767 mi
Registration #23	2016-03-18	68.767 mi
Registration #24	2016-03-18	68.767 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2040 mm
Height	1444 mm
Length	4861 mm
Wheel base	2909 mm
Kerb weight	1710 kg
Max. allowed weight	2180 kg

Additional information

Fuel tank capacity	69 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	542328359FG