





### General information

Make	HONDA
Model	CR-V I-DTEC EX
Colour	White
Year of manufacture	2014
Top speed	118 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	148 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.199 сс
Cylinders	4
Fuel type	Diesel
Consumption city	42.2 mpg
Consumption extra urban	53.3 mpg
Consumption combined	48.7 mpg
CO2 emission	149 g/km
CO2 label	F







## Internet history

Entry 1

Date

Pictures

2021-06-04

3

Listing price

View report







source: autotrader.co.uk



## MOT history

MOT expiry date	2025-03-15
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	18
Total items failed	1

МОТ #9	2024-03-12 12:52
MOT test number	387201810204
Result	✓ Passed
Next expiry date	2025-03-15

MOT #8		2023-03-15 11:45
MOT test	number	809272989141
Result		Passed
Advice	Front Tyre worn close to legal limit/worn on edge BOTH TYRES (5.2.3 (e))	
Advice	Rear Tyre worn close to legal limit/worn on edge BOTH TYRES (5.2.3 (e))	

MOT #7	2022-02-21 10:09	
MOT test number	487825164300	
Result	✓ Passed	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Tyre PressureMonitoring Warning lamp illuminated / Not Obviously Inoperativ	/e.	
<b>Advice</b> Nearside Rear Suspension component mounting prescribed area is corroded but not considered excessive forward axle location mounting. (5.3.6 (a) (i))		
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Nearside Front washer jet slightly defected.		
<b>Advice</b> Offside Rear Suspension component mounting prescribed area is corroded but excessive forward axle location arm mounting. (5.3.6 (a) (i))	ut not considered	



<b>RK14</b>	TGF
report date:	2024-03-28

MOT #6	2022-02-21 10:09	
MOT test number	415638226571	
Result	🗙 Failed	
Advice Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Nearside Rear Suspension component mounting prescribed area is corroded b	ut not considered	
excessive forward axle location mounting. (5.3.6 (a) (i))		
Advice Tyre PressureMonitoring Warning lamp illuminated / Not Obviously Inoperative	2.	
Pass with rectificationOffside Rear Rear fog lamp not working (4.5.1 (a) (ii))		
Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))		
Advice Offside Rear Suspension component mounting prescribed area is corroded but not considered		
excessive forward axle location arm mounting. (5.3.6 (a) (i))		
Advice Nearside Front washer jet slightly defected.		

MOT #5	2021-03-12 11:02
MOT test number	935318614824
Result	✓ Passed

MOT #4	2020-03-02 10:37
MOT test number	565769679482
Result	✓ Passed

Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #32019-02-26 12:02MOT test Imber344754085448ResultImage: PassedAdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))AdviceFront Brake pad(s) wearing thin (1.1.13 (a) (ii))AdviceOffside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice





MOT #2	2018-03-13 11:06
MOT test number	949052763940
Result	✓ Passed
MOT #1	2017-03-16 17:57
MOT test number	497502346549
Result	✓ Passed



Tax & MOT check

	√ xed	Expires:	✓ МОТ
1 March 2025		15 March 2025	Valid until 1 March
Days left			306
MOT expiry date			15 March 2025
Full MOT history			See MOT history

## Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-





### Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	Lamp
Туре	
Damage 2	AMPL
Date	
Date	OLE
Category	E.S.
Туре	

#### Extra HONDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	6 10.200
Auction value	4 10.000
Average private trade value	4 11 200





## Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

and the second	
************	
*******	
******	
***********	
*******	
	More info >
Plate changes	
See in this check if this HONDA had different number pla	tes.
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	
	More info >





### Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this HONDA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





# Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-03-03
Last registration	2024-03-12
Complete history	See info



Registration #1	2014-03-03	13 mi
Registration #2	2017-03-16	35.380 mi
Registration #3	2018-03-13	43.504 mi
Registration #4	2019-02-26	50.077 mi
Registration #5	2020-03-02	56.194 mi
Registration #6	2021-03-12	60.906 mi
Registration #7		10.317 est
Registration #7 Registration #8		11.777 es
•		11,777 es
Registration #8		01,000 est 01,000 est 01,000 est 01,000 est





# Safety ratings

NCAP rating	****
Adult	93%
Children	74%
Pedestrian	68%
Safety systems	66%
Overall rating	81%
Video	see crash video



Dimensions & weight	
Width	1820 mm
Height	1675 mm
Length	4530 mm
Wheel base	2630 mm
Kerb weight	1753 kg
Max. allowed weight	2200 kg
Additional information	
Additional information Fuel tank capacity	58 I
	58 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 5