



report date: 2024-03-29

## General information

Make	VAUXHALL
Model	ANTARA SE NAV CDTI S/S
Colour	Black
Year of manufacture	2013
Top speed	117 mph
0 - 60 mph	9.6 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	161 BHP
Max. torque	350 Nm at 2.000 rpm
Engine capacity	2.231 cc
Cylinders	4
Fuel type	Diesel
Consumption city	35.8 mpg
Consumption extra urban	50.4 mpg
Consumption combined	44.1 mpg
CO2 emission	170 g/km
CO2 label	H





Internet history

Entry 1

Date	2021-12-12
Pictures	27
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2024-04-17
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	44
Total items failed	9

MOT #112023-04-18 12:01

MOT test number276839428962

Result✓ Passed

Next expiry date2024-04-17

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice

Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))
- Minor

Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush (5.3.4 (a) (i))
- Advice

Stone chip in front windscreen
- Advice

Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Minor

Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))
- Advice

Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush (5.3.4 (a) (i))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #10**

2023-04-11 08:27

**MOT test number**

689545220137

**Result****✗ Failed**

- Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))
- Fail** Headlamp cleaning device for LED or HID headlamp inoperative (4.1.6 (a) (ii))
- Minor** Offside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Fail** Nearside Rear Seat belt retracting mechanism defective (7.1.2 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush (5.3.4 (a) (i))
- Fail** Reversing lamp inoperative (4.6.1 (a))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Fail** Offside Rear Seat belt retracting mechanism defective (7.1.2 (e))
- Advice** Stone chip in front windscreen
- Fail** Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm main bush (5.3.4 (a) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #9** 2021-12-15 16:15**MOT test number** 701917253614**Result** ✓ Passed**MOT #8** 2021-04-19 14:50**MOT test number** 117851097573**Result** ✓ Passed**Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))**Advice** Offside Front Outer c.v gaiter deteriorated**MOT #7** 2020-06-29 10:31**MOT test number** 420777772010**Result** ✓ Passed**Advice** Exhaust corroded at rear joiners**Advice** Brake pad(s) wearing thin both rears (1.1.13 (a) (ii))**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**MOT #6** 2020-06-26 11:57**MOT test number** 521787645157**Result** ✗ Failed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Nearside Front Side repeater slightly discoloured (4.4.3 (a))**Advice** Exhaust corroded at rear joiners**Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Brake pad(s) wearing thin both rears (1.1.13 (a) (ii))

**MOT #5**

2019-05-17 07:41

**MOT test number**

551466293865

**Result**

✓ Passed

**Advice** Nearside Rear Nail in tyre**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Child Seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #4**

2018-05-17 11:33

**MOT test number**

745587195652

**Result**

✓ Passed

**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Oil leak**Advice** Offside Rear Shock absorber has a light misting of oil (2.7.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Exhaust corrosion noted**MOT #3**

2017-06-07 09:40

**MOT test number**

413092322019

**Result**

✓ Passed



MOT #2	2017-04-04 13:09
MOT test number	372759971695
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #1	2016-03-17 12:15
MOT test number	613348128347
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 April 2025

✗  
**MOT**  
  
Expired:  
17 April 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	17 April 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-





Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29
Number of owners	1
Current owner since	2019-06-29
Previous owner since	2019-06-29

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>GJ13DDN</b>
Plate since	2019-06-29
Current registration	 <b>GJ13DDN</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2013-04-13
Last registration	2023-04-18
Complete history	<a href="#">See info</a>



Registration #1	2013-04-13	13 mi
Registration #2	2016-03-17	32.492 mi
Registration #3	2017-04-04	41.413 mi
Registration #4	2017-06-07	42.922 mi
Registration #5	2018-05-17	54.753 mi
Registration #6	2019-05-17	66.140 mi
Registration #7	2020-06-26	77.173 mi
Registration #8	2020-06-26	77.173 mi
Registration #9	2020-06-26	77.173 mi
Registration #10	2020-06-26	77.173 mi
Registration #11	2020-06-26	77.173 mi
Registration #12	2020-06-26	77.173 mi
Registration #13	2020-06-26	77.173 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	95%
Children	84%
Pedestrian	46%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2085 mm
Height	1717 mm
Length	4596 mm
Wheel base	2707 mm
Kerb weight	1896 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	Z22D1 291601K LNQ