




report date: 2024-03-29

General information

|                     |                   |
|---------------------|-------------------|
| Make                | FORD              |
| Model               | FUSION FUSION +   |
| Colour              | Blue              |
| Year of manufacture | 2009              |
| Top speed           | 109 mph           |
| 0 - 60 mph          | 12.7 seconds      |
| Gearbox             | 5 speed automatic |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 100 BHP             |
| Max. torque             | 145 Nm at 4.000 rpm |
| Engine capacity         | 1.596 cc            |
| Cylinders               | 4                   |
| Fuel type               | Petrol              |
| Consumption city        | 27.4 mpg            |
| Consumption extra urban | 46.3 mpg            |
| Consumption combined    | 37.2 mpg            |
| CO2 emission            | 179 g/km            |
| CO2 label               | I                   |






Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2022-05-14                  |
| Pictures      | 16                          |
| Listing price | <a href="#">View report</a> |



source: cargurus.co.uk



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2024-05-17 |
| MOT pass rate      | 73 %       |
| MOT passed         | 11         |
| Failed MOT tests   | 4          |
| Total advice items | 22         |
| Total items failed | 16         |

MOT #15 2023-05-17 16:51

MOT test number 413543286507

Result ✓ Passed

Next expiry date 2024-05-17

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #14 2022-05-18 07:36

MOT test number 288870681004

Result ✓ Passed

MOT #13 2021-08-24 10:14

MOT test number 647344529594

Result ✓ Passed

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing 195 60 15 (5.2.3 (d) (ii))

**MOT #12**

2021-06-17 11:51

**MOT test number**

943994332781

**Result**

✓ Passed

**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**MOT #11**

2021-06-16 10:17

**MOT test number**

934684796002

**Result**

✗ Failed

**Minor** Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking between treads (5.2.3 (d) (ii))**Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))**Advice** Central Rear Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))**Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))**Minor** Offside Rear Windscreen wiper blade defective (3.4 (b) (i))**Minor** Offside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Front Windscreen washer not working (3.5 (a))**Minor** Nearside Front Windscreen wiper blade defective (3.4 (b) (i))**MOT #10**

2019-12-10 13:15

**MOT test number**

921401866582

**Result**

✓ Passed

**MOT #9**

2019-12-02 13:20

**MOT test number**

645108352271

**Result**

✗ Failed

- Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Nearside Rear Brake pipe connection leaking on a hydraulic braking system (1.1.11 (b) (ii))
- Fail** Offside Rear Brake pipe excessively corroded to front (1.1.11 (c))
- Fail** Rear Brakes imbalanced across an axle by more than 50% 55% (1.2.1 (b) (ii))
- Fail** Offside Stop lamp(s) adversely affected by the operation of another lamp (4.3.3 (b))
- Minor** Brake fluid warning lamp illuminated (1.1.10 (f))
- Fail** Nearside Windscreen damaged and affecting the driver's view of the road (3.2 (a) (ii))
- Fail** Nearside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

**MOT #8**

2018-05-30 10:37

**MOT test number**

146115800974

**Result**

✓ Passed

- Advice** Nearside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #7**

2017-05-11 12:10

**MOT test number**

168708227849

**Result**

✓ Passed

**MOT #6** 2017-05-11 12:10**MOT test number** 275341577182**Result** ✗ Failed**Pass with rectification** Nearside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Offside Rear fog lamp not working (1.3.2b)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**MOT #5** 2015-11-06 12:05**MOT test number** 770850014167**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2015-11-06 12:05**MOT test number** 111382588371**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Pass with rectification** Offside Stop lamp not working (1.2.1b)**MOT #3** 2014-10-22 11:15**MOT test number** 157745594276**Result** ✓ Passed**MOT #2** 2013-10-25 08:57**MOT test number** 319328393258**Result** ✓ Passed



|                 |                  |
|-----------------|------------------|
| MOT #1          | 2012-11-01 14:35 |
| MOT test number | 755246402315     |
| Result          | ✓ Passed         |



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 September 2024

✓  
**MOT**  
**Expires:**  
17 May 2024

|                         |                                 |
|-------------------------|---------------------------------|
| <b>Tax status</b>       | Valid until 1 September         |
| <b>Days left</b>        | 125                             |
| <b>MOT expiry date</b>  | 17 May 2024                     |
| <b>Full MOT history</b> | <a href="#">See MOT history</a> |

Tax calculation

|  |            |
|--|------------|
| <b>Vehicle class</b>                           | 48         |
| <b>Band</b>                                    | I          |
| <b>Single payment (12 months)</b>              | £ 320,00,- |
| <b>Single six month payment</b>                | £ 176,00,- |
| <b>Total payable by 12 monthly instalments</b> | £ 336,00,- |





Damage history


Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |
| ***** | ***** |

More info >

Plate changes

See in this check if this FORD had different number plates.

|                      |            |
|----------------------|------------|
| Number of plates     | 1          |
| Current registration | *****      |
| Plate since          | 2019-09-29 |
| Current registration | *****      |
| Plate since          | 2019-09-29 |

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.


|                   |          |          |
|-------------------|----------|----------|
| Finance company   | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type    | REDACTED | REDACTED |
| Agreement term    | REDACTED | REDACTED |
| Agreement number  | REDACTED | REDACTED |
| Contact info      | REDACTED | REDACTED |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 17                       |
| First mileage registration | 2009-12-23               |
| Last registration          | 2023-05-17               |
| Complete history           | <a href="#">See info</a> |





Car features

The FORD factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

|                     |         |
|---------------------|---------|
| Width               | 1963 mm |
| Height              | 1543 mm |
| Length              | 4013 mm |
| Wheel base          | 2485 mm |
| Kerb weight         | 1110 kg |
| Max. allowed weight | 1630 kg |

Additional information

|                    |                       |
|--------------------|-----------------------|
| Fuel tank capacity | 45 l                  |
| Fuel delivery      | Multi-Point Injection |
| Number of doors    | 5                     |
| Number of seats    | 5                     |

|                        |         |
|------------------------|---------|
| <b>Number of axles</b> | 2       |
| <b>Engine number</b>   | 9P21532 |