



UK

SLIIZFH

report date: 2024-03-29

General information

|                     |                |
|---------------------|----------------|
| Make                | VOLKSWAGEN     |
| Model               | CADDY C20 TDI  |
| Colour              | Red            |
| Year of manufacture | 2011           |
| Top speed           | 93 mph         |
| 0 - 60 mph          | 16.7 seconds   |
| Gearbox             | 5 speed Manual |

Engine & fuel consumption

|                         |                     |
|-------------------------|---------------------|
| Power                   | 74 BHP              |
| Max. torque             | 225 Nm at 1.500 rpm |
| Engine capacity         | 1.598 cc            |
| Cylinders               | 4                   |
| Fuel type               | Diesel              |
| Consumption city        | 42.2 mpg            |
| Consumption extra urban | 53.3 mpg            |
| Consumption combined    | 49.6 mpg            |



LABEL UNKNOWN



Internet history

Entry 1

|               |                             |
|---------------|-----------------------------|
| Date          | 2021-02-06                  |
| Pictures      | 1                           |
| Listing price | <a href="#">View report</a> |



source: [autoonline.co.uk](https://www.autoonline.co.uk)



## MOT history

|                    |            |
|--------------------|------------|
| MOT expiry date    | 2025-02-18 |
| MOT pass rate      | 91 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 1          |
| Total advice items | 15         |
| Total items failed | 6          |

|                  |                  |
|------------------|------------------|
| MOT #11          | 2024-01-24 10:58 |
| MOT test number  | 528551793511     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-02-18       |

|                 |  |
|-----------------|--|
| MOT #10         | 2023-02-07 12:29   |
| MOT test number | 338201884454   |
| Result          | ✓ Passed   |
| Advice          | Offside Rear Exhaust silencer slightly loose outer skin corroded (8.1.1 (b) (i)) |

|                 |   |
|-----------------|---|
| MOT #9          | 2022-02-11 15:15  |
| MOT test number | 232445529389  |
| Result          | ✓ Passed  |
| Advice          | Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) |
| Advice          | Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))             |

**MOT #8** 2021-02-19 16:31**MOT test number** 406926189003**Result** ✓ Passed

- Advice** Rear silencer deteriorating
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**MOT #7** 2019-05-20 11:31**MOT test number** 666571217807**Result** ✓ Passed

- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #6** 2019-05-17 13:28**MOT test number** 618290197805**Result** ✗ Failed

- Fail** Offside Rear Anti-roll bar pin or bush excessively worn Saddle bush (5.3.4 (a) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Rear Anti-roll bar pin or bush excessively worn Saddle bush (5.3.4 (a) (i))
- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))
- Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Minor** Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

**MOT #5** 2018-05-17 11:10**MOT test number** 620323324032**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit inner edge (4.1.E.1)**Advice** Slight fuel misting at injector, no leak at time of test**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened inner surface (3.5.1i)**Advice** Offside Rear brake binding slightly**MOT #4** 2017-04-27 06:51**MOT test number** 553960316736**Result** ✓ Passed**MOT #3** 2016-04-27 09:45**MOT test number** 374286871484**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**MOT #2** 2015-05-08 15:02**MOT test number** 557768625102**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)**MOT #1** 2014-05-06 17:18**MOT test number** 377166524128**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
18 February 2025

|                  |  |                                 |
|------------------|--|---------------------------------|
| Tax status       |  | Valid until 1 February          |
| Days left        |  | 279                             |
| MOT expiry date  |  | 18 February 2025                |
| Full MOT history |  | <a href="#">See MOT history</a> |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |

Damage 2

|          |  |
|----------|--|
| Date     |  |
| Category |  |
| Type     |  |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

|                             |          |
|-----------------------------|----------|
| Trade retail value          | £ 19,999 |
| Auction value               | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >





Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

|       |       |
|-------|-------|
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |
| Owner | Since |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

|                      |  |
|----------------------|--|
| Number of plates     | 1  |
| Current registration |  <b>SL11ZFH</b> |
| Plate since          | 2019-03-29   |
| Current registration |  <b>SL11ZFH</b> |
| Plate since          | 2019-03-29   |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

|                   |          |      |
|-------------------|----------|------|
| Finance company   | XXXXXXXX | XXXX |
| Date of agreement | XXXXXXXX | XXXX |
| Agreement type    | XXXXXXXX | XXXX |
| Agreement term    | XXXXXXXX | XXXX |
| Agreement number  | XXXXXXXX | XXXX |
| Contact info      | XXXXXXXX | XXXX |

More info >



Mileage check

|                            |                          |
|----------------------------|--------------------------|
| Odometer                   | In miles                 |
| Mileage registrations      | 13                       |
| First mileage registration | 2011-05-26               |
| Last registration          | 2024-01-24               |
| Complete history           | <a href="#">See info</a> |



|                  |            |            |
|------------------|------------|------------|
| Registration #1  | 2011-05-26 | 16 mi      |
| Registration #2  | 2014-05-06 | 16.098 mi  |
| Registration #3  | 2015-05-08 | 21.030 mi  |
| Registration #4  | 2016-04-27 | 25.089 mi  |
| Registration #5  | 2017-04-27 | 44.043 mi  |
| Registration #6  | 2018-05-17 | 63.102 mi  |
| Registration #7  | 2019-05-17 | 81.089 mi  |
| Registration #8  | 2020-05-06 | 99.999 mi  |
| Registration #9  | 2021-05-06 | 118.888 mi |
| Registration #10 | 2022-05-06 | 137.777 mi |
| Registration #11 | 2023-05-06 | 156.666 mi |
| Registration #12 | 2024-01-24 | 175.555 mi |
| Registration #13 | 2024-03-29 | 194.444 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

|       |                  |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 |                  |
| S0482 |                  |
| S0501 |                  |
| S0566 |                  |
| S0567 |                  |
| S0569 |                  |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

|             |         |
|-------------|---------|
| Width       | 2062 mm |
| Height      | 1836 mm |
| Length      | 4876 mm |
| Kerb weight | 1475 kg |

Additional information

|                    |                  |
|--------------------|------------------|
| Fuel tank capacity | 60 l             |
| Fuel delivery      | Direct Injection |
| Number of doors    | 5                |
| Number of seats    | 2                |
| Engine number      | CAY C55081       |