





### General information

Make	VOLVO
Model	V90 D5 POWERPULSE R-DESIGN PRO AWD
Colour	Grey
Year of manufacture	2018
Top speed	145 mph
0 - 60 mph	6.9 seconds
Gearbox	8 speed automatic

## Engine & fuel consumption

Power	231 BHP
	201 0111
Max. torque	480 Nm at 1.750 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	57.7 mpg
CO2 emission	129 g/km
CO2 label	D





DX68FNT report date: 2024-03-29

ntry 1			
late	2022-06-	11	
ictures	6		
isting price	View repo	ort	
VOLVO	V O L V O	VOLVO	VOLVO
I DAY MONEY BACK UARANTEE ON USED CARS <sup>A</sup> with confidence at Marshall	ELICK. CONNECT. DRIVE. - Physical & Digital Appendements Analytike - Phone, Ernal, & Live Chat. - Wates/Zoom Call Appendements - Back Olstank for ISBN - M Day Marey Itack Gazantare on Lived Cars. - Olsta Callett - Itaria Delivery Services Analytik. - Castections Experience & Punchase	RESERVE THIS CAR FOR £99' With a first cloba, you can instantly reserve this can with a fully refundable reservation of £98, We accept than, Mastercent, Googie Hey and Apple Hay.	BENEFITS OF BUYING AN APPROVED USED VOLVO FROM US. - 30-day / 1500 met sufficienting gaventes - 3-month Valve Austideen - 3-mo



## MOT history

MOT expiry date	2024-07-17
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	5
Total items failed	2

MOT #5	2023-07-18 08:23
MOT test number	184896869852
Result	🗸 Passed
Next expiry date	2024-07-17
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply	or cords Main tread (5.2.3 (d) (i))

MOT #4	2023-07-10 08:2	14
MOT test	number 84200645404	19
Result	× Faile	ed
Advice	Offside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords Main tread (5.2.3 (d) (i))		)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Inner edge worn (5.2.3 (e))	
Fail Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))		

MOT #3	2022-07-14 15:31
MOT test number	370410858352
Result	✓ Passed
MOT #2	2021-09-27 11:51
MOT test number	275991587991

MOT test number	275991587991
Result	✓ Passed





MOT #1	2021-09-27 09:10
MOT test number	948532979750
Result	🗙 Failed
AdviceNearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))FailOffside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))	



Tax & MOT check

√ Taxed	✓ MOT
Tax due: 1 July 2024	Expires: 17 July 2024
Tax status	Valid until 1 July
Days left	62
MOT expiry date	17 July 2024
Full MOT history	See MOT history

## Tax calculation

Vehicle class	49
Band	G
First licence fee (12 months)	£ 210,00,-
First licence fee diesel non RDE2 tested (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





#### Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FEIDO
Category	4. ARMPE
Туре	
Damage 2	AMPL
	F Stores
Date	1.E
Category	ante
Туре	

#### Extra VOLVO salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info  $\rightarrow$ 





#### Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200

More info  $\rightarrow$ 





## Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

******	
***********	
*******	
******	
***********	
********	
	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	


More info  $\rightarrow$ 





# Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-27
Last registration	2023-07-18
Complete history	See info



Registration #1	2018-09-27	17 mi
Registration #2	2021-09-27	49.413 mi
Registration #3	2021-09-27	49.413 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 est
Registration #7		11.777 mi

More info >





## Car features

S0225	Air conditioning
\$0295	
S0482	
\$0501	
50566	
\$0567	
S0569	

# Safety ratings

NCAP rating	****
Adult	95%
Children	80%
Pedestrian	76%
Safety systems	93%
Overall rating	88%
Video	see crash video



Dimensions & weight	
Width	1895 mm
Height	1475 mm
Length	4936 mm
Wheel base	2941 mm
Kerb weight	1783 kg
Max. allowed weight	2400 kg
Additional information	
Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	2459800