



Mercedes-Benz



report date: 2024-03-29

General information

Make	MERCEDES
Model	C C220 CDI SPORT
Colour	Black
Year of manufacture	2007
Top speed	141 mph
Gearbox	5 speed automatic

Engine & fuel consumption

Power	168 BHP
Max. torque	400 Nm at 2.000 rpm
Engine capacity	2.148 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.7 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	177 g/km
CO2 label	I





MOT history

MOT expiry date	2024-08-23
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	49
Total items failed	12

MOT #19 2023-08-24 10:29

MOT test number 889409396062

Result ✓ Passed

Next expiry date 2024-08-23

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #18 2023-08-24 10:29

MOT test number 824164840683

Result ✗ Failed

Pass with rectification Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))

Minor Nearside Front Lower Suspension arm ball joint dust cover severely deteriorated (5.3.4 (b) (i))

Pass with rectification Offside Front Position lamp not working (4.2.1 (a) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Pass with rectification Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))

Minor Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #17**

2022-06-01 09:56

MOT test number

461926983006

Result

✓ Passed

Advice Parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (1.4.2 (a) (i))

MOT #16

2021-06-09 15:48

MOT test number

601964808394

Result

✓ Passed

Advice All position lamps have a product on the lenses but not adversely affecting light output all lamps (4.2.3 (b) (ii))

Advice Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

Advice Front Tyre slightly damaged/cracking or perishing both sides sidewalls slight damaged (5.2.3 (d) (ii))

Minor Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

Advice Headlamp has a product on the lens but not seriously reducing light output both sides (4.1.4 (b))

MOT #15

2020-05-20 09:54

MOT test number

661676734093

Result

✓ Passed

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Number of under covers fitted at time of test / engine cover fitted

Advice Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Brake pipe corroded, covered in grease or other material both n/s/r pipes near arch (1.1.11 (c))

**MOT #14** 2019-06-07 12:17**MOT test number** 658962197537**Result** ✓ Passed**Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))**Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge recommend replacement/camber check (5.2.3 (e))**MOT #13** 2019-06-07 11:28**MOT test number** 157301786910**Result** ✗ Failed**Fail** Nearside Rear Service brake lagging in operation (1.2.1 (d))**Advice** Offside Rear Inner Tyre worn close to legal limit/worn on edge recommend replacement/camber check (5.2.3 (e))**Minor** Nearside Front Position lamp incorrect colour (4.2.3 (a) (i))**Minor** Offside Front Position lamp incorrect colour (4.2.3 (a) (i))**MOT #12** 2018-06-09 13:39**MOT test number** 745469240108**Result** ✓ Passed**Advice** Rear Exhaust emits excessive smoke or vapour but not likely to obscure the vision of other road users (8.2.2.2 (c))**MOT #11** 2017-06-05 10:37**MOT test number** 447315784379**Result** ✓ Passed**MOT #10** 2017-06-05 08:29**MOT test number** 975059818774**Result** ✗ Failed**Fail** Nearside Rear Wheel nut(s) missing (4.2.A.1e)

**MOT #9** 2016-06-30 12:08**MOT test number** 126122208149**Result** ✓ Passed**Advice** Nearside Front Lower Ball joint has slight play (2.2.B.1f)**MOT #8** 2015-07-06 14:44**MOT test number** 727147785103**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**Advice** Offside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Outer Front Road wheel with a slightly distorted bead rim (4.2.A.1a)**Advice** Nearside Inner Rear Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Outer Rear Road wheel with a slightly distorted bead rim (4.2.A.1a)**MOT #7** 2014-08-02 10:32**MOT test number** 949874414233**Result** ✓ Passed**MOT #6** 2013-08-02 17:53**MOT test number** 486484913236**Result** ✓ Passed**Advice** Offside Front wheel bearing has slight play (2.5.A.3c)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #5**

2013-08-02 11:49

MOT test number

336684813477

Result

✗ Failed

- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Fail** Offside Rear Stop lamp not working (1.2.1b)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Front wheel bearing has slight play (2.5.A.3c)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front wheel bearing has slight play (2.5.A.3c)

MOT #4

2012-08-07 15:56

MOT test number

987990422246

Result

✓ Passed

- Notice** O/s/r tyre slightly worn from inner edges
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)

MOT #3

2011-07-26 17:14

MOT test number

806887201211

Result

✓ Passed



MOT #2	2010-07-01 11:35
MOT test number	291442780447
Result	✓ Passed

MOT #1	2010-06-30 11:32
MOT test number	370961280125
Result	✗ Failed
<div><div>Fail</div> Nearside Front position lamp(s) not working (1.1.A.3b)</div> <div><div>Fail</div> Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Advice</div> Front Brake pad(s) wearing thin (3.5.1g)</div> <div><div>Fail</div> Nearside Rear position lamp(s) not working (1.1.A.3b)</div> <div><div>Fail</div> Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
23 August 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	23 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-07-25
Last registration	2023-08-24
Complete history	See info



Registration #1	2007-07-25	14 mi
Registration #2	2010-06-30	48.143 mi
Registration #3	2010-07-01	48.183 mi
Registration #4	2011-07-26	61.023 mi
Registration #5	2012-08-07	74.066 mi
Registration #6	2013-08-02	83.787 mi
Registration #7	2013-08-02	83.787 mi
Registration #8	2014-08-02	86.375 mi
Registration #9	2015-07-06	93.795 mi
Registration #10	2016-06-30	100.103 mi
Registration #11	2016-06-30	100.103 mi
Registration #12	2016-06-30	100.103 mi
Registration #13	2016-06-30	100.103 mi
Registration #14	2016-06-30	100.103 mi
Registration #15	2016-06-30	100.103 mi
Registration #16	2016-06-30	100.103 mi
Registration #17	2016-06-30	100.103 mi
Registration #18	2016-06-30	100.103 mi
Registration #19	2016-06-30	100.103 mi
Registration #20	2016-06-30	100.103 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1447 mm
Length	4581 mm
Wheel base	2760 mm
Kerb weight	1560 kg
Max. allowed weight	2090 kg

Additional information

Fuel tank capacity	62 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64681130097391