





report date: 2024-03-29

General information

Make	FORD
Model	TRANSIT 350 LWB HR P/V 115
Colour	Silver
Year of manufacture	2010
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	310 Nm at 1.750 rpm
Engine capacity	2.402 cc
Cylinders	4
Fuel type	Diesel



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 2

Date 2022-04-30

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk


Entry 1

Date	2021-09-28
Pictures	14

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2024-07-27
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #11	2023-07-27 10:57
MOT test number	438966353364
Result	✓ Passed
Next expiry date	2024-07-27

MOT #10	2022-07-28 14:56
MOT test number	175814089498
Result	✓ Passed

MOT #9	2021-08-04 08:07

MOT test number 112772167259

Result \(\sqrt{Passed}\)

Advice Offside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing cracking up badly on sidewall but no ply or cords found (5.2.3 (d) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

Advice Nearside Front Anti-roll bar pin or bush worn but not resulting in excessive movement D bush (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing cracking up badly on sidewall but no ply or cords found (5.2.3 (d) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear bush (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT #8 2020-09-02 16:21

MOT test number 349150074469

Result ✓ Passed

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 215/75/16 continental (5.2.3 (d) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 215/75/16 continental (5.2.3 (d) (ii))

MOT #7 2020-08-18 11:13

MOT test number 177194028629

Result X Failed

Fail Nearside Rear Seat belt buckle not functioning as intended (7.1.2 (d))

Advice Offside Rear Tyre slightly damaged/cracking or perishing 215/75/16 continental (5.2.3 (d) (ii))

Advice Nearside Front Tyre worn close to legal limit/worn on edge 235/65/16 event (5.2.3 (e))

Advice Nearside Rear Tyre slightly damaged/cracking or perishing 215/75/16 continental (5.2.3 (d) (ii))

Fail Front Tyre(s) of different sizes are fitted on the same axle. 215/75/16 o/s and 235/65/16 n/s (5.2.3 (b))

Advice Offside Front Tyre slightly damaged/cracking or perishing 215/75/16 continental (5.2.3 (d) (ii))

MOT #6 2019-08-13 12:56

MOT test number 281707958762

Result

✓ Passed

MOT #5 2018-06-19 12:55

MOT test number 667325494837

Result ✓ Passed

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #4 2016-08-02 10:31

MOT test number 976794136640

Result \(\sqrt{Passed} \)

Advice Nearside Obligatory mirror damaged, but not seriously affecting the rear view (8.1.2a)

Advice Front Brake pad(s) wearing thin (3.5.1g)

MOT #3 2015-07-29 16:13

MOT test number 829030715201

Result \(\sqrt{Passed} \)

Notice Offside front tyre wearing on inner edge

MOT #2 2014-08-01 10:52

MOT test number 915533014238

Result ✓ Passed

Advice Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Ns mirror casing damaged

Notice Rear discs and pads wearing low

MOT #1 2013-07-29 12:00

MOT test number 758880313232

Result ✓ Passed

Notice Nsf tyre worn on edges and small cuts to sidewall

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Days left 94

MOT expiry date 27 July 2024

Full MOT history See MOT history

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
manus .	

manus .	

	More info >
Plate changes	
Con in this chool if this FORD had different acceptance along	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	UK UK
Finite since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2010-07-30
Last registration	2023-07-27
Complete history	See info



Registration #1	2010-07-30	6 mi
Registration #2	2013-07-29	67.287 mi
Registration #3	2014-08-01	92.779 mi
Registration #4	2015-07-29	114.119 mi
Registration #5	2016-08-02	142.700 mi
Registration #6	2018-06-19	17.052 mi
Registration #7	2019-08-13	18.547 mi
Registration #8		71.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 au

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Dimensions & weight

Width	2360 mm
Height	2601 mm
Length	5680 mm
Kerb weight	1790 kg
Max. allowed weight	3500 kg

Additional information

Fuel tank capacity	80
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	3
Engine number	AT18351

CarCheck.co.uk page 12/12