





report date: 2024-03-29

### General information

Make	MERCEDES
Model	SL SL 55 AMG KOMPRESSOR
Colour	Black
Year of manufacture	2004
Top speed	155 mph
0 - 60 mph	4.7 seconds
Gearbox	5 speed automatic

## Engine & fuel consumption

Power	476 BHP
Max. torque	700 Nm at 2.650 rpm
Engine capacity	5.439 cc
Cylinders	8
Fuel type	Petrol
Consumption city	13.5 mpg
Consumption extra urban	26.7 mpg
Consumption combined	19.9 mpg
CO2 emission	324 g/km
CO2 label	M



CarCheck.co.uk page 1/12




## Internet history


### Entry 1

Date 2021-06-29

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT	history
ו טויו	HISLULY

MOT expiry date	2023-09-04
MOT pass rate	89 %
MOT passed	16
Failed MOT tests	2
Total advice items	6
Total items failed	3

MOT #18	2022-09-05 13:30
MOT test number	137083399878
Result	✓ Passed
Next expiry date	2023-09-04

MOT #17	2021-03-08 13:02
MOT test number	525008060297
Result	✓ Passed

MOT #16	2020-03-21 17:07
MOT test number	815111784446
Result	<b>✓</b> Passed

MOT #15	2019-03-19 16:17
MOT test number	582688083433
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14	2018-02-14 09:55
MOT test number	958975251261
Result	<b>✓</b> Passed

CarCheck.co.uk page 3/12



**MOT #13** 2017-02-15 14:02

**MOT test number** 199656953564

MOT #12 2016-02-25 09:34

**MOT test number** 327465879665

**Result** ✓ Passed

**MOT #11** 2015-03-06 13:31

**MOT test number** 176785165028

**Result** 
✓ Passed

MOT #10 2015-03-05 12:17

**MOT test number** 417924565096

**Result** X Failed

Fail Offside Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Front Lower Suspension arm ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)

MOT #9 2014-09-26 12:05

**MOT test number** 875569864222

Result \rightarrow Passed

MOT #8 2013-09-27 15:16

**MOT test number** 529710373285

CarCheck.co.uk page 4/12



MOT #7		2012-08-06 14:17
MOT test	number	967239612269
Result		<b>✓</b> Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	

MOT #6	2011-05-24 10:02
MOT test number	905934241182
Result	✓ Passed
MOT #5	2009-11-30 16:19
MOT test number	731264439344
Result	✓ Passed
MOT #4	2008-10-03 16:02
MOT test number	631657078296
Result	✓ Passed
MOT #3	2008-09-30 17:23
MOT test number	390244178211
Result	<b>X</b> Failed
Fail Offside Front brake disc excessively scored (3.5.1h)	
Fail Nearside Front brake disc excessively scored (3.5.1h)	

MOT #2	2007-06-05 15:38
MOT test number	990206357168
Result	<b>✓</b> Passed

CarCheck.co.uk page 5/12



MOT test number

Result

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

#### Damage 1


Date
Category
Type

Damage 2

Date

Category

**Type** 



#### Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



## Owner history

Owner mistory	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downloner.	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Courts at info	

**Contact info** 


More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-03-31
Last registration	2022-09-05
Complete history	See info



Registration #1	2004-03-31	6 mi
Registration #2	2007-03-20	20.432 mi
Registration #3	2007-06-05	22.174 mi
Registration #4	2008-09-30	26.394 mi
Registration #5	2008-10-03	26.394 mi
Registration #6	2009-11-30	29.504 mi
Registration #7	2011-05-24	32.659 mi
Registration #8	2012-08-06	35.129 mi
Registration #9	2013-09-27	36.176 mi
Registration #10	2014-09-26	37.145 mi
Registration #11		9.70 es
Registration #12		11.777 es
Registration #13		9.70 es
Registration #14		11.777 es
Registration #15		9.70 es
Registration #16		11.777 es
Registration #17		9.70 es
Registration #18		11.777 es
Registration #19		0.70 es
Registration #20		11.777 au

More info >

CarCheck.co.uk page 11/12



# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1815 mm
Height	1295 mm
Length	4535 mm
Wheel base	2560 mm
Kerb weight	1955 kg

## Additional information

Fuel tank capacity	80 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11399260027423

CarCheck.co.uk page 12/12