



report date: 2024-03-28

General information

Make	MAZDA
Model	3 TS2
Colour	Black
Year of manufacture	2011
Top speed	114 mph
0 - 60 mph	12.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	103 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	34.0 mpg
Consumption extra urban	54.3 mpg
Consumption combined	44.8 mpg
CO2 emission	149 g/km
CO2 label	F





MOT history

MOT expiry date	2023-01-30
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	22
Total items failed	2

MOT #13 2022-01-31 14:37

MOT test number 129572825205

Result ✓ Passed

Next expiry date 2023-01-30

- Advice** Rear Exhaust has a minor leak of exhaust gases (6.1.2 (a))
- Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement center upper bush (5.3.4 (a) (i))
- Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
- Advice** Nearside Front Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
- Minor** Offside Front Windscreen wiper blade defective (3.4 (b) (i))

MOT #12 2021-01-26 12:57

MOT test number 211546258141

Result ✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front windscreen damaged

**MOT #11** 2021-01-21 17:38**MOT test number** 963855377579**Result** ✗ Failed**Advice** Front windscreen damaged**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm 205/55/16 (5.2.3 (e))**MAJOR** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))**DANGEROUS** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**MAJOR** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #10** 2019-11-14 16:52**MOT test number** 880856776081**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #9** 2019-11-13 09:28**MOT test number** 925320147302**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #8** 2018-11-15 16:59**MOT test number** 517197429045**Result** ✓ Passed**Advice** Wipers poor

**MOT #7** 2018-11-15 16:25**MOT test number** 476704358268**Result** ✗ Failed**Advice** Wipers poor**MAJOR** Nearside Rear Tyre(s) of different sizes are fitted on the same axle. (5.2.3 (b))**MAJOR** Offside Front Headlamp aim too low (4.1.2 (a))**MOT #6** 2017-10-19 09:30**MOT test number** 155535910983**Result** ✓ Passed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #5** 2016-10-18 15:10**MOT test number** 510472099504**Result** ✓ Passed**MOT #4** 2016-10-18 11:27**MOT test number** 955579843883**Result** ✗ Failed**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**MOT #3** 2015-10-22 08:26**MOT test number** 686824710347**Result** ✓ Passed**MOT #2** 2015-02-04 16:44**MOT test number** 945925635042**Result** ✓ Passed



MOT #1	2014-01-30 10:50
MOT test number	646710634023
Result	✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
1 December 2023

✕
MOT

Expired:
30 January 2023

Tax status	Expired at 1 December 2023
Days left	150 days too late
MOT expiry date	30 January 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-02-08
Last registration	2022-01-31
Complete history	See info



Registration #1	2011-02-08	17 mi
Registration #2	2014-01-30	28.204 mi
Registration #3	2015-02-04	34.354 mi
Registration #4	2015-10-22	38.969 mi
Registration #5	2016-10-18	51.632 mi
Registration #6	2016-10-18	51.632 mi
Registration #7	2017-10-19	60.270 mi
Registration #8	2019-05-29	75.277 mi
Registration #9	2019-05-29	75.277 mi
Registration #10	2019-05-29	75.277 mi
Registration #11	2019-05-29	75.277 mi
Registration #12	2019-05-29	75.277 mi
Registration #13	2019-05-29	75.277 mi
Registration #14	2019-05-29	75.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Adult	86%
Children	84%
Pedestrian	51%
Safety systems	71%
Overall rating	77%
Video	see crash video



Dimensions & weight

Width	2002 mm
Height	1470 mm
Length	4480 mm
Wheel base	2640 mm
Kerb weight	1332 kg
Max. allowed weight	1770 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	Z6 938262