





report date: 2024-03-29

### General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Grey
Year of manufacture	2008
Top speed	132 mph
0 - 60 mph	9.0 seconds
Gearbox	6 speed Manual

### Engine & fuel consumption

Power	173 BHP
Max. torque	400 Nm at 2.750 rpm
Engine capacity	2.179 сс
Cylinders	4
Fuel type	Diesel
Consumption city	31.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.8 mpg
CO2 emission	176 g/km
CO2 label	I



CarCheck.co.uk page 1/14



# Internet history

#### Entry 1

Date 2021-07-31

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/14



B 4	$\sim$ $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-01-25
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	29
Total items failed	7

MOT #16	2024-01-11 14:31
MOT test number	326962571133
Result	<b>✓</b> Passed
Next expiry date	2025-01-25
Advice All rear suspension and arms slight corroded	

MOT #15	2024-01-09 13:35
MOT test number	496954335853
Result	<b>×</b> Failed
Advice All rear suspension and arms slight corroded	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
Fail Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

CarCheck.co.uk page 3/14



**MOT #14** 2023-01-26 15:09

**MOT test number** 491193646816

Advice Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Rear heat shield slightly loose

(i))

Advice Offside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a)

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

Advice Nearside Rear Inner Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #13** 2022-01-13 15:34

MOT test number 571826183252

Result \rightarrow Passed

**Advice** Nearside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Nearside Front Headlamp reflector slightly defective (4.1.1 (b) (i))

**Advice** Offside Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm (5.3.4 (a) (i))

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #12** 2021-01-06 12:49

**MOT test number** 971659439658

CarCheck.co.uk page 4/14



Result

LJ58FJY

Passed

report date: 2024-03-29

**MOT #11** 2020-02-03 14:20

**MOT test number** 473129356725

Result \( \sqrt{Passed} \)

Advice Offside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #10** 2019-02-11 10:42

**MOT test number** 587730038128

Advice Offside Front Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))

**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #9 2019-02-09 10:31

MOT test number 622824481346

**Result** X Failed

Fail Nearside Front Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge On legal limit (5.2.3 (e))

**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Fail Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))

MOT #8 2018-02-15 08:37

MOT test number 170500330858

Result \rightarrow Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 5/14



LJ58FJY

report date: 2024-03-29

MOT #7 2017-02-22 11:19

**MOT test number** 549191762936

MOT #6 2016-02-20 11:01

**MOT test number** 769236036693

**Advice** Brake disc worn, pitted or scored, but not seriously weakened Both front (3.5.1i)

**Advice** Rear Brake pad(s) wearing thin Both (3.5.1g)

**Advice** Front Brake pad(s) wearing thin Both (3.5.1g)

MOT #5 2015-02-13 17:30

**MOT test number** 807704545053

Result \square Passed

**MOT #4** 2013-10-01 10:30

MOT test number 707264473266

**Result** ✓ Passed

MOT #3 2013-10-01 10:30

MOT test number 847114273227

Result × Failed

**Pass with rectification** Offside Stop lamp not working (1.2.1b)

Pass with rectification Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2012-08-24 13:02

**MOT test number** 256727732285

**Result** ✓ Passed

CarCheck.co.uk page 6/14



Notice

LJ58FJY report date: 2024-03-29

**MOT #1** 2011-09-15 14:53

**MOT test number** 578838351295

Result

Notice Engine malfunction display on-requires investigation

Notice Slight damage to osf wheel rim and face

3 centre row seats have child seats fitted- check seat belts as best as poss

CarCheck.co.uk page 7/14



### Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	25 January 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	49
Band	T
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-

CarCheck.co.uk page 8/14



#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	history
OWITCE	iliotoi y

For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report	
HARMAN	
*************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 11/14



#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-01
Last registration	2024-01-11
Complete history	See info



Registration #1	2008-09-01	15 mi
Registration #2	2011-09-15	24.863 mi
Registration #3	2012-08-24	33.218 mi
Registration #4	2013-10-01	42.052 mi
Registration #5	2015-02-13	50.406 mi
Registration #6	2016-02-20	58.077 mi
Registration #7	2017-02-22	66.125 mi
Registration #8	2018-02-15	78.741 mi
Registration #9	2019-02-09	88.083 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		D.777 es
Registration #17		71.777 au

More info >

CarCheck.co.uk page 13/14



### Car features

S0225	Air conditioning
S0295	
50482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1884 mm
Height	1658 mm
Length	4768 mm
Wheel base	2850 mm
Kerb weight	1974 kg
Max. allowed weight	2505 kg

# Additional information

Fuel tank capacity	70 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14