





report date: 2024-03-28

General information

Make	RENAULT
Model	CLIO EXPRESSION PLUS ENERGY TCE ECO2 S/S
Colour	Black
Year of manufacture	2013
Top speed	115 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	135 Nm at 2.500 rpm
Engine capacity	899 сс
Cylinders	3
Fuel type	Petrol
Consumption city	53.3 mpg
Consumption extra urban	76.4 mpg
Consumption combined	65.7 mpg
CO2 emission	99 g/km
CO2 label	A



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-02-04

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-09-23
MOT pass rate	54 %
MOT passed	7
Failed MOT tests	6
Total advice items	14
Total items failed	2

MOT #13		2023-08-31 09:58
MOT test	number	463947046391
Result		✓ Passed
Next expi	ry date	2024-09-23
Advice	Rear shock absorbers casings rusty	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #12		2023-08-30 08:06
MOT test i	number	510416567588
Result		X Failed
MAJOR	Windscreen wiper does not clear the windscreen effectively wiper arms dam	aged (3.4 (b) (ii))
Advice	Rear shock absorbers casings rusty	
Advice	Offside Rear Service brake binding but not excessively (1.2.1 (f))	

MOT #11	2022-09-15 12:08
MOT test number	837082681164
Result	√ Passed
MOT #10	2021-09-24 09:33
MOT test number	331889977199
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #9 2021-09-17 14:13

MOT test number 775061905491

Result X Failed

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #8 2020-09-18 11:52

MOT test number 474370383492

MOT #7 2020-09-17 11:12

MOT test number 630216467836

Result X Failed

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #6 2019-09-07 09:54

MOT test number 838151845210

Result \rightarrow Passed

MOT #5 2019-09-07 09:54

MOT test number 370333109348

Result X Failed

Pass with rectification Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

CarCheck.co.uk page 4/12



MOT #4 2018-09-03 15:42

MOT test number 402701014218

Result ✓ Passed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge outer edge worn and tread perished (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tread area perishing (5.2.3 (e))

MOT #3 2018-09-03 10:04

MOT test number 475605449415

Result X Failed

Advice Nearside Rear Tyre worn close to legal limit/worn on edge outer edge worn and tread perished (5.2.3 (e))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge tread area perishing (5.2.3 (e))

MOT #2 2016-10-22 09:19

MOT test number 290111154963

Result ✓ Passed

MOT #1 2016-10-22 09:19

MOT test number 359495029431

Result × Failed

Pass with rectification Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	23 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Vehicle Class	40
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



\sim	
Owner	nictory
CVVIICI	IIISLUIV
~	,

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	
Current registration	OK SIE
Plate since	
Current registration	OK SIE
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2013-11-29
Last registration	2023-08-31
Complete history	See info



Registration #1	2013-11-29	25 mi
Registration #2	2016-10-22	27.056 mi
Registration #3	2016-10-22	27.056 mi
Registration #4	2018-09-03	50.354 mi
Registration #5	2018-09-03	50.354 mi
Registration #6	2019-09-07	65.123 mi
Registration #7	2019-09-07	65.123 mi
Registration #8	2020-09-17	76.991 mi
Registration #9		11.777 66
Registration #10		77,777 46
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		D.777 es
Registration #15		11.777 ms

More info >

CarCheck.co.uk page 11/12



Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	88%
Children	89%
Pedestrian	66%
Safety systems	99%
Overall rating	85%
Video	see crash video



Dimensions & weight

Width	1732 mm
Height	1488 mm
Length	4062 mm
Wheel base	2589 mm
Kerb weight	980 kg
Max. allowed weight	1588 kg

Additional information

Fuel tank capacity	45 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 12/12

Number of axles 2

Engine number U128663