



PEUGEOT



report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI SW ZENITH
Colour	Silver
Year of manufacture	-
Top speed	126 mph
0 - 60 mph	10.1 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	136 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	35.7 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-08-28
Pictures	17
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history****MOT #21**

2021-06-29 09:27

MOT test number

358063078516

Result

✓ Passed

Next expiry date

2022-07-21

- Advice** Nearside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Minor** Indicator switch faulty Stalk (4.4.2 (a) (i))
- Advice** Offside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coolant pipe came off during test--bonnet stay clip broke
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Upper Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Possible steering pump leak
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #20**

2021-06-22 11:14

MOT test number

740508390954

Result**✗ Failed**

- Advice** Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Oil leak, but not excessive engine oil (8.4.1 (a) (i))
- Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- Minor** Offside Obligatory mirror slightly loose (3.3 (b) (i))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Hydraulic leak, but not excessive mist of steering fluid around steering reservoir & pump (8.4.1 (a) (i))
- Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Fail** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))
- Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Front Upper Suspension arm ball joint has slight play (5.3.4 (a) (i))
- Minor** Offside Windscreen wiper blade defective (3.4 (b) (i))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Fail** Nearside Windscreen washer provides insufficient washer liquid (3.5 (a))
- Minor** Nearside Obligatory mirror slightly loose (3.3 (b) (i))

**MOT #19**

2020-07-22 14:06

MOT test number

594990640088

Result

✓ Passed

- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Play in steering rack inner joint(s)
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))

MOT #18

2019-04-29 16:00

MOT test number

936397209770

Result

✓ Passed

- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))
- Advice** Indicator stalk faulty
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Play in steering rack inner joint(s)

**MOT #17** 2019-04-26 15:18**MOT test number** 211292582585**Result** ✗ Failed**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Fail** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Play in steering rack inner joint(s)**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Advice** Indicator stalk faulty**Advice** Front Registration plate insecure but not likely to fall off (0.1 (a))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MOT #16** 2018-04-24 15:14**MOT test number** 352926344622**Result** ✓ Passed**MOT #15** 2018-04-24 10:38**MOT test number** 590399500684**Result** ✗ Failed**Fail** Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)**Advice** Front Inner brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Nearside Rear Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

**MOT #14**

2017-04-24 10:34

MOT test number

964557861658

Result

✓ Passed

Advice Front Brake pad(s) wearing thin inner (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)**Advice** Nearside Rear Brake pad(s) wearing thin inner (3.5.1g)**MOT #13**

2017-04-21 11:35

MOT test number

244871066747

Result

✗ Failed

Advice Nearside Rear Brake pad(s) wearing thin inner (3.5.1g)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened inner (3.5.1i)**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Nearside Front Brake hose has insufficient room to move, resulting in fouling on any part (3.6.B.4a)**Advice** Front Brake pad(s) wearing thin inner (3.5.1g)**MOT #12**

2016-04-26 15:07

MOT test number

308167227662

Result

✓ Passed



MOT #11	2016-03-03 16:03
MOT test number	575182790826
Result	✗ Failed
Fail	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Front registration plate letter/figure incomplete (6.3.1c)
Fail	Offside Headlamp aim too high (1.8)
Fail	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Offside Front position lamp(s) not working (1.1.A.3b)
Fail	Nearside Front wheel bearing has excessive play (2.5.A.3c)
Fail	Nearside Headlamp aim too high (1.8)
Fail	Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)
Fail	Nearside Front position lamp(s) not working (1.1.A.3b)
Fail	Offside Stop lamp not working (1.2.1b)

MOT #10	2015-02-05 15:29
MOT test number	388066035014
Result	✓ Passed
Advice	Front registration plate deteriorated but not likely to be misread (6.3.1d)

**MOT #9** 2015-02-04 14:49**MOT test number** 416635935000**Result** ✗ Failed

- Fail** Nearside Stop lamp not working (1.2.1b)
- Fail** Nearside Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Registration plate lamp not working (1.1.C.1d)
- Fail** Nearside Rear Direction indicators not working (1.4.A.2c)
- Fail** Nearside Rear Anti-roll bar linkage has excessive play in a ball joint (2.4.G.2)
- Advice** Front registration plate deteriorated but not likely to be misread (6.3.1d)
- Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)

MOT #8 2013-11-04 16:41**MOT test number** 296298703367**Result** ✓ Passed

- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



MOT #7	2012-11-05 10:42
MOT test number	679420512394
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)

MOT #6	2012-11-02 14:45
MOT test number	559717302344
Result	✗ Failed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Rear Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Advice	Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Fail	Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

**MOT #5** 2011-10-27 16:22**MOT test number** 245120001393**Result** ✓ Passed**Notice** Rear brake discs pitted**Notice** All four brake discs worn**Notice** Offside front brake disc pitted**MOT #4** 2011-10-27 11:45**MOT test number** 916150301378**Result** ✗ Failed**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Parking brake: parking brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)**Notice** All four brake discs worn**Notice** Offside front brake disc pitted**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Notice** Rear brake discs pitted**MOT #3** 2010-01-30 12:05**MOT test number** 771170830088**Result** ✓ Passed



MOT #2

2009-02-18 17:11

MOT test number

683659349081

Result

✓ Passed

- Advice

Offside Front brake disc slightly scored (3.5.1h)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Rear brake disc slightly pitted (3.5.1h)
- Advice

Offside Front brake disc slightly pitted (3.5.1h)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #1

2009-02-18 17:11

MOT test number

273819749048

Result

✗ Failed

- Advice

Offside Front brake disc slightly scored (3.5.1h)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Rear brake disc slightly pitted (3.5.1h)
- Advice

Offside Front brake disc slightly pitted (3.5.1h)
- Pass with rectification

Nearside Headlamp not working on dipped beam (1.7.5a)
- Advice

Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice

Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	KS55EBC
Plate since	2024-03-29
Current registration	KS55EBC
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2006-02-14
Last registration	2021-06-29
Complete history	See info



Registration #1	2006-02-14	17 mi
Registration #2	2009-02-18	41.743 mi
Registration #3	2010-01-30	56.254 mi
Registration #4	2011-10-27	84.803 mi
Registration #5	2011-10-27	84.804 mi
Registration #6	2012-11-02	101.009 mi
Registration #7	2012-11-05	101.030 mi
Registration #8	2013-11-04	107.349 mi
Registration #9	2015-02-04	116.873 mi
Registration #10	2015-02-05	116.873 mi
Registration #11	2016-03-03	123.297 mi
Registration #12	2016-03-03	123.297 mi
Registration #13	2016-03-03	123.297 mi
Registration #14	2016-03-03	123.297 mi
Registration #15	2016-03-03	123.297 mi
Registration #16	2016-03-03	123.297 mi
Registration #17	2016-03-03	123.297 mi
Registration #18	2016-03-03	123.297 mi
Registration #19	2016-03-03	123.297 mi
Registration #20	2016-03-03	123.297 mi
Registration #21	2016-03-03	123.297 mi
Registration #22	2016-03-03	123.297 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1811 mm
Height	1471 mm
Length	4763 mm
Wheel base	2725 mm
Kerb weight	1568 kg
Max. allowed weight	2183 kg

Additional information

Fuel tank capacity	66 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Engine number

DYTJ4104012