



report date: 2024-03-29

General information

Make	NISSAN
Model	ALMERA S TINO
Colour	Silver
Year of manufacture	2004
Top speed	104 mph
0 - 60 mph	12.7 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	114 BHP
Max. torque	163 Nm at 4.000 rpm
Engine capacity	1.769 cc
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.5 mpg
CO2 emission	199 g/km
CO2 label	J





Internet history

Entry 1

Date	2022-06-14
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-05-14
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	30
Total items failed	13

MOT #23	2023-05-15 15:15
MOT test number	773576766206
Result	✓ Passed
Next expiry date	2024-05-14
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))
Advice	Items removed from driver's view prior to test
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #22	2023-05-15 10:13
MOT test number	292429638122
Result	✗ Failed
Advice	Items removed from driver's view prior to test
Fail	Offside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Fail	Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Minor	Nearside Windscreen wiper blade defective (3.4 (b) (i))

MOT #21	2022-06-14 10:48
MOT test number	278209832191
Result	✓ Passed

**MOT #20**

2021-06-25 12:44

MOT test number

816735043803

Result

✓ Passed

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Boot bumper damaged and open door/boot light displayed on the dash
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Various corrosion to the underside of the vehicle/suspension arms/rear coil springs/all brake ferrules/front exhaust system
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Wiper scuttle panel heavily corroded

MOT #19

2021-06-25 10:01

MOT test number

835964025259

Result

✗ Failed

- Fail** Offside Front Headlamp aim not tested (4.1.2 (b))
- Advice** Tyre slightly damaged/cracking or perishing Both rear tyres (5.2.3 (d) (ii))
- Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Wiper scuttle panel heavily corroded
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Boot bumper damaged and open door/boot light displayed on the dash
- Fail** Offside Front Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Tyre worn close to legal limit/worn on edge Both rear tyres close to limit on inner edges (5.2.3 (e))
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Various corrosion to the underside of the vehicle/suspension arms/rear coil springs/all brake ferrules/front exhaust system
- Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #18** 2020-06-29 14:45**MOT test number** 348808683998**Result** ✓ Passed**MOT #17** 2020-06-29 09:59**MOT test number** 870430138895**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**Pass with rectification** Offside Front Headlamp lens seriously defective (4.1.1 (b) (ii))**MOT #16** 2019-06-28 10:20**MOT test number** 346510608917**Result** ✓ Passed**Minor** Offside Headlamp lens slightly defective (4.1.1 (b) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #15** 2018-06-13 11:01**MOT test number** 599819082711**Result** ✓ Passed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Fluid leak, but not excessive steering rack (8.4.1 (a) (i))

**MOT #14** 2018-06-12 10:39**MOT test number** 335283618537**Result** ✗ Failed**Advice** Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Fluid leak, but not excessive steering rack (8.4.1 (a) (i))**MOT #13** 2017-06-22 10:46**MOT test number** 862897014706**Result** ✓ Passed**MOT #12** 2016-06-20 10:21**MOT test number** 534941144865**Result** ✓ Passed**Advice** Offside Front head light lense deteriorated**MOT #11** 2015-06-04 12:14**MOT test number** 699225555176**Result** ✓ Passed**MOT #10** 2015-06-04 12:14**MOT test number** 739855755170**Result** ✗ Failed**Pass with rectification** Nearside Headlamp aim too low (1.8)



MOT #9	2014-06-04 14:33
MOT test number	485945954135
Result	✓ Passed
MOT #8	2013-06-05 12:24
MOT test number	218586053435
Result	✓ Passed
MOT #7	2012-06-13 09:57
MOT test number	325705262107
Result	✓ Passed
MOT #6	2011-06-16 14:03
MOT test number	316887861109
Result	✓ Passed
MOT #5	2010-06-11 11:56
MOT test number	782372960165
Result	✓ Passed
MOT #4	2009-06-18 13:33
MOT test number	873589669104
Result	✓ Passed
MOT #3	2008-06-16 15:45
MOT test number	170298168194
Result	✓ Passed



MOT #2	2008-06-16 15:45
MOT test number	263488068166
Result	✗ Failed
Pass with rectification	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Pass with rectification	Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #1	2007-06-22 12:46
MOT test number	763543077147
Result	✓ Passed
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 July 2024

✓
MOT
Expires:
14 May 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	14 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2004-07-24
Last registration	2023-05-15
Complete history	See info



Registration #1	2004-07-24	27 mi
Registration #2	2007-06-22	12.133 mi
Registration #3	2008-06-16	16.865 mi
Registration #4	2009-06-18	20.946 mi
Registration #5	2010-06-11	23.949 mi
Registration #6	2011-06-16	26.745 mi
Registration #7	2012-06-13	27.500 mi
Registration #8	2013-06-05	29.736 mi
Registration #9	2014-06-04	30.557 mi
Registration #10	2015-06-04	31.625 mi
Registration #11	2016-06-20	32.181 mi
Registration #12	2017-06-22	34.503 mi
Registration #13	2018-06-22	35.557 mi
Registration #14	2019-06-22	36.557 mi
Registration #15	2020-06-22	37.557 mi
Registration #16	2021-06-22	38.557 mi
Registration #17	2022-06-22	39.557 mi
Registration #18	2023-06-22	40.557 mi
Registration #19	2024-06-22	41.557 mi
Registration #20	2025-06-22	42.557 mi
Registration #21	2026-06-22	43.557 mi
Registration #22	2027-06-22	44.557 mi
Registration #23	2028-06-22	45.557 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1758 mm
Height	1608 mm
Length	4264 mm
Wheel base	2535 mm
Kerb weight	1420 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	323773