



report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	BORA SE (102BHP)
Colour	Beige
Year of manufacture	-
Top speed	115 mph
0 - 60 mph	12.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	102 BHP
Max. torque	200 Nm at 3.800 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	35.3 mpg
Consumption extra urban	25.2 mpg
Consumption combined	45.6 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-07-11
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT #20	2021-10-12 17:05
MOT test number	813152870971
Result	✓ Passed
Next expiry date	2022-10-17
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Advice	Front Macpherson strut pin or bush worn but not resulting in excessive movement both side front upper (5.3.4 (a) (i))
Advice	Front Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))

MOT #19	2020-10-13 12:03
MOT test number	921507935715
Result	✓ Passed
Advice	Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))
Advice	Front Registration plate deteriorated but not likely to be misread (0.1 (b))
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))

MOT #18	2019-10-16 13:22
MOT test number	740692733007
Result	✓ Passed

MOT #17	2019-10-16 09:01
MOT test number	134971653711
Result	✗ Failed
Fail	Offside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

MOT #16	2018-09-21 11:30
MOT test number	181926091957
Result	✓ Passed

**MOT #15** 2018-09-20 10:45**MOT test number** 270282461145**Result** ✗ Failed**Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**Fail** Front Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))**Fail** Nearside Obligatory mirror missing (3.3 (a))**Advice** Offside Rear Nail in tyre**Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #14** 2017-10-12 08:20**MOT test number** 950001548749**Result** ✓ Passed**MOT #13** 2016-10-14 14:03**MOT test number** 548333268701**Result** ✓ Passed**Advice** Offside Rear Nail in tyre**MOT #12** 2016-10-14 07:36**MOT test number** 761807798193**Result** ✗ Failed**Fail** Offside Rear passenger door cannot be opened from outside the vehicle (6.2.B.1c)**Advice** Nearside Front Inner Front constant velocity joint is slightly worn (2.5.C.1b)**Advice** Offside Rear Nail in tyre

**MOT #11** 2015-10-05 13:05**MOT test number** 628481814006**Result** ✓ Passed**MOT #10** 2014-10-17 08:44**MOT test number** 255570694207**Result** ✓ Passed**MOT #9** 2013-10-16 15:14**MOT test number** 189879383279**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2012-10-18 13:58**MOT test number** 207952592209**Result** ✓ Passed**Advice** Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2011-10-11 13:13**MOT test number** 607934681219**Result** ✓ Passed**MOT #6** 2010-10-13 13:22**MOT test number** 993946380274**Result** ✓ Passed**Notice** Near side front tyre wearing outside edge...close to minimum limit.**Notice** Off side rear tyre tread edge cracking...no cords exposed.

**MOT #5** 2010-10-12 11:08**MOT test number** 180985180224**Result** ✗ Failed**Fail** Nearside Rear coil spring fractured (2.4.C.1a)**Notice** Near side front tyre wearing outside edge...close to minimum limit.**Notice** Off side rear tyre tread edge cracking...no cords exposed.**MOT #4** 2009-10-14 10:03**MOT test number** 753557689261**Result** ✓ Passed**MOT #3** 2008-10-13 09:29**MOT test number** 320107188217**Result** ✓ Passed**MOT #2** 2007-10-16 14:40**MOT test number** 320459587283**Result** ✓ Passed**MOT #1** 2006-10-16 08:45**MOT test number** 354979386444**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

Number of plates	1
Current registration	 YC52WYV
Plate since	2019-06-29
Current registration	 YC52WYV
Plate since	2019-06-29

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2002-11-07
Last registration	2021-10-12
Complete history	See info



Registration #1	2002-11-07	28 mi
Registration #2	2006-10-16	21.055 mi
Registration #3	2007-10-16	28.310 mi
Registration #4	2008-10-13	34.734 mi
Registration #5	2009-10-14	40.657 mi
Registration #6	2010-10-12	46.908 mi
Registration #7	2010-10-13	46.927 mi
Registration #8	2011-10-11	53.325 mi
Registration #9	2012-10-18	58.557 mi
Registration #10	2013-10-16	60.318 mi
Registration #11	2014-10-17	63.853 mi
Registration #12	2015-10-18	65.377 mi
Registration #13	2016-10-19	66.901 mi
Registration #14	2017-10-20	68.425 mi
Registration #15	2018-10-21	69.949 mi
Registration #16	2019-10-22	71.473 mi
Registration #17	2020-10-23	72.997 mi
Registration #18	2021-10-24	74.521 mi
Registration #19	2022-10-25	76.045 mi
Registration #20	2023-10-26	77.569 mi
Registration #21	2024-10-27	79.093 mi
Registration #22	2025-10-28	80.617 mi

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1735 mm
Height	1439 mm
Length	4149 mm
Wheel base	2511 mm
Kerb weight	1202 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2

Engine number

BFQ 014254