



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IONIQ PREMIUM SE
Colour	Black
Year of manufacture	2017
Top speed	115 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	140 BHP
Max. torque	265 Nm at 4.000 rpm
Engine capacity	1.580 cc
Cylinders	4
Fuel type	Hybrid / Electric
Consumption city	83.1 mpg
Consumption extra urban	78.5 mpg
Consumption combined	83.1 mpg
CO2 emission	79 g/km
CO2 label	A





Internet history

Entry 2

Date	2021-08-13
Pictures	40
Listing price	View report



source: [heycar.co.uk](#)

Entry 1

Date	2021-06-29
Pictures	0
Listing price	View report

source: [cargurus.co.uk](#)

**MOT history**

MOT expiry date	2024-07-17
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	10
Total items failed	6

MOT #7	2023-07-18 16:41
MOT test number	620592916804
Result	✓ Passed
Next expiry date	2024-07-17

MOT #6	2023-07-11 08:12
MOT test number	879937241718
Result	✗ Failed
Fail	Nearside Side repeater not working (4.4.1 (a) (ii))

MOT #5	2022-07-05 11:47
MOT test number	955916383337
Result	✓ Passed
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Advice	Central Front Upper Items removed from driver's view prior to test offside front
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2022-06-27 11:30**MOT test number** 203168943646**Result** ✗ Failed**Fail** Offside Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))**Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Service brake excessively binding (1.2.1 (f))**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Central Front Upper Items removed from driver's view prior to test offside front**MOT #3** 2021-06-30 15:38**MOT test number** 613806169040**Result** ✓ Passed**MOT #2** 2021-06-30 15:38**MOT test number** 606864445623**Result** ✗ Failed**Pass with rectification** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #1** 2020-08-03 09:44**MOT test number** 748608995244**Result** ✓ Passed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
17 July 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	17 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	59
Band	D
First licence fee (12 months)	£ 120,00,-
Standard rate (12 months)	£ 170,00,-
Standard rate (6 months)	£ 93,50,-
Premium rate (12 months)	£ 560,00,-
Premium rate (6 months)	£ 308,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2017-08-31
Last registration	2023-07-18
Complete history	See info



Registration #1	2017-08-31	6 mi
Registration #2	2020-08-03	30.817 mi
Registration #3	2021-06-30	38.312 mi
Registration #4	2021-06-30	38.312 mi
Registration #5	2023-07-18	38.312 mi
Registration #6		
Registration #7		
Registration #8		
Registration #9		
Registration #10		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	80%
Pedestrian	70%
Safety systems	82%
Overall rating	83%
Video	see crash video



Copyright © 2016 Euro NCAP

Dimensions & weight

Width	1820 mm
Height	1450 mm
Length	4470 mm
Wheel base	2700 mm
Kerb weight	1370 kg
Max. allowed weight	1870 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	G4LEGU299702