




report date: 2024-03-29

General information

Make	MAZDA
Model	RX-8 RX-8 PZ
Colour	Grey
Year of manufacture	2007
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	231 BHP
Max. torque	211 Nm at 5.500 rpm
Engine capacity	2.616 cc
Cylinders	2
Fuel type	Petrol
Consumption city	18.1 mpg
Consumption extra urban	32.5 mpg
Consumption combined	25.2 mpg
CO2 emission	284 g/km
CO2 label	M





Internet history

Entry 1

Date	2022-02-25
Pictures	1
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)

**MOT history**

MOT expiry date	2023-07-20
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	21
Total items failed	11

MOT #18 2022-07-21 08:26**MOT test number** 899363014995**Result** ✓ Passed**Next expiry date** 2023-07-20**Advice** Exhaust has a minor leak of exhaust gases rear joint (6.1.2 (a))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #17** 2022-07-21 08:26**MOT test number** 564038222149**Result** ✗ Failed**Advice** Exhaust has a minor leak of exhaust gases rear joint (6.1.2 (a))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Pass with rectification** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #16** 2021-07-21 09:13**MOT test number** 307206460037**Result** ✓ Passed

**MOT #15** 2021-07-16 11:34**MOT test number** 546023953696**Result** ✗ Failed**Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Rear Road wheel fixing missing (5.2.1 (a) (i))**Fail** Nearside Front Road wheel fixing missing (5.2.1 (a) (i))**MOT #14** 2019-10-21 11:34**MOT test number** 485897347179**Result** ✓ Passed**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear exhaust clamp broken**MOT #13** 2019-10-21 09:38**MOT test number** 855496941010**Result** ✗ Failed**Fail** Nearside Front Anti-roll bar linkage insecurely attached (5.3.3 (a) (i))**Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))**Advice** Rear exhaust clamp broken**Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #12** 2018-09-26 12:35**MOT test number** 738047935145**Result** ✓ Passed**Advice** Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))**Minor** Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))**Minor** Offside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))

**MOT #11** 2017-10-20 14:16**MOT test number** 924955525420**Result** ✓ Passed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

MOT #10 2017-10-20 08:47**MOT test number** 856994199134**Result** ✗ Failed

Advice Offside Front Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the ingress of dirt (2.4.G.2)

Fail Offside Rear coil spring broken (2.4.C.1a)

Fail Offside Front Shock absorber has a serious fluid leak (2.7.3)

Fail Nearside Front Anti-roll bar linkage insecure (2.4.G.1)

MOT #9 2016-10-20 10:19**MOT test number** 717471073120**Result** ✓ Passed

Advice Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Advice Offside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

MOT #8 2015-10-17 10:47**MOT test number** 577340309039**Result** ✓ Passed

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front Shock absorber has a light misting of oil (2.7.3)

Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2014-10-13 11:13**MOT test number** 718396084219**Result** ✓ Passed**MOT #6** 2014-10-13 10:52**MOT test number** 335846684258**Result** ✗ Failed**Fail** Offside Front Anti-roll bar linkage fractured (2.4.G.1)**MOT #5** 2013-09-25 09:54**MOT test number** 966308963246**Result** ✓ Passed**MOT #4** 2013-09-25 09:27**MOT test number** 856628863262**Result** ✗ Failed**Fail** Nearside Front Lower Anti-roll bar linkage cracked (2.4.G.1)**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2012-09-25 15:13**MOT test number** 586689362276**Result** ✓ Passed**MOT #2** 2011-08-06 10:30**MOT test number** 116258611261**Result** ✓ Passed**MOT #1** 2010-08-21 11:58**MOT test number** 912003330234**Result** ✓ Passed



Tax & MOT check

X

Untaxed

Tax expired:
1 February 2023

X

MOT

Expired:
20 July 2023

Tax status	Expired at 1 February 2023
Days left	454 days too late
MOT expiry date	20 July 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-09-01
Last registration	2022-07-21
Complete history	See info



Registration #1	2007-09-01	25 mi
Registration #2	2010-08-21	12.420 mi
Registration #3	2011-08-06	19.809 mi
Registration #4	2012-09-25	32.194 mi
Registration #5	2013-09-25	41.419 mi
Registration #6	2013-09-25	41.420 mi
Registration #7	2014-10-13	42.839 mi
Registration #8	2014-10-13	42.840 mi
Registration #9	2015-10-17	44.166 mi
Registration #10	2016-10-20	46.057 mi
Registration #11	2016-10-20	46.057 mi
Registration #12	2016-10-20	46.057 mi
Registration #13	2016-10-20	46.057 mi
Registration #14	2016-10-20	46.057 mi
Registration #15	2016-10-20	46.057 mi
Registration #16	2016-10-20	46.057 mi
Registration #17	2016-10-20	46.057 mi
Registration #18	2016-10-20	46.057 mi
Registration #19	2016-10-20	46.057 mi
Registration #20	2016-10-20	46.057 mi

More info >



Dimensions & weight

Width	1770 mm
Height	1340 mm
Length	4430 mm
Wheel base	2700 mm
Kerb weight	1350 kg
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B 504499