





### General information

| Make                | CITROEN               |
|---------------------|-----------------------|
| Model               | RELAY 35 L3 LUTON HDI |
| Colour              | White                 |
| Year of manufacture | 2011                  |
| Gearbox             | 6 speed Manual        |

# Engine & fuel consumption

| Power           | 120 BHP  | 0 < 101 A     |
|-----------------|----------|---------------|
| Engine capacity | 2.198 cc | 101 - 120 B   |
| linders         | 4        | 121 - 140 E   |
| el type         | Diesel   | 141 - 165 F G |
|                 |          | 166 - 185     |

225+





# Internet history

Entry 1

Date Pictures 2021-08-26

30

Listing price

View report



source: cargurus.co.uk



### MOT history

| MOT expiry date    | 2024-09-20 |
|--------------------|------------|
| MOT pass rate      | 67 %       |
| MOT passed         | 10         |
| Failed MOT tests   | 5          |
| Total advice items | 20         |
| Total items failed | 14         |

| MOT #15          |   | 2023-09-19 10:46 |
|------------------|---|------------------|
| MOT test         | number  | 247249915171     |
| Result           |   | 🗸 Passed         |
| Next expi        | ry date   | 2024-09-20       |
| Advice<br>Advice | Brake pipe corroded, covered in grease or other material N/S/R & O/S/R (1.1.11 ( $\sigma$ Oil leak, but not excessive (8.4.1 (a) (i)) | 5))              |
| Advice           | Under the vehicle muddy   |                  |



| <b>PO61</b>  | YBX        |
|--------------|------------|
| report date: | 2024-03-29 |

| <b>40T #14</b> 2023-09-13  | 3 11:53            |
|--|--------------------|
| <b>10T test number</b> 6263438   | 829173             |
| Result ×   | <b>&lt;</b> Failed |
| Advice Brake pipe corroded, covered in grease or other material N/S/R & O/S/R (1.1.11 (c))                 |                    |
| Fail Windscreen washer not working (3.5 (a))   |                    |
| Advice Under the vehicle muddy   |                    |
| <b>Fail</b> Registration plate lamp does not illuminate simultaneously with the position lamps (4.7.2 (a)) |                    |
| Advice Oil leak, but not excessive (8.4.1 (a) (i))   |                    |
| <b>Fail</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))                  |                    |
| FailParking brake lever inoperative (1.1.6 (d))  |                    |
| <b>Fail</b> Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))                             |                    |
| Fail Road wheel fixing missing (5.2.1 (a) (i))   |                    |

| MOT #13  | 2022-09-21 13:31                 |
|--|----------------------------------|
| MOT test number  | 957216834522                     |
| Result   | ✓ Passed                         |
| AdviceParking brake efficiency only just met. It would appear that the braking systeadjustment or repair. (1.4.2 (a) (i))MinorParking brake lever pivot obviously worn (1.1.6 (b) (i)) | em requires                      |
| MOT #12  |                                  |
|  | 2021-08-18 14:59                 |
| MOT test number  | 2021-08-18 14:59<br>910314557513 |
|  |                                  |



| MOT #11   | 2021-08-04 11:04 |
|---|------------------|
| MOT test number   | 981473864950     |
| Result  | 🗙 Failed         |
| <b>Fail</b> Parking brake efficiency below requirements (1.4.2 (a) (i))   |                  |
| Fail   Offside Rear Valve stem seriously damaged (5.2.3 (j))  |                  |
| Advice Rear Both Rear Suspension Leaf Springs Weakened - Limited Travel - Bump St   | ops Touching     |
| Fail Offside Rear Parking brake inoperative on one side (1.4.1 (a))   |                  |
| Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps of (4.7.1 (b) (i))                                       | or light sources |
| Advice Front Anti-roll bar linkage pin or bush worn but not resulting in excessive move Drop Link Lower Bushes Split/Perished (5.3.4 (a) (i)) | ement Both Front |
| Advice Nearside Rear Nail in tyre   |                  |

| MOT #10         | 2020-03-13 16:09 |
|-----------------|------------------|
| MOT test number | 859812997332     |
| Result          | ✓ Passed         |

| МОТ #9   | 2020-03-13 12:18 |
|--|------------------|
| MOT test number  | 705124694781     |
| Result   | × Failed         |
| FailParking brake efficiency below requirements (1.4.2 (a) (i))FailExhaust emissions exceed manufacturer's specified limit (8.2.2.2 (a)) |                  |

| MOT #8          | 2019-01-23 16:51 |
|-----------------|------------------|
| MOT test number | 555072946744     |
| Result          | ✓ Passed         |

**PO61YBX** 

report date: 2024-03-29



PO61YBX report date: 2024-03-29

| MOT #7  | 2019-01-22 13:31 |
|---|------------------|
| MOT test number   | 521145554622     |
| Result  | 🗙 Failed         |
| Fail   Nearside Rear Service brake excessively binding (1.2.1 (f))                        |                  |
| <b>Fail</b> Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii)) |                  |

| МОТ #6  | 2018-01-22 15:03 |
|---|------------------|
| MOT test number   | 696223234148     |
| Result  | ✓ Passed         |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |                  |

| MOT #5  |   | 2018-01-22 15:03 |
|---|---|------------------|
| MOT test number   |   | 130141899222     |
| Result  |   | × Failed         |
| Pass with rectification   | Nearside Registration plate lamp not working (1.1.C.1d) |                  |
| Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i) |   |                  |

| MOT #4                                   | 2017-01-27 13:04 |
|--|------------------|
| MOT test number                          | 166467339722     |
| Result                                   | ✓ Passed         |
| Advice Nearside door mirror cover broken |                  |
| MOT #3                                   | 2016-09-20 13:45 |
| MOT test number                          | 197679874655     |

| MOT test humber  | 197079874055 |
|--|--------------|
| Result   | Passed       |
| Advice Rear Brake pad(s) wearing thin both sides near limit (3.5.1g) |              |





| MOT #2   |   | 2015-08-25 10:41 |
|----------|---|------------------|
| MOT test | number  | 588124649315     |
| Result   |   | ✓ Passed         |
| Advice   | Offside Rear Brake pad(s) wearing thin brake pad worn (3.5.1g)  |                  |
| Advice   | Nearside Rear Brake pad(s) wearing thin brake pad worn (3.5.1g) |                  |

| MOT #1          | 2014-09-24 10:45 |
|-----------------|------------------|
| MOT test number | 339367364419     |
| Result          | ✓ Passed         |



Tax & MOT check







#### Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 |          |              |
|----------|----------|--------------|
| Date     |          |              |
| Category |          | Lawer        |
| Туре     | (******* |              |
| Damage 2 |          | AMPLE        |
| Damage 2 |          | E CONTRACTOR |
| Date     |          |              |
| Category |          | AMP          |
| Туре     |          |              |

#### Extra CITROEN salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





### Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

| and the second |             |
|---|-------------|
| ************  |             |
| ********  |             |
| *******   |             |
| **********  |             |
| ********  |             |
|   | More info > |
| Plate changes   |             |
| See in this check if this CITROEN had different number plates.  |             |
| Number of plates  | ,           |
| Carrent registration  |             |
| Plate since   |             |
| Current registration  |             |
| Plate since   |             |
|   |             |





#### Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this CITROEN is financed.


| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
| Contact info      |  |



PO61YBX report date: 2024-03-29

## Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 17         |
| First mileage registration | 2011-09-19 |
| Last registration          | 2023-09-19 |
| Complete history           | See info   |



| Registration #1  | 2011-09-19 | 29 mi      |
|------------------|------------|------------|
| Registration #2  | 2014-09-24 | 49.417 mi  |
| Registration #3  | 2015-08-25 | 62.397 mi  |
| Registration #4  | 2016-09-20 | 79.548 mi  |
| Registration #5  | 2017-01-27 | 81.120 mi  |
| Registration #6  | 2018-01-22 | 85.909 mi  |
| Registration #7  | 2018-01-22 | 85.909 mi  |
| Registration #8  | 2019-01-22 | 90.319 mi  |
| Registration #9  | 2019-01-23 | 90.319 mi  |
| Registration #10 |            | 11.777 esi |
| Registration #11 |            | 11.777 mi  |
| Registration #12 |            | 11.777 esi |
| Registration #13 |            | 11.777 mi  |
| Registration #14 |            | 11.777 esi |
| Registration #15 |            | 11.777 mi  |
| Registration #16 |            | 11.777 esi |
| Registration #17 |            | 11.777 mi  |
|                  |            |            |



### Additional information

| Fuel delivery   | Direct Injection |
|-----------------|------------------|
| Number of doors | 4                |
| Number of seats | 3                |
| Engine number   | TRJ70504727      |