



RE590KV

report date: 2024-03-29

General information

Make	FIAT
Model	MULTIPLA MULTIJET ELEGANZA
Colour	Black
Year of manufacture	2009
Top speed	111 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	210 Nm at 3.000 rpm
Engine capacity	1.910 cc
Cylinders	4
Fuel type	Diesel
Consumption extra urban	54.3 mpg
Consumption combined	45.6 mpg
CO2 emission	164 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-07-21
Pictures	0
Listing price	View report

source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	55 %
MOT passed	12
Failed MOT tests	10
Total advice items	24
Total items failed	19

MOT #22 2024-01-16 13:48

MOT test number 387865031694

Result ✓ Passed

Next expiry date 2025-01-16

- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge wearing heavily on edges and cracking (5.2.3 (e))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing cracking (5.2.3 (d) (ii))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge wearing heavily on edges and cracking (5.2.3 (e))

MOT #21 2023-01-17 11:45

MOT test number 117051191604

Result ✓ Passed

MOT #20 2023-01-13 09:20

MOT test number 391936585160

Result ✗ Failed

- Advice** Offside Rear brake inspection cover missing
- Fail** Rear Registration plate lamp inoperative in the case of a single lamp or all lamps both lamps out (4.7.1 (b) (ii))
- Fail** Nearside Rear Position lamp adversely affected by the operation of another lamp flashes with indicator (4.2.3 (c))
- Advice** Front Exhaust has a minor leak of exhaust gases flexi joint blowing (6.1.2 (a))

**MOT #19** 2022-10-22 10:59**MOT test number** 170562877250**Result** ✗ Failed**Minor** Offside Front Position lamp light intensity obviously reduced (4.2.3 (a) (i))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Exhaust has a minor leak of exhaust gases Flexi (6.1.2 (a))**MOT #18** 2021-11-09 13:51**MOT test number** 954205573729**Result** ✓ Passed**MOT #17** 2021-11-08 12:57**MOT test number** 732112012548**Result** ✗ Failed**Fail** Offside Rear Position lamp not working (4.2.1 (a) (ii))**Fail** Nearside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))**Fail** Horn sound not in accordance with requirements (7.7 (c))**Fail** Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))**MOT #16** 2021-01-06 14:00**MOT test number** 116583113306**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))

**MOT #15** 2021-01-05 10:21**MOT test number** 811454633678**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))**Fail** Nearside Stop lamp(s) not working (4.3.1 (a) (ii))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge low on edges (5.2.3 (e))**Fail** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))**MOT #14** 2020-01-04 11:45**MOT test number** 171068317453**Result** ✓ Passed**MOT #13** 2020-01-04 11:45**MOT test number** 146883904591**Result** ✗ Failed**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #12** 2018-12-08 12:29**MOT test number** 638736876181**Result** ✓ Passed

**MOT #11** 2017-12-29 11:07**MOT test number** 768409175724**Result** ✓ Passed**Advice** Nearside front brake fluctuating, but not excessively (3.7.B.3)**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement inner front bush (2.4.G.2)**Advice** Offside Rear brake slightly binding**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement inner front bush (2.4.G.2)**MOT #10** 2017-01-09 11:18**MOT test number** 627073171950**Result** ✓ Passed**MOT #9** 2017-01-09 09:44**MOT test number** 795330222858**Result** ✗ Failed**Pass with rectification** Offside Headlamp aim too high (1.8)**Fail** Offside Stop lamp not working (1.2.1b)**MOT #8** 2015-12-23 11:05**MOT test number** 289627277736**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin offside and nearside (3.5.1g)

**MOT #7** 2015-12-22 16:51**MOT test number** 744412208415**Result** ✗ Failed**Fail** Nearside Front Tyre has ply or cords exposed (4.1.D.1b)**Advice** Front Brake pad(s) wearing thin offside and nearside (3.5.1g)**Fail** Offside Front Tyre has ply or cords exposed (4.1.D.1b)**MOT #6** 2014-12-30 11:51**MOT test number** 419184064421**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5** 2014-12-30 11:51**MOT test number** 706244164363**Result** ✗ Failed**Pass with rectification** Registration plate lamp not working (1.1.C.1d)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #4** 2013-12-23 09:59**MOT test number** 827857553330**Result** ✓ Passed**MOT #3** 2013-12-21 11:53**MOT test number** 155775553306**Result** ✗ Failed**Fail** Stop lamp remains on when the brakes are released (1.2.1e)



MOT #2	2012-12-19 15:11
MOT test number	806034452327
Result	✓ Passed

MOT #1	2012-12-14 12:14
MOT test number	418299142356
Result	✗ Failed
<div><div>Advice</div>Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Fail</div>Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div> <div><div>Advice</div>Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><div>Fail</div>Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)</div>	



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
16 January 2025

Tax status	Valid until 1 January
Days left	246
MOT expiry date	16 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	RE59OKV
Plate since	2024-03-29
Current registration	RE59OKV
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2009-12-31
Last registration	2024-01-16
Complete history	See info



Registration #1	2009-12-31	20 mi
Registration #2	2012-12-14	25.631 mi
Registration #3	2012-12-19	25.837 mi
Registration #4	2013-12-21	37.006 mi
Registration #5	2013-12-23	37.055 mi
Registration #6	2014-12-30	48.589 mi
Registration #7	2015-12-22	59.314 mi
Registration #8	2015-12-23	59.310 mi
Registration #9	2017-01-09	71.990 mi
Registration #10	2017-01-09	71.993 mi
Registration #11	2017-12-29	78.776 mi
Registration #12	2018-12-08	84.926 mi
Registration #13	2019-01-01	85.000 mi
Registration #14	2019-01-01	85.000 mi
Registration #15	2019-01-01	85.000 mi
Registration #16	2019-01-01	85.000 mi
Registration #17	2019-01-01	85.000 mi
Registration #18	2019-01-01	85.000 mi
Registration #19	2019-01-01	85.000 mi
Registration #20	2019-01-01	85.000 mi
Registration #21	2019-01-01	85.000 mi
Registration #22	2019-01-01	85.000 mi
Registration #23	2019-01-01	85.000 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

★★★★☆

Video

[see crash video](#)



Dimensions & weight

Width	1871 mm
Height	1695 mm
Length	4089 mm
Wheel base	2666 mm
Kerb weight	1370 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	63 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	6

Number of axles	2
Engine number	6340167