



PEUGEOT

LRIIJXK

report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI CC ALLURE
Colour	Silver
Year of manufacture	2011
Top speed	126 mph
0 - 60 mph	9.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	163 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	37.7 mpg
Consumption extra urban	60.1 mpg
Consumption combined	49.6 mpg
CO2 emission	149 g/km
CO2 label	F






Internet history

Entry 1

Date	2021-08-13
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2024-11-04
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	29
Total items failed	3

MOT #14 2023-11-03 13:08

MOT test number 831737129764

Result ✓ Passed

Next expiry date 2024-11-04

Advice Rear Tyre slightly damaged/cracking or perishing both rears (5.2.3 (d) (ii))

Advice Oil leak, but not excessive (8.4.1 (a) (i))

MOT #13 2022-11-01 13:45

MOT test number 103933981256

Result ✓ Passed

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #12 2022-10-31 12:04

MOT test number 856896351984

Result ✗ Failed

Fail Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #11 2021-11-05 14:31

MOT test number 507066535766

Result ✓ Passed

**MOT #10**

2021-11-05 11:47

MOT test number

271910798712

Result**✗ Failed****Fail**

Offside Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

MOT #9

2021-01-27 09:32

MOT test number

811818445190

Result**✓ Passed****Advice**

Nearside Front Direction indicator slightly discoloured (4.4.3 (a))

Advice

Under floor covers are fitted, preventing inspection of components

Advice

Items removed from driver's view prior to test

Advice

Rear Tyre slightly damaged/cracking or perishing perished on shoulders 205/60/16 (5.2.3 (d) (ii))

MOT #8

2020-02-10 11:35

MOT test number

574179775064

Result**✓ Passed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing outer side wall (5.2.3 (d) (ii))

MOT #7

2020-02-10 11:35

MOT test number

928697505968

Result**✗ Failed****Advice**

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Nearside Front Tyre slightly damaged/cracking or perishing outer side wall (5.2.3 (d) (ii))

Pass with rectification

Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))

**MOT #6**

2019-02-11 10:57

MOT test number

708377138389

Result

✓ Passed

Minor

Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Advice

Plastic under floor covers are fitted preventing inspection of components

Advice

Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall damage 205/60/16 (5.2.3 (d) (ii))

Advice

Oil leak, but not excessive (8.4.1 (a) (i))

MOT #5

2018-02-19 12:27

MOT test number

217459661661

Result

✓ Passed

Advice

Engine cover and undertrays fitted

Advice

Front brake pads approx 70 per cent worn uneven wear between nsf and osf

MOT #4

2017-02-21 09:40

MOT test number

150473491473

Result

✓ Passed

Advice

Nearside Rear Tyre worn close to the legal limit 205/60/16 (4.1.E.1)

Advice

Under floor covers are fitted

Advice

Oil leak

Advice

Offside Rear Tyre worn close to the legal limit perished in tread 205/60/16 (4.1.E.1)

Advice

Engine undertray is missing

MOT #3

2016-02-15 11:05

MOT test number

397700808141

Result

✓ Passed

Advice

Nearside rear tyre wearing on edges



MOT #2	2015-02-23 13:18
MOT test number	187794055040
Result	✓ Passed
Notice	Osf tyre worn outer edges
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
Notice	Front and rear brake discs corroded inner faces
Notice	Under-trays fitted obscuring some underside components
Notice	Engine covers fitted obscuring some components in the engine bay

MOT #1	2014-02-27 10:01
MOT test number	498378554023
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
4 November 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	4 November 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	F
Single payment (12 months)	£ 200,00,-
Single six month payment	£ 110,00,-
Total payable by 12 monthly instalments	£ 210,00,-



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	

Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	LR11JXK
Plate since	2024-03-29
Current registration	LR11JXK
Plate since	2024-03-29

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-03-08
Last registration	2023-11-03
Complete history	See info



Registration #1	2011-03-08	9 mi
Registration #2	2014-02-27	55.612 mi
Registration #3	2015-02-23	63.649 mi
Registration #4	2016-02-15	68.188 mi
Registration #5	2017-02-21	72.293 mi
Registration #6	2018-02-19	75.948 mi
Registration #7	2019-02-11	77.780 mi
Registration #8	2020-02-10	79.537 mi
Registration #9	2020-02-10	79.537 mi
Registration #10	2020-02-10	79.537 mi
Registration #11	2020-02-10	79.537 mi
Registration #12	2020-02-10	79.537 mi
Registration #13	2020-02-10	79.537 mi
Registration #14	2020-02-10	79.537 mi
Registration #15	2020-02-10	79.537 mi
Registration #16	2020-02-10	79.537 mi

More info >



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	82%
Children	81%
Pedestrian	53%
Safety systems	83%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1817 mm
Height	1426 mm
Length	4440 mm
Wheel base	2605 mm
Kerb weight	1690 kg
Max. allowed weight	2025 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	DYYF4064143