




report date: 2024-03-29

General information

| | |
|---------------------|----------------------------|
| Make | MAZDA |
| Model | MX-5 I ROADSTER POWERSHIFT |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 121 mph |
| 0 - 60 mph | 8.9 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 158 BHP |
| Max. torque | 188 Nm at 5.000 rpm |
| Engine capacity | 1.999 cc |
| Cylinders | 4 |
| Fuel type | Petrol |
| Consumption city | 25.9 mpg |
| Consumption extra urban | 46.3 mpg |
| Consumption combined | 35.8 mpg |
| CO2 emission | 188 g/km |
| CO2 label | J |





Internet history

Entry 2

| | |
|---------------|-----------------------------|
| Date | 2022-05-06 |
| Pictures | 21 |
| Listing price | View report |



source: cargurus.co.uk

Entry 1

| | |
|---------------|-----------------------------|
| Date | 2021-06-18 |
| Pictures | 4 |
| Listing price | View report |



source: autotrader.co.uk



MOT history

| | |
|--------------------|------------|
| MOT expiry date | 2024-07-24 |
| MOT pass rate | 71 % |
| MOT passed | 12 |
| Failed MOT tests | 5 |
| Total advice items | 6 |
| Total items failed | 10 |

| | |
|------------------|------------------|
| MOT #17 | 2023-07-18 10:59 |
| MOT test number | 864126721272 |
| Result | ✓ Passed |
| Next expiry date | 2024-07-24 |

| | |
|-----------------|------------------|
| MOT #16 | 2022-07-25 15:33 |
| MOT test number | 568668150364 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #15 | 2021-11-25 12:56 |
| MOT test number | 948195624671 |
| Result | ✓ Passed |

| | |
|-----------------|------------------|
| MOT #14 | 2021-02-19 11:31 |
| MOT test number | 215529283599 |
| Result | ✓ Passed |

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))



MOT #13 2021-02-19 11:31

MOT test number 477166710537

Result ✗ Failed

Pass with rectification Offside Stop lamp(s) not working (4.3.1 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12 2020-03-25 11:55

MOT test number 867783420319

Result ✓ Passed

MOT #11 2020-03-24 11:16

MOT test number 254709427035

Result ✗ Failed

Fail Offside Front Service brake excessively binding (1.2.1 (f))

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #10 2019-03-25 09:57

MOT test number 538131972805

Result ✓ Passed

MOT #9 2018-03-09 12:29

MOT test number 311870511461

Result ✓ Passed



| | |
|------------------------|---|
| MOT #8 | 2018-03-09 08:38 |
| MOT test number | 908886536661 |
| Result | ✗ Failed |
| Fail | Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |
| Fail | Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1) |

| | |
|------------------------|------------------|
| MOT #7 | 2017-03-08 15:54 |
| MOT test number | 994611235183 |
| Result | ✓ Passed |

| | |
|------------------------|---|
| MOT #6 | 2017-03-03 09:30 |
| MOT test number | 442107819451 |
| Result | ✗ Failed |
| Fail | Front Brake pad(s) less than 1.5 mm thick (3.5.1g) |
| Advice | Rear Brake pad(s) wearing thin (3.5.1g) |
| Fail | Front brake disc in such a condition that it is seriously weakened (3.5.1i) |
| Fail | Brake performance not tested (3.7.A.1) |

| | |
|------------------------|------------------|
| MOT #5 | 2016-03-04 09:12 |
| MOT test number | 583544018299 |
| Result | ✓ Passed |

| | |
|------------------------|------------------|
| MOT #4 | 2015-03-18 15:24 |
| MOT test number | 946957175009 |
| Result | ✓ Passed |



MOT #3 2015-03-18 15:24

MOT test number 298037375031

Result ✗ Failed

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2 2014-04-15 14:34

MOT test number 239105204170

Result ✓ Passed

MOT #1 2013-04-22 16:26

MOT test number 337152913110

Result ✓ Passed



Tax & MOT check

✓
Taxed

Tax due:
1 April 2025

✓
MOT

Expires:
24 July 2024

| | |
|-------------------------|---------------------------------|
| Tax status | Valid until 1 April |
| Days left | 337 |
| MOT expiry date | 24 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| | |
|--|------------|
| Vehicle class | 48 |
| Band | J |
| Single payment (12 months) | £ 365,00,- |
| Single six month payment | £ 200,75,- |
| Total payable by 12 monthly instalments | £ 383,25,- |




Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.


Damage 1

| | |
|-----------------|--|
| Date | |
| Category | |
| Type | |



Damage 2

| | |
|-----------------|--|
| Date | |
| Category | |
| Type | |



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|------------------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

[More info >](#)



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | | |
|-------|-------|-----|
| Owner | Start | End |

More info >

Plate changes

See in this check if this MAZDA had different number plates.

| | |
|----------------------|--------------|
| Number of plates | 1 |
| Current registration | XXXXX |
| Plate since | 2024-03-29 |
| Current registration | XXXXX |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled. If not, and you buy this MAZDA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this MAZDA is financed.


| | |
|--------------------------|----------|
| Finance company | REDACTED |
| Date of agreement | REDACTED |
| Agreement type | REDACTED |
| Agreement term | REDACTED |
| Agreement number | REDACTED |
| Contact info | REDACTED |

More info >



Mileage check

| | |
|-----------------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 19 |
| First mileage registration | 2010-05-01 |
| Last registration | 2023-07-18 |
| Complete history | See info |



| | | |
|-------------------------|------------|-----------|
| Registration #1 | 2010-05-01 | 24 mi |
| Registration #2 | 2013-04-22 | 16.902 mi |
| Registration #3 | 2014-04-15 | 21.807 mi |
| Registration #4 | 2015-03-18 | 26.124 mi |
| Registration #5 | 2016-03-04 | 34.521 mi |
| Registration #6 | 2017-03-03 | 41.207 mi |
| Registration #7 | 2017-03-08 | 41.375 mi |
| Registration #8 | 2018-03-09 | 52.385 mi |
| Registration #9 | 2018-03-09 | 52.385 mi |
| Registration #10 | 2019-03-25 | 55.207 mi |
| Registration #11 | 2019-03-25 | 55.207 mi |
| Registration #12 | 2019-03-25 | 55.207 mi |
| Registration #13 | 2019-03-25 | 55.207 mi |
| Registration #14 | 2019-03-25 | 55.207 mi |
| Registration #15 | 2019-03-25 | 55.207 mi |
| Registration #16 | 2019-03-25 | 55.207 mi |
| Registration #17 | 2019-03-25 | 55.207 mi |
| Registration #18 | 2019-03-25 | 55.207 mi |
| Registration #19 | 2019-03-25 | 55.207 mi |

[More info >](#)



Safety ratings

NCAP rating ★★★★☆
Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1720 mm |
| Height | 1245 mm |
| Length | 4020 mm |
| Wheel base | 2330 mm |
| Kerb weight | 1186 kg |
| Max. allowed weight | 1375 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 2 |
| Number of seats | 2 |
| Number of axles | 2 |
| Engine number | LF 10916663 |