





report date: 2024-03-29

General information

Make	ТОУОТА
Model	VERSO VALVEMATIC TR
Colour	Red
Year of manufacture	2012
Top speed	115 mph
0 - 60 mph	11.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	132 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	32.8 mpg
Consumption extra urban	49.6 mpg
Consumption combined	42.2 mpg
CO2 emission	158 g/km
CO2 label	G



CarCheck.co.uk page 1/14



report date: 2024-03-29


Internet history

Entry 1

Date 2022-06-05

Pictures 31

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/14



report date: 2024-03-29

MOT history

MOT expiry date	2024-08-12
MOT pass rate	60 %
MOT passed	9
Failed MOT tests	6
Total advice items	30
Total items failed	10

MOT #15	2023-07-31 14:58
MOT test number	191029867733
Result	√ Passed
Next expiry date	2024-08-12
Advice Engine cover fitted	

MOT #14	2023-07-31 14:58
MOT test number	478576041268
Result	▼ Failed
Advice Engine cover fitt	red
Pass with rectification	Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #13	2022-08-03 16:13
MOT test number	294817737518
Result	✓ Passed

CarCheck.co.uk page 3/14



report date: 2024-03-29

MOT #12 2022-07-25 06:15 642352940993 **MOT** test number Result × Failed **Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Nearside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) Fail Nearside Front Headlamp not working on dipped beam (4.1.1 (a) (ii)) **Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i)) Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii)) **Advice** Advice Offside Rear Brake disc worn, but not excessively (1.1.14 (a) (i)) **Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #11	2021-08-05 11:40
MOT test number	779412376910
Result	✓ Passed
MOT #10	2021-08-05 11:21
MOT test number	963845250602
Result	X Failed
Fail Nearside Headlamp not working on dipped beam (4.1.1 (a) (ii))	

CarCheck.co.uk page 4/14



report date: 2024-03-29

MOT #9 2020-08-13 16:17

MOT test number 693516893297

Result ✓ Passed

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear

most bush (5.3.4 (a) (i))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most

bush (5.3.4 (a) (i))

MOT #8 2020-08-13 10:48

MOT test number 906208128022

Result × Failed

Fail Offside Front Position lamp not working (4.2.1 (a) (ii))

Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))

Advice Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Minor Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

Fail Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Fail Offside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Front Suspension arm pin or bush worn but not resulting in excessive movement rear most bush (5.3.4 (a) (i))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 5/14



report date: 2024-03-29

MOT #7	2019-09-04 09:24
MOT test number	712801155594
Result	✓ Passed
MOT #6	2019-09-03 11:20
MOT test number	142890991384
Result	× Failed
Fail Offside Front Tyre has ply or cords damaged (5.2.3 (d) (ii))	
Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))	
MOT #5	2018-09-13 09:08
MOT test number	765088228572
Result	✓ Passed
MOT #4	2017-09-06 08:06
MOT test number	278742021641
Result	✓ Passed
MOT #3	2017-09-01 09:17
MOT test number	254106990039

MOT #3	2017-09-01 09:17
MOT test number	254106990039
Result	X Failed
Advice Offside Front Brake pad(s) wearing thin (3.5.1g) Fail Nearside Side repeater not working (1.4.A.2c)	

CarCheck.co.uk page 6/14



report date: 2024-03-29

MOT #2 2016-08-24 15:30

MOT test number 576499330039

Advice Front brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)

Advice Offside Front Upper Anti-roll bar linkage ball joint dust cover deteriorated, but preventing the

ingress of dirt (2.4.G.2)

Advice Brake disc worn, pitted or scored, but not seriously weakened BOTH (3.5.1i)

MOT #1 2015-09-14 15:44

MOT test number 718322236251

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Brake disc worn, pitted or scored, but not seriously weakened Both Front and Rear (3.5.1i)

CarCheck.co.uk page 7/14



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 August
Days left	94
MOT expiry date	12 August 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 8/14



report date: 2024-03-29

Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



report date: 2024-03-29

Owner	history
OWITEL	HISLULY

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it	
HARMAN CO. C.	

	More info >
Plate changes	
See in this check if this TOYOTA had different number plates.	
Number of plates	,
Current registration	UK UK
Plate since	
Current registration	NK SIE
Plate since	
	More info >

CarCheck.co.uk page 11/14



report date: 2024-03-29

Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >

CarCheck.co.uk page 12/14



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2012-11-26
Last registration	2023-07-31
Complete history	See info



Registration #1	2012-11-26	17 mi
Registration #2	2015-09-14	28.330 mi
Registration #3	2016-08-24	34.178 mi
Registration #4	2017-09-01	43.300 mi
Registration #5	2017-09-06	43.396 mi
Registration #6	2018-09-13	49.892 mi
Registration #7	2019-09-03	57.629 mi
Registration #8	2019-09-04	57.629 mi
Registration #9	2020-08-13	64.303 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		9.777 es
Registration #14		11.777 es
Registration #15		9.777 es
Registration #16		0.00 44
Registration #17		11,177 ms

More info >

CarCheck.co.uk page 13/14



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	75%
Pedestrian	69%
Safety systems	86%
Overall rating	82%
Video	see crash video



Dimensions & weight

Width	1790 mm
Height	1620 mm
Length	4440 mm
Wheel base	2780 mm
Kerb weight	1505 kg
Max. allowed weight	2125 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 14/14

Engine number

1ZRU499754