



report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE SOVEREIGN
Colour	Black
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	152 BHP
Max. torque	366 Nm at 1.800 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	34.0 mpg
Consumption extra urban	60.1 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-02
Pictures	25
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](#)



## MOT history

MOT #23	2022-03-11 14:41
MOT test number	208516154695
Result	✓ Passed
Next expiry date	2023-03-10
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22	2022-03-11 14:41
MOT test number	854771171164
Result	✗ Failed
Minor	Nearside Front Anti-roll bar linkage ball joint dust cover severely deteriorated (5.3.4 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Pass with rectification	Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #21	2021-02-04 11:34
MOT test number	316112322542
Result	✓ Passed
Advice	Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge ON LEGAL LIMIT OF 1.6MM (5.2.3 (e))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Offside Front Direction indicator slightly discoloured (4.4.3 (a))
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #20** 2020-02-03 15:19**MOT test number** 744247853019**Result** ✓ Passed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- Advice** Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #19** 2020-02-03 12:03**MOT test number** 400864768458**Result** ✗ Failed

- Advice** Nearside Front Direction indicator slightly discoloured (4.4.3 (a))
- Advice** Nearside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))
- MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))
- MAJOR** Offside Rear Lower Suspension arm pin or bush excessively worn INNER BUSH (5.3.4 (a) (i))
- Advice** Offside Rear Upper Suspension arm corroded but not seriously weakened (5.3.3 (b) (i))

**MOT #18** 2019-02-06 12:25**MOT test number** 416625658520**Result** ✓ Passed**MOT #17** 2018-10-24 16:38**MOT test number** 709278549179**Result** ✓ Passed

- Advice** Suspension arm corroded but not seriously weakened nearside/offside front lower (5.3.3 (b) (i))

**MOT #16**

2018-10-23 15:17

**MOT test number**

287340331566

**Result****✗ Failed****Advice** Nearside/offside front tyre inner shoulders worn to zero/sidewalls/treads perished**DANGEROUS** Nearside Front Tyre has ply or cords exposed inner shoulder (5.2.3 (d) (ii))**Advice** Suspension arm corroded but not seriously weakened nearside/offside front lower (5.3.3 (b) (i))**Advice** Nearside/offside rear tyres worn to 3mm/perished treads**MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**MOT #15**

2017-10-14 08:19

**MOT test number**

677253500030

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit on 3mm and perishing (4.1.E.1)**Advice** Offside Rear Suspension arm has slight play in a pin/bearing from trailing arm to subframe (2.4.G.2)**Advice** Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)**Advice** Offside Rear Tyre worn close to the legal limit on 3mm and perishing (4.1.E.1)



MOT #14	2017-10-14 08:19
MOT test number	293571762347
Result	✗ Failed
Pass with rectification	Nearside Headlamp not working on dipped beam (1.7.5a)
Advice	Nearside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)
Advice	Nearside Rear Tyre worn close to the legal limit on 3mm and perishing (4.1.E.1)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Advice	Offside Rear Suspension arm has slight play in a pin/bearing from trailing arm to subframe (2.4.G.2)
Advice	Offside Front Tyre worn close to the legal limit on 3mm (4.1.E.1)
Advice	Offside Rear Tyre worn close to the legal limit on 3mm and perishing (4.1.E.1)

MOT #13	2016-10-18 08:19
MOT test number	961678726684
Result	✓ Passed
Advice	Engine management light on

MOT #12	2016-10-18 08:19
MOT test number	210723413935
Result	✗ Failed
Pass with rectification	Nearside Front position lamp(s) not working (1.1.A.3b)
Advice	Engine management light on

MOT #11	2015-10-19 13:37
MOT test number	650473145751
Result	✓ Passed
Advice	Front brake disc worn, pitted or scored, but not seriously weakened worn and corroded on inner faces (3.5.1i)
Advice	Engine light on at time of test.

**MOT #10**

2015-10-19 13:37

**MOT test number**

733636448262

**Result****✗ Failed****Pass with rectification** Offside Headlamp aim too high and too far to the right. (1.8)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened worn and corroded on inner faces (3.5.1i)**Advice** Engine light on at time of test.**MOT #9**

2014-10-24 10:03

**MOT test number**

728977594275

**Result****✓ Passed****Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**MOT #8**

2013-10-24 17:19

**MOT test number**

699197293223

**Result****✓ Passed****MOT #7**

2013-10-03 16:27

**MOT test number**

657416273290

**Result****✗ Failed****Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)

**MOT #6** 2013-04-12 08:58**MOT test number** 439682003159**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**MOT #5** 2012-10-04 14:21**MOT test number** 689748572219**Result** ✓ Passed**Notice** (alloy wheels, 225/45ZR17 tyres, minimum tread depth readings = n/s/f & o/s/f 4mm, n/s/r & o/s/r 5mm.)**Notice** N/s/f tyre cuts in outer side wall (some have been glued together).**MOT #4** 2012-03-15 14:19**MOT test number** 265585572038**Result** ✓ Passed**Notice** N/s front tyre side wall is damaged/cut (no ply/cord exposed).**Notice** N/s & o/s front inner brake pads are worn thin. n/s & o/s rear brake pads are worn thin. (we recomend new brake pads are fitted a,s,a,p).**MOT #3** 2012-03-15 14:19**MOT test number** 527915072086**Result** ✗ Failed**Notice** N/s front tyre side wall is damaged/cut (no ply/cord exposed).**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Notice** N/s & o/s front inner brake pads are worn thin. n/s & o/s rear brake pads are worn thin. (we recomend new brake pads are fitted a,s,a,p).**Pass with rectification** Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #2** 2011-03-01 15:39**MOT test number** 589400961040**Result** ✓ Passed





MOT #1	2010-03-24 13:52
MOT test number	832403780085
Result	✓ Passed



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners did this JAGUAR have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this JAGUAR had different number plates.

Number of plates	1
Current registration	<b>UK</b> <b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>UK</b> <b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled. If not, and you buy this JAGUAR then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this JAGUAR is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2007-03-29
Last registration	2022-03-11
Complete history	<a href="#">See info</a>



Registration #1	2007-03-29	11 mi
Registration #2	2010-03-24	17.863 mi
Registration #3	2011-03-01	26.478 mi
Registration #4	2012-03-15	37.488 mi
Registration #5	2012-10-04	43.307 mi
Registration #6	2013-04-12	47.057 mi
Registration #7	2013-10-03	51.931 mi
Registration #8	2013-10-24	51.938 mi
Registration #9	2014-10-24	60.476 mi
Registration #10	2015-10-19	68.092 mi
Registration #11	2015-10-19	68.092 mi
Registration #12	2016-10-18	71.145 mi
Registration #13	2016-10-18	71.145 mi
Registration #14	2016-10-18	71.145 mi
Registration #15	2016-10-18	71.145 mi
Registration #16	2016-10-18	71.145 mi
Registration #17	2016-10-18	71.145 mi
Registration #18	2016-10-18	71.145 mi
Registration #19	2016-10-18	71.145 mi
Registration #20	2016-10-18	71.145 mi
Registration #21	2016-10-18	71.145 mi
Registration #22	2016-10-18	71.145 mi
Registration #23	2016-10-18	71.145 mi
Registration #24	2016-10-18	71.145 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1502 kg
Max. allowed weight	2035 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	070911231434BG