

Ford



### General information

Make	FORD
Model	GALAXY GHIA TDCI
Colour	Silver
Year of manufacture	2009
Top speed	120 mph
0 - 60 mph	10.0 seconds
Gearbox	6 speed Manual

## Engine & fuel consumption

Power	143 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	34.5 mpg
Consumption extra urban	51.4 mpg
Consumption combined	43.5 mpg
CO2 emission	159 g/km
CO2 label	G





LRO9TLX report date: 2024-03-28

Internet history		
Entry 2		
Date	2021-08-29	
Pictures	4	
Listing price	View report	
Source: cargurus.co.uk	<section-header></section-header>	<image/>
Date	2021-08-28	
Pictures	29	
Listing price	View report	



source: autotrader.co.uk



### MOT history

MOT expiry date	2024-07-15
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	17
Total items failed	7

MOT #16	2023-07-03 10:57
MOT test number	697946752586
Result	✓ Passed
Next expiry date	2024-07-15
Advice Nearside Front Tyre worn close to legal limit/worn on edge Inner trea	ad wearing (5.2.3 (e))
Advice Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice Offside Front Tyre worn close to legal limit/worn on edge Inner tread	l wearing (5.2.3 (e))

MOT #15	2022-07-14 09:11
MOT test number	992225010677
Result	✓ Passed
Minor Nearside Rear Position lamp with a multiple lig	ht source up to 1/2 not functioning (4.2.1 (a) (i))
Advice Nearside Rear Shock absorbers has light mist	ing of oil (5.3.2 (b))



LR09TL	<b>.</b> X
report date: 2024	-03-28

MOT #14	2022-07-12 12:05
MOT test number	728846582662
Result	🗙 Failed
<b>Fail</b> Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))	
FailOffside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
<b>Fail</b> Offside Front Brake disc significantly and obviously worn (1.1.14 (a) (i))	
Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not function	ing (4.2.1 (a) (i))

MOT #13	2021-07-16 14:19
MOT test number	980911000299
Result	✓ Passed

MOT #12	2020-09-23 15:56
MOT test number	833827979729
Result	🗸 Passed
Advice Front Tyre worn close to legal limit/worn on edge both front inner edge (5.2.3 (e))	)

MOT #11	2019-03-28 14:54
MOT test number	996661265684
Result	✓ Passed

MOT #10	2018-03-20 08:50
MOT test number	583419881476
Result	✓ Passed
Advice Exhaust has a minor leak of exhaust gases (7.1.2)	





МОТ #9	2017-03-27 15:23
MOT test number	505646669511
Result	✓ Passed
MOT #8	2016-03-29 13:21
MOT test number	727236304398
Result	✓ Passed

MOT #7	2015-03-24 11:23
MOT test number	645023385053
Result	✓ Passed
Advice Front Brake pad(s) wearing thin (3.5.1g)	

MOT #6		2015-03-24 11:23
MOT test number		149243985436
Result		🗙 Failed
Advice Front Brake pad	(s) wearing thin (3.5.1g)	
Pass with rectification	Rear Stop lamp not working (1.2.1b)	

MOT #5	2014-03-18 08:27
MOT test number	486337174081
Result	✓ Passed
МОТ #4	2014-03-18 08:27
MOT test number	197917574499
Result	× Failed





MOT #3	2013-03-19 14:52
MOT test number	627928673079
Result	✓ Passed
MOT #2	2012-03-12 17:22
MOT test number	309632772021
Result	✓ Passed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

MOT #1	2012-03-12 12:19
MOT test number	295712472001
Result	🗙 Failed
Advice Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)	



Tax & MOT check

✓ Taxed Tax due: 1 September 2024	MOT Expires: 15 July 2024
Tax status	Valid until 1 September
Days left	125
MOT expiry date	15 July 2024
Full MOT history	See MOT history
Tax calculation	

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





#### Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1		
Date	F	
Category		ARME
Туре		
Damage 2		AMPLE
	E E	
Date		\$
Category	AMP	
Туре	No. Contraction of the second se	

#### Extra FORD salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





#### Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





### Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	
************	
********	
*******	
************	
********	
	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Current registration	
Plate since	





#### Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



LRO9TLX report date: 2024-03-28

# Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-03-12
Last registration	2023-07-03
Complete history	See info



Registration #1	2009-03-12	23 mi
Registration #2	2012-03-12	25.256 mi
Registration #3	2012-03-12	25.256 mi
Registration #4	2013-03-19	34.524 mi
Registration #5	2014-03-18	43.966 mi
Registration #6	2015-03-24	54.276 mi
Registration #7	2016-03-29	64.526 mi
Registration #8	2017-03-27	76.423 mi
Registration #9	2018-03-20	83.979 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 est
Registration #13		11.777 mi
Registration #14		11.777 est
Registration #15		11.777 esi
Registration #16		11.777 esi
Registration #17		11.777 mi





### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

# Safety ratings

**NCAP** rating

Video

see crash video



Dimensions & weight	
Width	1884 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1933 kg
Max. allowed weight	2505 kg
Additional information	
Fuel tank capacity	70
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	7 page 13/13

Number of axles	2
Engine number	8Y55040