



PEUGEOT



report date: 2024-03-28

General information

Make	PEUGEOT
Model	307 S COUPE CABRIOLET
Colour	Blue
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	10.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	138 BHP
Max. torque	200 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.0 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.9 mpg





LABEL UNKNOWN



Internet history

Entry 1

Date	2021-05-25
Pictures	5
Listing price	<a href="#">View report</a>



source: autotrader.co.uk

**MOT history**

<b>MOT #23</b>	2022-11-24 10:55
<b>MOT test number</b>	858261952336
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-23
<b>Advice</b>	Slight rear brake imbalance
<b>Advice</b>	Oil leak, but not excessive (8.4.1 (a) (i))
<b>Advice</b>	Play in steering rack inner joint(s) Nearside & Offside
<b>Advice</b>	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
<b>Advice</b>	Offside Rear Tyre worn close to legal limit/worn on edge Cracking on shoulder (5.2.3 (e))
<b>Advice</b>	Nearside front tyre close to legal limit
<b>Advice</b>	Service brake binding but not excessively Both rear (1.2.1 (f))
<b>Advice</b>	Offside Front Integral body structure is corroded but structural rigidity is not significantly reduced Corrosion to floor (6.1.1 (c) (i))
<b>Advice</b>	Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

<b>MOT #22</b>	2021-11-24 12:01
<b>MOT test number</b>	398071668356
<b>Result</b>	✓ Passed
<b>Advice</b>	Rear Service brake binding but not excessively (1.2.1 (f))
<b>Advice</b>	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
<b>Advice</b>	Play in n/s and o/s rack ends
<b>Advice</b>	Nearside Rear Tyre slightly damaged/cracking or perishing and worn to limit (5.2.3 (d) (ii))
<b>Minor</b>	Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))

**MOT #21**

2021-11-24 11:11

**MOT test number**

514496065945

**Result****✗ Failed**

- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Minor** Offside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing and worn to limit (5.2.3 (d) (ii))
- Fail** Fuel cap/sealing device ineffective (6.1.3 (b) (i))
- Advice** Play in n/s and o/s rack ends

**MOT #20**

2020-10-23 14:07

**MOT test number**

825176015443

**Result****✓ Passed**

- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #19**

2020-10-23 10:09

**MOT test number**

826572286512

**Result****✗ Failed**

- Fail** Nearside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Rear Service brake binding but not excessively (1.2.1 (f))
- Fail** Offside Front Tyre has ply or cords exposed (5.2.3 (d) (ii))
- Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Fail** Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #18** 2019-05-21 14:09**MOT test number** 636546150970**Result** ✓ Passed**Advice** Surface corrosion brakes/suspension of car looks like its been stood**Advice** Nearside Front Play in steering rack inner joint(s)**MOT #17** 2019-05-21 14:09**MOT test number** 148747320284**Result** ✗ Failed**Advice** Nearside Front Play in steering rack inner joint(s)**Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))**Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))**Advice** Surface corrosion brakes/suspension of car looks like its been stood**MOT #16** 2019-05-13 10:36**MOT test number** 452239051557**Result** ✗ Failed**Advice** Nearside Front Track rod end ball joint has slight play (2.1.3 (b) (i))**Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))**Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))**Advice** Offside Front Coil spring corroded (5.3.1 (b) (i))**Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))**MOT #15** 2017-09-21 10:06**MOT test number** 456577556316**Result** ✓ Passed**Advice** Nearside Play in steering rack inner joint(s)

**MOT #14**

2017-09-14 12:59

**MOT test number**

848670399945

**Result****✗ Failed****Fail** Offside Headlamp not working on dipped beam (1.7.5a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Fail** Nearside Rear position lamp(s) not working (1.1.A.3b)**Advice** Nearside Play in steering rack inner joint(s)**MOT #13**

2016-09-13 13:31

**MOT test number**

463032074957

**Result****✓ Passed****Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #12**

2016-09-09 09:27

**MOT test number**

159669721107

**Result****✗ Failed****Fail** Nearside Front Tyre has ply or cords exposed also below legal limit (4.1.D.1b)**Fail** Nearside Front Front position lamp(s) not working (1.1.A.3b)**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Track rod end ball joint has slight play (2.2.B.1f)**Fail** Nearside Rear Tyre has ply or cords exposed (4.1.D.1b)**Fail** Nearside Front Headlamp not working on dipped beam (1.7.5a)**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #11** 2015-09-17 09:14**MOT test number** 895471332169**Result** ✓ Passed**Advice** Offside Rear child seat fitted**Advice** Nearside Front Track rod end ball joint has slight play n/s/f track rod end has minor play (2.2.B.1f)**MOT #10** 2015-09-17 09:14**MOT test number** 951350854253**Result** ✗ Failed**Pass with rectification** Offside Rear Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Offside Rear child seat fitted**Pass with rectification** Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)**Advice** Nearside Front Track rod end ball joint has slight play n/s/f track rod end has minor play (2.2.B.1f)**MOT #9** 2014-09-10 14:47**MOT test number** 145743054256**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #8** 2014-09-10 11:41**MOT test number** 425993154231**Result** ✗ Failed**Fail** Supplementary Restraint System warning lamp indicates a fault (5.4.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #7** 2013-09-11 11:47**MOT test number** 468284953230**Result** ✓ Passed

**MOT #6** 2013-09-10 14:27**MOT test number** 447043053246**Result** ✗ Failed**Fail** Rear Brake lining(s) less than 1.5 mm thick (3.5.1g)**MOT #5** 2012-08-30 17:08**MOT test number** 379093142293**Result** ✓ Passed**MOT #4** 2012-08-29 11:11**MOT test number** 398372742443**Result** ✗ Failed**Fail** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Front Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Offside Track rod end ball joint has slight play (2.2.B.1f)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Fail** Nearside Track rod end ball joint has excessive play (2.2.B.1f)**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2011-05-31 17:13**MOT test number** 737731051107**Result** ✓ Passed**MOT #2** 2010-03-11 17:12**MOT test number** 371420170076**Result** ✓ Passed





MOT #12009-06-26 11:56

MOT test number860397679179

Result

✓ Passed

- Advice

Nearside Track rod end ball joint has slight play (2.2.B.1f)
- Advice

Rear brake disc slightly scored (3.5.1h)
- Advice

Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice

Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice

Nearside Rear Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owners did this PEUGEOT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this PEUGEOT had different number plates.

Number of plates	1
Current registration	<b>SX06AHP</b>
Plate since	2024-03-28
Current registration	<b>SX06AHP</b>
Plate since	2024-03-28

More info >



Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this PEUGEOT is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2006-06-26
Last registration	2022-11-24
Complete history	<a href="#">See info</a>



Registration #1	2006-06-26	14 mi
Registration #2	2009-06-26	17.264 mi
Registration #3	2010-03-11	18.683 mi
Registration #4	2011-05-31	35.514 mi
Registration #5	2012-08-29	48.906 mi
Registration #6	2012-08-30	48.909 mi
Registration #7	2013-09-10	55.955 mi
Registration #8	2013-09-11	55.955 mi
Registration #9	2014-09-10	60.021 mi
Registration #10	2014-09-10	60.024 mi
Registration #11	2015-09-17	73.340 mi
Registration #12	2015-09-17	73.340 mi
Registration #13	2016-09-09	84.049 mi
Registration #14	2016-09-09	84.049 mi
Registration #15	2016-09-09	84.049 mi
Registration #16	2016-09-09	84.049 mi
Registration #17	2016-09-09	84.049 mi
Registration #18	2016-09-09	84.049 mi
Registration #19	2016-09-09	84.049 mi
Registration #20	2016-09-09	84.049 mi
Registration #21	2016-09-09	84.049 mi
Registration #22	2016-09-09	84.049 mi
Registration #23	2016-09-09	84.049 mi
Registration #24	2016-09-09	84.049 mi
Registration #25	2016-09-09	84.049 mi



Car features

The PEUGEOT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete PEUGEOT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1757 mm
Height	1440 mm
Length	4357 mm
Wheel base	2605 mm
Kerb weight	1543 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

<b>Number of axles</b>	2
<b>Engine number</b>	LH4P1445371