





report date: 2024-03-28

General information

| Make | KIA |
|---------------------|-------------------|
| Model | NIRO 2 |
| Colour | Grey |
| Year of manufacture | 2017 |
| Top speed | 101 mph |
| 0 - 60 mph | 11.1 seconds |
| Gearbox | 6 speed automatic |

Engine & fuel consumption

| Power | 140 BHP |
|-------------------------|---------------------|
| Max. torque | 265 Nm at 4.000 rpm |
| Engine capacity | 1.580 cc |
| Cylinders | 4 |
| Fuel type | Hybrid / Electric |
| Consumption city | 74.3 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 74.3 mpg |
| CO2 emission | 88 g/km |
| CO2 label | Α |



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1


Date 2021-02-01

Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-09-29 |
|--------------------|------------|
| MOT pass rate | 100 % |
| MOT passed | 4 |
| Failed MOT tests | 0 |
| Total advice items | 9 |
| Total items failed | 0 |

| MOT #4 | 2023-08-31 13:27 |
|--|---------------------------|
| MOT test number | 688388223994 |
| Result | ✓ Passed |
| Next expiry date | 2024-09-29 |
| Advice Rear Tyre slightly damaged/cracking or perishing both rear tires pe stepping badly (5.2.3 (d) (ii)) | rished , also inner edges |

| MOT #3 | 20 | 22-09-30 13:56 |
|----------|--|-----------------|
| MOT test | number | 661724857112 |
| Result | | ✓ Passed |
| Advice | Nearside Front Tyre worn close to legal limit/worn on edge cracking, 205/60/16 (5.2. | 3 (e)) |
| Advice | Rear Tyre slightly damaged/cracking or perishing both sides, cracking round side wa | lls, (5.2.3 (d) |
| Advice | Offside Front Tyre worn close to legal limit/worn on edge cracking, (5.2.3 (e)) | |
| Advice | Front factory fitted engine trims/covers, | |

CarCheck.co.uk page 3/11



report date: 2024-03-28

| MOT #2 | 2021-09-08 10:00 |
|--------------------------|---|
| MOT test | number 104404284407 |
| Result | ✓ Passed |
| Advice | Nearside Rear Outer Tyre slightly damaged/cracking or perishing sidewall perishing (5.2.3 (d) (ii)) |
| Advice | Offside Rear Outer Tyre slightly damaged/cracking or perishing sidewall perishing (5.2.3 (d) (ii)) |
| Advice (5.2.3 (d) | Nearside Front Outer Tyre slightly damaged/cracking or perishing sidewall perishing 205/60/R16 |
| Advice | Offside Front Outer Tyre slightly damaged/cracking or perishing sidewall perishing (5.2.3 (d) (ii)) |

| MOT #1 | 2020-09-08 10:15 |
|-----------------|------------------|
| MOT test number | 705950217246 |
| Result | √ Passed |

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check





Expires: 29 September 2024

| Tax status | Valid until 1 February |
|------------------|------------------------|
| Days left | 278 |
| MOT expiry date | 29 September 2024 |
| Full MOT history | See MOT history |

Tax calculation

| 59 |
|------------|
| D |
| £ 120,00,- |
| £ 170,00,- |
| £ 93,50,- |
| £ 560,00,- |
| £ 308,00,- |
| |

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this KIA. See if, where and when this KIA had damage and the car repair costs. We also check if this KIA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Туре | |



Extra KIA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this KIA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

| For how long did the current and previous owner(s) have this KIA? How many owners did this KIA have? Check it in the premium report and see all owner registrations. Download the full report here. | |
|---|-------------|
| | |
| | |
| | |
| | |
| *************************************** | |
| ******** | |
| *************************************** | |
| *************************************** | |
| | More info > |
| | 7 |
| Plate changes | |
| See in this check if this KIA had different number plates. | |
| Number of plates | , |
| | |
| Current registration | NE NE |
| Plate since | |
| Current registration | OK SIE |
| Plate since | |
| | More info > |
| | |

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this KIA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this KIA has been settled.

If not, and you buy this KIA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this KIA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 6 |
| First mileage registration | 2017-09-30 |
| Last registration | 2023-08-31 |
| Complete history | See info |



| Registration #1 | 2017-09-30 | 23 mi |
|-----------------|------------|-----------|
| Registration #2 | 2020-09-08 | 13.924 mi |
| Registration #3 | | 11.777 es |
| Registration #4 | | 11.777 es |
| Registration #5 | | 11.777 es |
| Pogistration #6 | | |

Registration #6

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| 50482 | |
| 50501 | |
| 50566 | |
| 50567 | |
| 50569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 80% |
| Pedestrian | 70% |
| Safety systems | 81% |
| Overall rating | 83% |
| Video | see crash video |



Dimensions & weight

| Width | 1805 mm |
|---------------------|---------|
| Height | 1545 mm |
| Length | 4355 mm |
| Wheel base | 2700 mm |
| Kerb weight | 1566 kg |
| Max. allowed weight | 1930 kg |

Additional information

| Fuel tank capacity | 45 |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 5 |
| Number of seats CarCheck.co.uk | 5 page 11/11 |

Number of axles 2

Engine number G4LEGS136588