



SP09ZKU

report date: 2024-03-28

General information

Make	SUZUKI
Model	JIMNY JLX PLUS
Colour	Purple
Year of manufacture	2009
Top speed	87 mph
0 - 60 mph	14.1 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	84 BHP
Max. torque	110 Nm at 4.100 rpm
Engine capacity	1.328 cc
Cylinders	4
Fuel type	Petrol
Consumption city	30.4 mpg
Consumption extra urban	45.6 mpg
Consumption combined	38.7 mpg
CO2 emission	171 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-06-15
Pictures	20
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-20
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	27
Total items failed	30

MOT #18	2023-07-21 12:25
MOT test number	628046459767
Result	✓ Passed
Next expiry date	2024-07-20
Advice	Chassis corroded
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Advice	Fuel pipes corroded

MOT #17	2023-07-11 13:51
MOT test number	477436031838
Result	✗ Failed
Fail	Parking brake efficiency below requirements (1.4.2 (a) (i))
Advice	Chassis corroded
Fail	Offside Front Axle swivel pins and bushes swivel pin and/or bush excessively worn steering ball bearing (5.1.2 (b) (i))
Fail	Prop shaft likely to become detached off side transfer box mount broken (6.1.7 (a) (ii))
Advice	Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))
Fail	Suspension component damaged and seriously weakened front axle stay bar bent (5.3.3 (b) (i))
Advice	Fuel pipes corroded
Fail	Offside Rear Parking brake inoperative on one side (1.4.1 (a))

**MOT #16** 2022-06-27 15:46**MOT test number** 570128982220**Result** Passed**MOT #15** 2022-06-27 10:36**MOT test number** 738926181324**Result** Failed

- Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Lower Suspension component pin or bush excessively worn (5.3.4 (a) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))
- Fail** Nearside Front Upper Suspension component pin or bush excessively worn (5.3.4 (a) (i))

MOT #14 2021-06-04 11:22**MOT test number** 365863927755**Result** Passed

- Advice** Nearside Front swivel hub ball joint has slight play

**MOT #13**

2021-06-01 12:11

MOT test number

252996732441

Result**✗ Failed**

- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))
- Fail** Nearside Front Wheel bearing has excessive play (5.1.3 (a) (i))
- Fail** Nearside Rear Position lamp not working (4.2.1 (a) (ii))
- Fail** Hazard warning switch inoperative (4.4.2 (a) (ii))
- Fail** Offside Front Wheel bearing rough when rotated (5.1.3 (b) (i))

MOT #12

2020-11-19 12:15

MOT test number

452544625689

Result**✓ Passed**

- Advice** Front hub play o / s f/ and n / s/ f both sides

**MOT #11**

2020-11-09 17:26

MOT test number

406530917759

Result**✗ Failed**

- Advice** Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Central Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Nearside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))
- Advice** Offside Front Wheel hub spigot mounting slightly worn (5.2.1 (b) (i))
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Fail** Offside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))
- Advice** Nearside Front Wheel hub spigot mounting slightly worn (5.2.1 (b) (i))
- Advice** Rear Suspension component mounting prescribed area is corroded but not considered excessive (5.3.6 (a) (i))

MOT #10

2019-03-16 08:39

MOT test number

952487463497

Result**✓ Passed****MOT #9**

2018-03-27 14:01

MOT test number

469656152899

Result**✓ Passed**

**MOT #8** 2018-03-16 13:29**MOT test number** 970063695281**Result** ✗ Failed**Fail** Nearside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Exhaust has a major leak of exhaust gases (7.1.2)**Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**Fail** Emissions not tested (7.4.B.1)**MOT #7** 2017-03-11 10:27**MOT test number** 657343893686**Result** ✓ Passed**Advice** Offside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Brake pad(s) wearing thin (3.5.1g)**Advice** Nearside Front Brake pipe slightly corroded (3.6.B.2c)**Advice** Central Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Rear Brake pipe slightly corroded (3.6.B.2c)**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #6** 2016-04-02 11:13**MOT test number** 363358493545**Result** ✓ Passed**Advice** Offside Front Axle swivel joint has slight movement between a swivel joint and its housing (2.5.A.1b)

**MOT #5** 2016-03-28 11:37**MOT test number** 499222071947**Result** ✗ Failed**Fail** Nearside Front front brake binding (3.7.B.1)**Fail** Nearside Front Axle swivel joint has excessive movement between a swivel joint and its housing (2.5.A.1b)**Fail** Offside rear brake recording little or no effort (3.7.B.5a)**Fail** Rear Brakes imbalanced across an axle Axle 2 (3.7.B.5b)**Fail** Offside Front front brake binding (3.7.B.1)**Advice** Offside Front Axle swivel joint has slight movement between a swivel joint and its housing (2.5.A.1b)**Advice** Nearside Front swivel hub seal leaking slightly.**MOT #4** 2015-04-09 10:44**MOT test number** 509239195034**Result** ✓ Passed**MOT #3** 2014-10-28 08:42**MOT test number** 559550704374**Result** ✓ Passed**MOT #2** 2013-07-10 13:00**MOT test number** 466631793184**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #1** 2012-06-20 10:09**MOT test number** 666012672129**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
20 July 2024

Tax status	Valid until 1 November
Days left	187
MOT expiry date	20 July 2024
Full MOT history	See MOT history

Tax calculation


Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1		
Date		
Category		
Type		
Damage 2		
Date		
Category		
Type		



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-28
Current registration	 
Plate since	2024-03-28

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2009-04-30
Last registration	2023-07-21
Complete history	See info



Registration #1	2009-04-30	14 mi
Registration #2	2012-06-20	10.197 mi
Registration #3	2013-07-10	12.160 mi
Registration #4	2014-10-28	12.928 mi
Registration #5	2015-04-09	15.368 mi
Registration #6	2016-03-28	33.833 mi
Registration #7	2016-04-02	34.175 mi
Registration #8	2017-03-11	55.183 mi
Registration #9	2018-03-16	78.713 mi
Registration #10	2018-03-27	78.777 mi
Registration #11	2019-05-20	79.277 mi
Registration #12	2019-05-20	79.277 mi
Registration #13	2019-05-20	79.277 mi
Registration #14	2019-05-20	79.277 mi
Registration #15	2019-05-20	79.277 mi
Registration #16	2019-05-20	79.277 mi
Registration #17	2019-05-20	79.277 mi
Registration #18	2019-05-20	79.277 mi
Registration #19	2019-05-20	79.277 mi
Registration #20	2019-05-20	79.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1705 mm
Length	3665 mm
Wheel base	2250 mm
Kerb weight	1150 kg
Max. allowed weight	1420 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	M13A-2102287