



report date: 2024-03-29

General information

Make	MAZDA
Model	RX-8 RX-8 231PS
Colour	Silver
Year of manufacture	2005
Top speed	146 mph
0 - 60 mph	6.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	228 BHP
Max. torque	216 Nm at 5.500 rpm
Engine capacity	2.616 cc
Fuel type	Petrol
Consumption city	17.9 mpg
Consumption extra urban	31.7 mpg
Consumption combined	24.8 mpg
CO2 emission	284 g/km
CO2 label	M






Internet history

Entry 1

Date	2021-06-07
Pictures	7
Listing price	View report



source: autotrader.co.uk

**MOT history**

MOT expiry date	2022-04-02
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	17
Total items failed	10

MOT #10	2021-04-03 13:37
MOT test number	984102573760
Result	✓ Passed
Next expiry date	2022-04-02
Advice	Nearside Rear Coil spring corroded (5.3.1 (b) (i))
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))

MOT #9	2013-09-06 12:24
MOT test number	296029843265
Result	✓ Passed
Advice	Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)

MOT #8	2012-07-06 16:32
MOT test number	639138882103
Result	✓ Passed
Advice	Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)
Advice	Front Brake pad(s) wearing thin (3.5.1g)
Advice	Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)

**MOT #7**

2012-07-05 10:13

MOT test number

529537382147

Result**✗ Failed****Fail** Offside Front Steering system has a road wheel fouling a part of the vehicle (2.2.D.2a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Steering system has a tyre fouling a part of the vehicle (2.2.D.2a)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a pin/bush (2.4.G.2)**Advice** Offside Side repeater damaged, but still visible from a reasonable distance (1.4.A.2e)**MOT #6**

2011-06-22 08:28

MOT test number

787953971161

Result**✓ Passed****Notice** O/s wing repeater lamp damaged**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #5**

2011-06-14 09:40

MOT test number

917675661141

Result**✗ Failed****Fail** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Offside Front Headlamp aim too low (1.8)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Notice** O/s wing repeater lamp damaged**Fail** Nearside Front Headlamp aim too low (1.8)

**MOT #4** 2010-05-28 13:05**MOT test number** 283308540120**Result** ✓ Passed**Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)**MOT #3** 2009-06-18 18:25**MOT test number** 660809369100**Result** ✗ Failed**Pass with rectification** Nearside Front Wheel nut(s) missing (4.2.A.1e)**Pass with rectification** Offside Wheel nut(s) missing (4.2.A.1e)**Pass with rectification** Offside Front Wheel nut(s) missing (4.2.A.1e)**Pass with rectification** Nearside Front Direction indicators not working (1.4.A.2c)**Notice** Front bumper loose**MOT #2** 2009-06-18 18:25**MOT test number** 943489869112**Result** ✓ Passed**Notice** Front bumper loose**MOT #1** 2008-05-09 12:09**MOT test number** 643990138124**Result** ✓ Passed



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	PX05PHZ
Plate since	2024-03-29
Current registration	PX05PHZ
Plate since	2024-03-29

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX XXXX
Date of agreement	XXXXXXXXXX XXXX
Agreement type	XXXXXXXXXX XXXX
Agreement term	XXXXXXXXXX XXXX
Agreement number	XXXXXXXXXX XXXX
Contact info	XXXXXXXXXX XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2005-03-17
Last registration	2021-04-03
Complete history	See info



Registration #1	2005-03-17	17 mi
Registration #2	2008-05-09	22.385 mi
Registration #3	2009-06-18	30.347 mi
Registration #4	2010-05-28	38.752 mi
Registration #5	2011-06-14	44.218 mi
Registration #6	2011-06-22	44.314 mi
Registration #7	2012-06-20	50.277 mi
Registration #8	2013-06-20	55.277 mi
Registration #9	2014-06-20	60.277 mi
Registration #10	2015-06-20	65.277 mi
Registration #11	2021-04-03	70.277 mi

More info >



Dimensions & weight

Width	1771 mm
Height	1340 mm
Length	4435 mm
Wheel base	2700 mm
Max. allowed weight	1815 kg

Additional information

Fuel tank capacity	61 l
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	4
Number of axles	2
Engine number	13B485319