



TOYOTA




report date: 2024-03-29

General information

Make	TOYOTA
Model	LAND CRUISER TD
Colour	Red
Year of manufacture	2007
Top speed	112 mph
0 - 60 mph	11.5 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	201 BHP
Max. torque	429 Nm at 1.400 rpm
Engine capacity	4.164 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.1 mpg
Consumption extra urban	31.4 mpg
Consumption combined	26.7 mpg
CO2 emission	282 g/km
CO2 label	M







Internet history

Entry 1

Date	2022-02-15
Pictures	76
Listing price	<a href="#">View report</a>



source: [autotrader.co.uk](https://www.autotrader.co.uk)



## MOT history

MOT expiry date	2024-10-25
MOT pass rate	93 %
MOT passed	14
Failed MOT tests	1
Total advice items	19
Total items failed	2

MOT #15	2023-10-26 08:50
MOT test number	875513616930
Result	✓ Passed
Next expiry date	2024-10-25
Advice	Nearside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
Advice	Offside Rear Lower Anti-roll bar linkage pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #14	2022-10-19 12:28
MOT test number	676046048603
Result	✓ Passed

MOT #13	2021-10-22 12:30
MOT test number	550805901656
Result	✓ Passed

MOT #12	2020-08-25 10:15
MOT test number	388108539953
Result	✓ Passed

**MOT #11** 2019-09-17 09:31**MOT test number** 168267432500**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Minor** Offside Front Windscreen damaged but not adversely affecting driver's view zone a small crack below 10mm (3.2 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**MOT #10** 2018-08-29 15:35**MOT test number** 444618253621**Result** ✓ Passed**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (i))**Advice** Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #9** 2017-09-05 09:22**MOT test number** 224533436820**Result** ✓ Passed**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**Advice** Central Front Lower Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)**MOT #8** 2016-09-21 09:57**MOT test number** 371235497162**Result** ✓ Passed**Advice** Chip in front screen**Advice** Slight cracking to both rear tyres

**MOT #7** 2015-10-22 13:39**MOT test number** 566739106032**Result** ✓ Passed**Advice** Offside Front Windscreen has damage to an area less than a 10mm circle within zone 'A' stone chip (8.3.1a)**MOT #6** 2014-09-15 10:01**MOT test number** 998208154255**Result** ✓ Passed**Advice** Offside Front Front wheel bearing has slight play (2.5.A.3c)**MOT #5** 2013-09-10 11:26**MOT test number** 245783953286**Result** ✓ Passed**MOT #4** 2012-09-19 11:30**MOT test number** 259773862230**Result** ✓ Passed**Notice** All four tyres have surface cracks**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Both front tyres wearing uneven**Notice** Under-trays fitted obscuring some underside components**MOT #3** 2011-09-23 11:34**MOT test number** 609346661218**Result** ✓ Passed**Notice** All four tyres wearing uneven



MOT #2	2011-09-07 17:13
MOT test number	596540351219
Result	✗ Failed
Fail	Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)
Fail	Offside Rear Rear reflector excessively damaged so that its function is impaired (1.5.1c)
Advice	Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2010-09-27 11:14
MOT test number	463250170239
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 June 2024

✓  
**MOT**  
**Expires:**  
25 October 2024

<b>Tax status</b>	Valid until 1 June
<b>Days left</b>	33
<b>MOT expiry date</b>	25 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	M
<b>Single payment (12 months)</b>	£ 695,00,-
<b>Single six month payment</b>	£ 382,25,-
<b>Total payable by 12 monthly instalments</b>	£ 729,75,-




Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this TOYOTA? How many owners did this TOYOTA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this TOYOTA had different number plates.

Number of plates	1
Current registration	EK57WMJ
Plate since	2019-03-29
Current registration	EK57WMJ
Plate since	2019-03-29

More info >



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled. If not, and you buy this TOYOTA then you could lose the money and the car you paid for. Download the premium report [here](#) and check if this TOYOTA is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-09-27
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2007-09-27	9 mi
Registration #2	2010-09-27	26.585 mi
Registration #3	2011-09-07	30.268 mi
Registration #4	2011-09-23	30.401 mi
Registration #5	2012-09-19	37.137 mi
Registration #6	2013-09-10	40.695 mi
Registration #7	2014-09-15	46.838 mi
Registration #8	2015-10-22	53.852 mi
Registration #9	2016-09-21	58.595 mi
Registration #10	2017-09-21	65.337 mi
Registration #11	2018-09-21	72.079 mi
Registration #12	2019-09-21	78.821 mi
Registration #13	2020-09-21	85.563 mi
Registration #14	2021-09-21	92.305 mi
Registration #15	2022-09-21	99.047 mi
Registration #16	2023-09-21	105.789 mi
Registration #17	2023-10-26	112.531 mi

More info >



Car features

The TOYOTA factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete TOYOTA factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1940 mm
Height	1890 mm
Length	4890 mm
Wheel base	2850 mm
Kerb weight	2510 kg
Max. allowed weight	3260 kg

Additional information

Fuel tank capacity	87 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	1HD0306096