



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	KANGOO SL 17P 75
Colour	Blue
Year of manufacture	2002
Top speed	91 mph
0 - 60 mph	17.0 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	75 BHP
Max. torque	114 Nm at 2.800 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-01
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



MOT history

MOT expiry date	2025-03-24
MOT pass rate	77 %
MOT passed	17
Failed MOT tests	5
Total advice items	21
Total items failed	8

MOT #22	2024-03-25 14:12
MOT test number	475230260087
Result	✓ Passed
Next expiry date	2025-03-24
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Play in steering rack inner joint(s)
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear Exhaust mounting defective (6.1.2 (a))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Minor	Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))



## MOT #21

2024-03-25 14:12

MOT test number

743294340271

## Result

✗ Failed

**Pass with rectification** Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Rear Exhaust mounting defective (6.1.2 (a))

**Advice** Play in steering rack inner joint(s)

**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

## MOT #20

2023-03-02 08:45

MOT test number

877005812745

## Result

✓ Passed

## MOT #19

2022-08-01 13:58

MOT test number

279066747974

## Result

✓ Passed

## MOT #18

2022-08-01 11:33

MOT test number

508563861150

## Result

✗ Failed

**Fail** Front Registration plate inscription illegible (0.1 (b))

**Fail** Battery insecure and likely to cause a short circuit (4.13 (a) (ii))

**Fail** Nearside Steering rack gaiter missing or no longer prevents the ingress of dirt (2.1.3 (g) (ii))

**MOT #17** 2021-07-24 14:45**MOT test number** 464195442911**Result** ✓ Passed**MOT #16** 2021-07-24 14:45**MOT test number** 178950269216**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))**MOT #15** 2019-05-08 10:59**MOT test number** 222608822013**Result** ✓ Passed**MOT #14** 2018-03-27 08:43**MOT test number** 202665449091**Result** ✓ Passed**MOT #13** 2017-03-28 12:04**MOT test number** 786349653791**Result** ✓ Passed**MOT #12** 2016-02-22 11:32**MOT test number** 662003821714**Result** ✓ Passed**Advice** Nearside Front Tyre has got crack around the circumference**MOT #11** 2015-03-02 11:07**MOT test number** 205421565044**Result** ✓ Passed**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**MOT #10** 2014-02-27 11:04**MOT test number** 457678354027**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)**MOT #9** 2014-02-26 17:08**MOT test number** 749097754031**Result** ✗ Failed**Fail** Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Offside Front Road wheel slightly damaged (4.2.A.1a)**MOT #8** 2011-11-21 12:49**MOT test number** 206345921370**Result** ✓ Passed**MOT #7** 2010-11-30 11:32**MOT test number** 504424330311**Result** ✓ Passed**MOT #6** 2009-11-16 11:25**MOT test number** 440880229436**Result** ✓ Passed

**MOT #5** 2008-11-25 10:46**MOT test number** 484470938461**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #4** 2007-11-26 11:56**MOT test number** 534960637395**Result** ✓ Passed**Notice** Advise nearside front tyre is on the legal limit .**MOT #3** 2006-11-09 11:25**MOT test number** 690383516315**Result** ✓ Passed**MOT #2** 2006-11-07 17:07**MOT test number** 953141416338**Result** ✗ Failed**Fail** Anti-lock braking system warning lamp indicates an ABS fault (3.4.1c)**MOT #1** 2005-11-25 12:01**MOT test number** 883969525326**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
24 March 2025

<b>Tax status</b>	Valid until 1 February
-------------------	------------------------

<b>Days left</b>	279
------------------	-----

<b>MOT expiry date</b>	24 March 2025
------------------------	---------------

<b>Full MOT history</b>	<a href="#">See MOT history</a>
-------------------------	---------------------------------





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01
Current registration	<b>XXXXXX</b>
Plate since	2020-01-01

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2002-11-30
Last registration	2024-03-25
Complete history	<a href="#">See info</a>



Registration #1	2002-11-30	14 mi
Registration #2	2005-11-25	9.452 mi
Registration #3	2006-11-07	12.131 mi
Registration #4	2006-11-09	12.131 mi
Registration #5	2007-11-26	14.678 mi
Registration #6	2008-11-25	16.264 mi
Registration #7	2009-11-16	16.549 mi
Registration #8	2010-11-30	16.739 mi
Registration #9	2011-11-21	16.872 mi
Registration #10	2014-02-26	16.873 mi
Registration #11	2014-02-27	16.873 mi
Registration #12	2015-03-02	16.901 mi
Registration #13	2015-03-20	20,000
Registration #14	2015-03-20	20,000
Registration #15	2015-03-20	20,000
Registration #16	2015-03-20	20,000
Registration #17	2015-03-20	20,000
Registration #18	2015-03-20	20,000
Registration #19	2015-03-20	20,000
Registration #20	2015-03-20	20,000
Registration #21	2015-03-20	20,000
Registration #22	2015-03-20	20,000
Registration #23	2015-03-20	20,000
Registration #24	2015-03-20	20,000

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	2031 mm
Height	1835 mm
Length	4035 mm
Kerb weight	1080 kg

Additional information

Fuel tank capacity	50 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Engine number	R008895