



report date: 2024-03-28

General information

Make	VAUXHALL
Model	COMBO 2000 CDTI
Colour	White
Year of manufacture	2009
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	170 Nm at 1.750 rpm
Engine capacity	1.248 cc
Cylinders	4
Fuel type	Diesel
Consumption city	45.6 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg



LABEL UNKNOWN



Internet history

Entry 2

Date	2022-06-18
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-10-09
Pictures	20
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-04
MOT pass rate	81 %
MOT passed	13
Failed MOT tests	3
Total advice items	25
Total items failed	5

MOT #16	2023-12-14 10:35
MOT test number	266024737379
Result	✓ Passed
Next expiry date	2025-01-04
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

MOT #15	2023-12-11 12:04
MOT test number	447083722131
Result	✗ Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail	Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

MOT #14	2022-12-05 10:56
MOT test number	526430525253
Result	✓ Passed
Minor	Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Vehicles internal headlight adjuster altered to recheck lights
Advice	Items removed from driver's view prior to test



MOT #13	2022-01-05 13:53
MOT test number	362395053093
Result	✓ Passed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))

MOT #12	2022-01-04 10:26
MOT test number	712199568905
Result	✗ Failed
Minor	Battery insecure but not likely to fall from carrier (4.13 (a) (i))
Fail	Nearside Front Position lamp not working (4.2.1 (a) (ii))
Fail	Nearside Front Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

MOT #11	2021-02-26 09:25
MOT test number	316592997128
Result	✓ Passed

MOT #10	2020-05-02 10:05
MOT test number	283225365143
Result	✓ Passed
Minor	Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Offside Front Service brake binding but not excessively (1.2.1 (f))

MOT #9	2019-01-25 15:23
MOT test number	574960817315
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))
Advice	Offside Front brake slight bind

**MOT #8** 2017-12-27 11:25**MOT test number** 427625332217**Result** ✓ Passed**MOT #7** 2017-01-04 09:10**MOT test number** 223196985122**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust back box slightly corroded by rust but not leaking**MOT #6** 2017-01-04 09:10**MOT test number** 389776941709**Result** ✗ Failed**Pass with rectification** Offside Stop lamp not working (1.2.1b)**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Exhaust back box slightly corroded by rust but not leaking**MOT #5** 2016-01-14 12:12**MOT test number** 280545936109**Result** ✓ Passed**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front Tie bar/rod has slight play in a ball joint (2.4.G.2)**Advice** Rear Exhaust has a minor leak of exhaust gases back box (7.1.2)**MOT #4** 2015-02-26 10:53**MOT test number** 947127355016**Result** ✓ Passed

**MOT #3** 2014-03-06 15:56**MOT test number** 446885464098**Result** ✓ Passed**Advice** Nearside Front Lower Anti-roll bar ball joint dust cover damaged, but preventing the ingress of dirt (2.4.G.2)**Advice** Nearside Rear Upper Stop lamp damaged, but still visible from a reasonable distance (1.2.1d)**MOT #2** 2013-03-25 15:58**MOT test number** 717004783012**Result** ✓ Passed**MOT #1** 2012-03-30 15:24**MOT test number** 467260092046**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed

Tax due:
1 January 2025

✓
MOT

Expires:
4 January 2025

Tax status

Valid until 1 January

Days left

248

MOT expiry date

4 January 2025

Full MOT history

[See MOT history](#)



Damage history


Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	WN09HDA
Plate since	2019-09-29
Current registration	WN09HDA
Plate since	2019-09-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-03-23
Last registration	2023-12-14
Complete history	See info



Registration #1	2009-03-23	21 mi
Registration #2	2012-03-30	25.397 mi
Registration #3	2013-03-25	35.848 mi
Registration #4	2014-03-06	45.273 mi
Registration #5	2015-02-26	54.102 mi
Registration #6	2016-01-14	64.655 mi
Registration #7	2017-01-04	72.245 mi
Registration #8	2017-01-04	72.245 mi
Registration #9	2017-12-27	79.001 mi
Registration #10	2019-01-25	87.326 mi
Registration #11	2019-01-25	87.326 mi
Registration #12	2019-01-25	87.326 mi
Registration #13	2019-01-25	87.326 mi
Registration #14	2019-01-25	87.326 mi
Registration #15	2019-01-25	87.326 mi
Registration #16	2019-01-25	87.326 mi
Registration #17	2019-01-25	87.326 mi
Registration #18	2019-01-25	87.326 mi
Registration #19	2019-01-25	87.326 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1892 mm
Height	1801 mm
Length	4323 mm
Kerb weight	1210 kg
Max. allowed weight	1995 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	3302375