



report date: 2024-03-29

General information

Make	FORD
Model	GALAXY ZETEC TDCI
Colour	Silver
Year of manufacture	2008
Top speed	72 mph
0 - 60 mph	11.8 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	130 BHP
Max. torque	340 Nm at 2.000 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Diesel
Consumption city	28.3 mpg
Consumption extra urban	47.9 mpg
Consumption combined	38.2 mpg
CO2 emission	196 g/km
CO2 label	J





MOT history

MOT expiry date	2021-01-05
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	59
Total items failed	3

MOT #142021-01-05 10:56

MOT test number132945363651

ResultX Failed

**MAJOR** Offside Front Prop shaft joint constant velocity boot no longer prevents the ingress of dirt (6.1.7 (g) (ii))

**Advice** Osr tail lamp cracked

**Minor** Windscreen wiper blade defective osf (3.4 (b) (i))

**Advice** Nearside Front Nail in tyre

**MAJOR** Offside Front Position lamp not working (4.2.1 (a) (ii))

**Advice** Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MAJOR** Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

**MAJOR** Nearside Rear Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MAJOR** Offside Front Windscreen washer jets misaligned and not providing sufficient fluid to the windscreen (3.5 (a))

**Minor** Offside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

**Advice** Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**Advice** Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))



MOT #13

2020-01-06 12:13

MOT test number

419200106742

Result

✓ Passed

- Advice

Registration plate lamps damaged but operate
- Advice

Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Engine covers and undertrays fitted obscuring components
- Advice

Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice

Rear suspension components corroded
- Advice

Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice

Offside Rear Outer lens damaged
- Advice

Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- Minor

Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice

Gear lever safety lock out missing

**MOT #12** 2020-01-02 14:10**MOT test number** 582294877635**Result** ✗ Failed

- Advice** Nearside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- MAJOR** Engine MIL inoperative or indicates a malfunction (8.2.2.2 (g))
- Advice** Gear lever safety lock out missing
- Advice** Rear Registration plate deteriorated but not likely to be misread (0.1 (b))
- Minor** Offside Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))
- MAJOR** Exhaust has a major leak of exhaust gases pipe at catalyser broken (6.1.2 (a))
- Advice** Engine covers and undertrays fitted obscuring components
- Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))
- Advice** Rear suspension components corroded
- MAJOR** Nearside Front Body component damaged and likely to cause injury fog light lens (6.2.1 (a) (i))
- MAJOR** Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))

**MOT #11** 2018-12-03 20:25**MOT test number** 315486373297**Result** ✓ Passed**MOT #10** 2018-01-05 13:41**MOT test number** 243197457910**Result** ✓ Passed

**MOT #9** 2017-01-09 16:28**MOT test number** 129042720571**Result** ✓ Passed**Advice** Rear registration plate deteriorated but not likely to be misread cracked (6.3.1d)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #8** 2016-01-20 10:03**MOT test number** 304701364594**Result** ✓ Passed**MOT #7** 2015-01-19 09:34**MOT test number** 268399215009**Result** ✓ Passed**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**MOT #6** 2015-01-19 09:34**MOT test number** 938229215085**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Pass with rectification** Offside Rear Stop lamp not working (1.2.1b)**Notice** Under-trays fitted obscuring some underside components

**MOT #5** 2014-01-10 09:50**MOT test number** 166980414087**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Oil leak**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #4** 2013-01-24 12:39**MOT test number** 166204623039**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #3** 2013-01-23 13:52**MOT test number** 409643923022**Result** ✗ Failed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)



MOT #2 2012-01-16 09:47

MOT test number 345496212053

Result ✓ Passed

**Notice** Engine covers fitted obscuring some components in the engine bay

**Advice** Front Brake pad(s) wearing thin (3.5.1g)

**Notice** Under-trays fitted obscuring some underside components

**Notice** Child seat fitted not allowing full inspection of adult belt

MOT #1 2011-01-21 10:00

MOT test number 895521321095

Result ✓ Passed

**Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**Notice** Child seat fitted not allowing full inspection of adult belt

**Advice** Power steering component(s) has slight seepage from a component (2.3.3b)



Tax & MOT check

X

Untaxed

Tax expired:  
28 December 2020

X

MOT

Expired:  
5 January 2021

Tax status	Expired at 28 December 2020
Days left	1219 days too late
MOT expiry date	5 January 2021
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>YB57FNW</b>
Plate since	2019-03-29
Current registration	<b>YB57FNW</b>
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2008-01-30
Last registration	2021-01-05
Complete history	<a href="#">See info</a>



Registration #1	2008-01-30	10 mi
Registration #2	2011-01-21	28.498 mi
Registration #3	2012-01-16	34.773 mi
Registration #4	2013-01-23	38.972 mi
Registration #5	2013-01-24	38.972 mi
Registration #6	2014-01-10	43.380 mi
Registration #7	2015-01-19	48.461 mi
Registration #8	2015-01-20	51.277 mi
Registration #9	2015-01-21	51.277 mi
Registration #10	2015-01-22	51.277 mi
Registration #11	2015-01-23	51.277 mi
Registration #12	2015-01-24	51.277 mi
Registration #13	2015-01-25	51.277 mi
Registration #14	2015-01-26	51.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2154 mm
Height	1736 mm
Length	4820 mm
Wheel base	2850 mm
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	7
Number of axles	2

**Engine number**

8R41849