



RENAULT



report date: 2024-03-28

General information

Make	RENAULT
Model	SCENIC EXPRESSION 16V SCENIC EU4
Colour	Black
Year of manufacture	2004
Top speed	108 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	97 BHP
Max. torque	127 Nm at 3.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	47.1 mpg
Consumption combined	38.7 mpg
CO2 emission	175 g/km
CO2 label	H



**MOT history**

MOT expiry date	2022-11-30
MOT pass rate	75 %
MOT passed	15
Failed MOT tests	5
Total advice items	39
Total items failed	17

MOT #20	2021-12-01 17:32
MOT test number	294036069742
Result	✓ Passed
Next expiry date	2022-11-30

MOT #19	2020-11-16 15:42
MOT test number	229720278616
Result	✓ Passed

- Advice** Engine, under tray and floor covers fitted
- Advice** Tyre slightly damaged/cracking or perishing all fitted perished (5.2.3 (d) (ii))
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Exhaust heat shield loose
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

**MOT #18**

2020-11-05 13:11

MOT test number

672802704275

Result**✗ Failed**

- Fail** Rear Brake pipe excessively corroded over axle (1.1.11 (c))
- Fail** Offside Front Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt split/twisted (5.3.4 (b) (ii))
- Pass with rectification** Offside Front Headlamp aim too low (4.1.2 (a))
- Advice** Engine, under tray and floor covers fitted
- Advice** Offside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Tyre slightly damaged/cracking or perishing all fitted perished (5.2.3 (d) (ii))
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Rear Road wheel slightly distorted (5.2.2 (c) (i))
- Pass with rectification** Nearside Front Headlamp aim too low (4.1.2 (a))
- Advice** Nearside Rear Axle swivel pins and bushes swivel pin and/or bush slightly worn (5.1.2 (b) (i))
- Advice** Exhaust heat shield loose
- Advice** Nearside Front Coil spring corroded (5.3.1 (b) (i))

MOT #17

2019-11-19 09:59

MOT test number

785438101762

Result**✓ Passed**

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Items removed from driver's view prior to test
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Advice** Nearside Play in steering rack inner joint(s)

**MOT #16**

2019-11-13 09:55

MOT test number

519577025128

Result

✗ Failed

- Advice** Offside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))
- Advice** Items removed from driver's view prior to test
- Fail** Offside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))
- Fail** Offside Stop lamp(s) not working (4.3.1 (a) (ii))
- Advice** Unable to check offside rear wheel bearing due to brake binding
- Fail** Nearside Headlamp has a product on the lens so that the light output is severely reduced (4.1.4 (b))
- Advice** Nearside Play in steering rack inner joint(s)
- Fail** Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #15

2018-11-07 10:05

MOT test number

434809456588

Result

✓ Passed

- Advice** Nearside Play in steering rack inner joint(s)

MOT #14

2017-11-01 11:11

MOT test number

487757901930

Result

✓ Passed

MOT #13

2016-11-02 10:50

MOT test number

629046907012

Result

✓ Passed

**MOT #12** 2015-11-09 11:29**MOT test number** 536306366695**Result** ✓ Passed**Advice** Removed items from drivers view**MOT #11** 2014-11-15 08:58**MOT test number** 428119414420**Result** ✓ Passed**MOT #10** 2014-11-15 08:58**MOT test number** 548169814329**Result** ✗ Failed**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**MOT #9** 2013-11-02 12:09**MOT test number** 769586703388**Result** ✓ Passed**Notice** Front brake discs worn and pitted**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Under-trays fitted obscuring some underside components

**MOT #8** 2013-10-30 09:35**MOT test number** 917223203304**Result** ✗ Failed**Notice** Engine covers fitted obscuring some components in the engine bay**Fail** Offside Track rod end ball joint has excessive play (2.2.B.1f)**Notice** Coolant level below min**Notice** Under-trays fitted obscuring some underside components**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Offside Headlamp aim too high and too far to the left. (1.8)**Notice** Child seat fitted not allowing full inspection of adult belt**Notice** Front brake discs worn and pitted**MOT #7** 2012-11-05 16:21**MOT test number** 927060912387**Result** ✓ Passed**MOT #6** 2011-11-17 11:23**MOT test number** 195121821352**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt

**MOT #5** 2011-11-12 13:07**MOT test number** 315336811351**Result** ✗ Failed

Advice Service brake: service brake efficiency only just met. It would appear that the braking system requires adjustment or repair. (3.7.B.7)

Fail Offside Stop lamp not working (1.2.1b)

Fail Brakes imbalanced across an axle (3.7.B.5b)

Notice Child seat fitted not allowing full inspection of adult belt

Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

MOT #4 2010-11-03 12:14**MOT test number** 404547500425**Result** ✓ Passed**MOT #3** 2009-11-20 09:38**MOT test number** 531264329311**Result** ✓ Passed**MOT #2** 2008-11-11 14:41**MOT test number** 554916118392**Result** ✓ Passed**MOT #1** 2007-11-19 14:57**MOT test number** 470003527482**Result** ✓ Passed

Advice Offside Rear brake disc slightly pitted (3.5.1h)

Advice Nearside Rear brake disc slightly pitted (3.5.1h)



Tax & MOT check

X

Untaxed

Tax expired:
1 June 2022

X

MOT

Expired:
30 November 2022

Tax status	Expired at 1 June 2022
Days left	697 days too late
MOT expiry date	30 November 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-11-26
Last registration	2021-12-01
Complete history	See info



Registration #1	2004-11-26	13 mi
Registration #2	2007-11-19	22.327 mi
Registration #3	2008-11-11	28.027 mi
Registration #4	2009-11-20	34.574 mi
Registration #5	2010-11-03	40.979 mi
Registration #6	2011-11-12	10.128 mi
Registration #7	2011-11-17	10.333 mi
Registration #8	2012-11-05	19.006 mi
Registration #9	2013-10-30	25.734 mi
Registration #10	2013-11-02	25.838 mi
Registration #11	2014-11-02	25.777 mi
Registration #12	2015-11-02	25.777 mi
Registration #13	2016-11-02	25.777 mi
Registration #14	2017-11-02	25.777 mi
Registration #15	2018-11-02	25.777 mi
Registration #16	2019-11-02	25.777 mi
Registration #17	2020-11-02	25.777 mi
Registration #18	2021-11-02	25.777 mi
Registration #19	2022-11-02	25.777 mi
Registration #20	2023-11-02	25.777 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1620 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1315 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

D051994