



RENAULT




report date: 2024-03-29

General information

Make	RENAULT
Model	SCENIC EXTREME II 16V 100 SCENIC
Colour	Blue
Year of manufacture	2008
Top speed	108 mph
0 - 60 mph	14.3 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	100 BHP
Max. torque	127 Nm at 3.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	47.9 mpg
Consumption combined	39.2 mpg
CO2 emission	173 g/km
CO2 label	H






Internet history

Entry 1

Date	2021-08-11
Pictures	5
Listing price	<a href="#">View report</a>



source: cargurus.co.uk



MOT history

MOT expiry date	2025-02-12
MOT pass rate	70 %
MOT passed	14
Failed MOT tests	6
Total advice items	33
Total items failed	11

MOT #20	2024-02-13 18:41
MOT test number	382956292956
Result	✓ Passed
Next expiry date	2025-02-12
Advice	Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))

MOT #19	2022-09-26 14:27
MOT test number	863223243951
Result	✓ Passed

MOT #18	2021-09-24 08:33
MOT test number	860992885238
Result	✓ Passed

**MOT #17**

2020-09-05 09:33

**MOT test number**

124379891132

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))
- Advice** Nearside Play in steering rack inner joint(s)
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #16**

2019-09-14 08:43

**MOT test number**

657321440446

**Result**

✓ Passed

- Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Play in steering rack inner joint(s)

**MOT #15**

2018-09-15 08:31

**MOT test number**

198762464937

**Result**

✓ Passed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge LOW ON EDGES (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge LOW ON EDGES (5.2.3 (e))

**MOT #14** 2018-09-15 08:31**MOT test number** 571387199132**Result** ✗ Failed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge LOW ON EDGES (5.2.3 (e))**Pass with rectification** Nearside Front Position lamp not working (4.2.1 (a))**Advice** Offside Front Tyre worn close to legal limit/worn on edge LOW ON EDGES (5.2.3 (e))**Pass with rectification** Offside Front Position lamp not working (4.2.1 (a))**MOT #13** 2017-09-23 09:42**MOT test number** 909771602726**Result** ✓ Passed**MOT #12** 2016-09-17 11:51**MOT test number** 386004092817**Result** ✓ Passed**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #11** 2016-09-17 08:05**MOT test number** 586163063901**Result** ✗ Failed**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)**Advice** Offside inner tie rod has slight play**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Offside front tyre worn excessively on edges

**MOT #10** 2015-09-05 11:57**MOT test number** 944826129210**Result** ✓ Passed

- Advice** Rack inner joints have slight play.
- Advice** O/S/R tyre cracked and perished.
- Advice** Both front tyres wearing on their inner edges.

**MOT #9** 2015-09-05 08:52**MOT test number** 725736874164**Result** ✗ Failed

- Advice** Both front tyres wearing on their inner edges.
- Advice** Rack inner joints have slight play.
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm 195/65R15 (4.1.E.1)
- Advice** O/S/R tyre cracked and perished.

**MOT #8** 2014-09-06 12:07**MOT test number** 385039244464**Result** ✓ Passed**MOT #7** 2014-09-06 08:48**MOT test number** 277589244204**Result** ✗ Failed

- Fail** Offside Front position lamp(s) not working (1.1.A.3b)
- Fail** Nearside Front position lamp(s) not working (1.1.A.3b)



<b>MOT #6</b>	2013-09-09 12:37
<b>MOT test number</b>	797342353298
<b>Result</b>	✓ Passed
<div><b>Notice</b> Play in steering rack inner joint(s)</div>	

<b>MOT #5</b>	2013-09-07 08:43
<b>MOT test number</b>	359060153419
<b>Result</b>	✗ Failed
<div><b>Fail</b> Nearside Rear Shock absorber has a serious fluid leak (2.7.3)</div> <div><b>Advice</b> Offside Front Tyre worn close to the legal limit (4.1.E.1)</div> <div><b>Notice</b> Play in steering rack inner joint(s)</div> <div><b>Fail</b> Offside Front position lamp(s) not working (1.1.A.3b)</div> <div><b>Advice</b> Nearside Front Tyre worn close to the legal limit (4.1.E.1)</div>	

<b>MOT #4</b>	2012-09-26 16:30
<b>MOT test number</b>	748290272256
<b>Result</b>	✓ Passed
<div><b>Notice</b> Under-trays fitted obscuring some underside components</div> <div><b>Notice</b> Engine covers fitted obscuring some components in the engine bay</div>	



MOT #3	2012-09-26 16:30
MOT test number	785460172279
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Notice	Under-trays fitted obscuring some underside components
Pass with rectification	Nearside Headlamp aim too low (1.8)
Notice	Engine covers fitted obscuring some components in the engine bay
Pass with rectification	Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #2	2012-03-06 11:15
MOT test number	758146162017
Result	✓ Passed

MOT #1	2011-03-11 14:19
MOT test number	696980571096
Result	✓ Passed





Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
12 February 2025

<b>Tax status</b>	Valid until 1 April
<b>Days left</b>	336
<b>MOT expiry date</b>	12 February 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	H
<b>Single payment (12 months)</b>	£ 290,00,-
<b>Single six month payment</b>	£ 159,50,-
<b>Total payable by 12 monthly instalments</b>	£ 304,50,-



Damage history


Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	KU08XZD
Plate since	2019-03-29
Current registration	KU08XZD
Plate since	2019-03-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-04-19
Last registration	2024-02-13
Complete history	<a href="#">See info</a>



Registration #1	2008-04-19	10 mi
Registration #2	2011-03-11	16.794 mi
Registration #3	2012-03-06	20.476 mi
Registration #4	2012-09-26	22.060 mi
Registration #5	2013-09-07	27.332 mi
Registration #6	2013-09-09	27.332 mi
Registration #7	2014-09-06	33.271 mi
Registration #8	2014-09-06	33.271 mi
Registration #9	2015-09-05	39.788 mi
Registration #10	2015-09-05	39.788 mi
Registration #11	2016-09-17	46.040 mi
Registration #12	2016-09-17	46.040 mi
Registration #13	2016-09-17	46.040 mi
Registration #14	2016-09-17	46.040 mi
Registration #15	2016-09-17	46.040 mi
Registration #16	2016-09-17	46.040 mi
Registration #17	2016-09-17	46.040 mi
Registration #18	2016-09-17	46.040 mi
Registration #19	2016-09-17	46.040 mi
Registration #20	2016-09-17	46.040 mi
Registration #21	2016-09-17	46.040 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2087 mm
Height	1701 mm
Length	4259 mm
Wheel base	2685 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

**Number of axles**

2

**Engine number**

D034133