



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S
Colour	Red
Year of manufacture	2011
Top speed	109 mph
0 - 60 mph	12.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





Internet history

Entry 2

Date	2021-07-28
Pictures	0
Listing price	View report

source: cargurus.co.uk

Entry 1

Date	2021-07-27
Pictures	0
Listing price	View report

source: autotrader.co.uk



MOT history

MOT expiry date	2023-06-17
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	9
Total items failed	6

MOT #14	2022-06-14 14:58
MOT test number	250704620211
Result	✓ Passed
Next expiry date	2023-06-17

MOT #13	2022-06-10 12:14
MOT test number	798924090529
Result	✗ Failed
Fail	Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Stop lamp(s) not working (4.3.1 (a) (ii))
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Fail	Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

MOT #12	2021-06-16 08:48
MOT test number	994427470040
Result	✓ Passed
Advice	Oil leak, but not excessive (8.4.1 (a) (i))

**MOT #11** 2020-06-18 12:51**MOT test number** 357141250048**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Advice** Rear brake pipe surface corrosion hand brake high**MOT #10** 2020-06-18 12:51**MOT test number** 846537853090**Result** ✗ Failed**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Rear brake pipe surface corrosion hand brake high**Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Pass with rectification** Headlamp aim too low both fronts (4.1.2 (a))**MOT #9** 2019-03-22 14:05**MOT test number** 898810026378**Result** ✓ Passed**MOT #8** 2018-02-23 13:10**MOT test number** 364079170429**Result** ✓ Passed**MOT #7** 2017-01-27 14:49**MOT test number** 700475307034**Result** ✓ Passed**Advice** Both rear tyres splitting and cracking on treads 185/60/15



MOT #6	2016-01-15 09:44
--------	------------------

MOT test number	915279387988
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #5	2015-01-20 15:25
--------	------------------

MOT test number	679370425090
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #4	2015-01-20 15:25
--------	------------------

MOT test number	556330325011
-----------------	--------------

Result	✗ Failed
--------	----------

Pass with rectification	Inner Front Windscreen washer provides insufficient washer liquid (8.2.3)
-------------------------	---

MOT #3	2014-09-24 09:03
--------	------------------

MOT test number	795977264215
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #2	2014-04-24 16:14
--------	------------------

MOT test number	487824914128
-----------------	--------------

Result	✓ Passed
--------	----------

MOT #1	2014-02-24 09:45
--------	------------------

MOT test number	826225454055
-----------------	--------------

Result	✓ Passed
--------	----------



Tax & MOT check

✕
Untaxed

Tax expired:
31 August 2023

✕
MOT

Expired:
17 June 2023

Tax status	Expired at 31 August 2023
Days left	243 days too late
MOT expiry date	17 June 2023
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-




Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history


For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

XXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX
XXXXXX	XXXXXXXXXX
XXXXXXXXXXXXXX	XXXXXXXXXX
XXXXXXXXXX	XXXXXXXXXX

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2019-01-01
Current registration	 XXXXXX
Plate since	2019-01-01

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2011-04-15
Last registration	2022-06-14
Complete history	See info



Registration #1	2011-04-15	10 mi
Registration #2	2014-02-24	19.707 mi
Registration #3	2014-04-24	21.174 mi
Registration #4	2014-09-24	21.201 mi
Registration #5	2015-01-20	21.314 mi
Registration #6	2016-01-15	23.055 mi
Registration #7	2017-01-27	25.821 mi
Registration #8	2018-02-23	40.328 mi
Registration #9	2019-05-20	55.277 mi
Registration #10	2020-05-20	65.277 mi
Registration #11	2021-05-20	75.277 mi
Registration #12	2022-05-20	85.277 mi
Registration #13	2023-05-20	95.277 mi
Registration #14	2024-05-20	105.277 mi
Registration #15	2025-05-20	115.277 mi
Registration #16	2026-05-20	125.277 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	1331429