





report date: 2024-03-28

General information

| Make | JAGUAR |
|---------------------|----------------|
| Model | X-TYPE S |
| Colour | Black |
| Year of manufacture | 2008 |
| Top speed | 125 mph |
| 0 - 60 mph | 9.9 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 130 BHP |
|-------------------------|---------------------|
| Max. torque | 330 Nm at 1.800 rpm |
| Engine capacity | 1.998 сс |
| Cylinders | 4 |
| Fuel type | Diesel |
| Consumption city | 37.2 mpg |
| Consumption extra urban | 62.8 mpg |
| Consumption combined | 50.4 mpg |
| CO2 emission | 149 g/km |
| CO2 label | F |



CarCheck.co.uk page 1/13



report date: 2024-03-28

Internet history

| | market a | 1 |
|---|----------|---|
| ᄃ | nuv | - |

| LIICI Y I | |
|---------------|-------------|
| Date | 2021-06-14 |
| Pictures | 0 |
| Listing price | View report |

source: autotrader.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-28

MOT history

| MOT expiry date | 2024-07-21 |
|--------------------|------------|
| MOT pass rate | 87 % |
| MOT passed | 13 |
| Failed MOT tests | 2 |
| Total advice items | 16 |
| Total items failed | 2 |

| MOT #15 | 2023-06-27 15:50 |
|--|---|
| MOT test number | 941193856282 |
| Result | ✓ Passed |
| Next expiry date 2024-07-2 | |
| Advice Nearside Front Brake disc worn, pitted or score Advice Offside Front Brake disc worn, pitted or scored | red, but not seriously weakened (1.1.14 (a) (ii)) d, but not seriously weakened (1.1.14 (a) (ii)) |

| MOT #14 | | 2023-06-27 13:29 |
|---|---|---------------------------|
| MOT test | number | 533044442465 |
| Result | | X Failed |
| | earside Front Tyre has a cut in excess of the requirements deep enough (5.2.3 (d) (i)) | to reach the ply or cords |
| Advice Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) | | |
| Advice Offside Front Tyre wearing on edges and has sidewall damage | | |
| Advice | Offside Front Brake disc worn, pitted or scored, but not seriously weak | kened (1.1.14 (a) (ii)) |

| MOT #13 | 2022-07-22 13:42 |
|-----------------|------------------|
| MOT test number | 779465455387 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/13



report date: 2024-03-28

| MOT #12 | 2021-08-28 06:20 |
|---------|------------------|
| | |

MOT test number 871544907113

Result
✓ Passed

MOT #11 2020-11-02 13:42

MOT test number 562692974846

Result

Passed

MOT #10 2019-10-18 09:31

MOT test number 231355212202

Result ✓ Passed

MOT #9 2018-11-08 10:33

MOT test number 227608813207

Result ✓ Passed

Advice Offside Rear Tyre slightly damaged/cracking or perishing inner sidewall (5.2.3 (d) (ii))

Advice Both front tyres wearing on inner edges

MOT #8 2017-11-06 13:51

MOT test number 141728712357

Result \(\sqrt{Passed} \)

Advice O/s/f tyre worn on inner edge

Advice O/s/r tyre has cracking to inner tread not exposing cords

CarCheck.co.uk page 4/13



report date: 2024-03-28

| MOT #7 | 2017-11-06 10:04 |
|--|------------------|
| MOT test number | 604952005539 |
| Result | × Failed |
| Fail Offside Rear Shock absorber has a serious fluid leak (2.7.3) | |
| Advice O/s/r tyre has cracking to inner tread not exposing cords | |
| Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3) | |
| Advice O/s/f tyre worn on inner edge | |

| o, a, r. sy, a mem en mmer eage | |
|---------------------------------|------------------|
| | |
| MOT #6 | 2016-10-28 09:41 |
| MOT test number | 126737188133 |
| Result | ✓ Passed |
| | |
| MOT #5 | 2015-10-07 09:04 |
| MOT test number | 559066731006 |
| Result | ✓ Passed |
| | |
| MOT #4 | 2014-10-07 11:08 |
| MOT test number | 269230684266 |
| Result | ✓ Passed |
| | |
| MOT #3 | 2013-10-29 10:03 |
| MOT test number | 708992503379 |
| Result | ✓ Passed |

| MOT #3 | | 2013-10-29 10:03 |
|----------|---|------------------|
| MOT test | number | 708992503379 |
| Result | | ✓ Passed |
| Advice | Offside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Offside Rear Shock absorber has a light misting of oil (2.7.3) | |
| Advice | Nearside Rear Tyre worn close to the legal limit (4.1.E.1) | |
| Advice | Nearside Rear Shock absorber has a light misting of oil (2.7.3) | |

CarCheck.co.uk page 5/13



report date: 2024-03-28

| MOT #2 | 2012-11-05 15:13 |
|-----------------|------------------|
| MOT test number | 555970512355 |
| Result | ✓ Passed |
| | |
| MOT #1 | 2011-09-28 10:52 |
| MOT test number | 665301871241 |
| Result | ✓ Passed |

CarCheck.co.uk page 6/13



report date: 2024-03-28

Tax & MOT check



| Tax status | Valid until 1 July |
|------------------|--------------------|
| Days left | 63 |
| MOT expiry date | 21 July 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 49 |
|---|------------|
| Band | F |
| Single payment (12 months) | £ 200,00,- |
| Single six month payment | £ 110,00,- |
| Total payable by 12 monthly instalments | £ 210,00,- |

CarCheck.co.uk page 7/13



report date: 2024-03-28

Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-28

| _ | |
|--------|-----------|
| Owner | history |
| OWITCE | ilistoi y |

| For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full r | |
|--|-------------|
| | |
| | |
| *************************************** | |
| | |
| *************************************** | |
| *************************************** | |
| ************* | |
| | More info > |
| Plate changes | |
| See in this check if this JAGUAR had different number plates. | |
| Number of plates | |
| Current registration | MK MK |
| Plate since | |
| Current registration | NK NY |
| Plate since | |
| | More info > |

CarCheck.co.uk page 10/13



report date: 2024-03-28

Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-28

Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 17 |
| First mileage registration | 2008-09-30 |
| Last registration | 2023-06-27 |
| Complete history | See info |



| Registration #1 | 2008-09-30 | 7 mi |
|-----------------------------------|------------|-----------|
| Registration #2 | 2011-09-28 | 11.527 mi |
| Registration #3 | 2012-11-05 | 14.539 mi |
| Registration #4 | 2013-10-29 | 17.071 mi |
| Registration #5 | 2014-10-07 | 20.269 mi |
| Registration #6 | 2015-10-07 | 23.080 mi |
| Registration #7 | 2016-10-28 | 26.322 mi |
| Registration #8 | 2017-11-06 | 28.549 mi |
| Registration #9 | 2017-11-06 | 28.549 mi |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 10 JUL 44 |
| | | |
| Registration #15 | | 11,777 es |
| Registration #15 Registration #16 | | 11.777 es |

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 12/13



report date: 2024-03-28

Safety ratings

| NCAP rating | **** |
|-------------|-----------------|
| Video | see crash video |



Dimensions & weight

| Width | 2003 mm |
|---------------------|---------|
| Height | 1395 mm |
| Length | 4672 mm |
| Wheel base | 2710 mm |
| Kerb weight | 1502 kg |
| Max. allowed weight | 2015 kg |

Additional information

| Fuel tank capacity | 61 I |
|--------------------|------------------|
| Fuel delivery | Direct Injection |
| Number of doors | 4 |
| Number of seats | 5 |
| Number of axles | 2 |
| Engine number | 0804140438546G |

CarCheck.co.uk page 13/13